LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 EIRE TYPE 30 57 CAT 58
SOURCE L 6 0 5 0 - 0 3 2 4 7 0 2 1 6 8 3 8 0 3 0 7 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While performing routine RTGB surveillance during plant operation, it was
0 3 determined that closed position indication for drywell to suppression pool vacuum
0 4 breaker X18C could not be achieved. This event did not affect the health and
safety of the public.
06
0 7
Technical Specifications 3.6.4.1, 6.9.1.9b
SYSTEM CODE CODE SUBCODE SUBCO
This event is believed to have resulted from a problem with the vacuum breaker
[1] closed position limit switch, Model No. LB-240-794. This problem will be fully invest
tigated and resolved during a future outage. Input from a spare position limit switch
on the vacuum breaker was connected to the subject RTGB position indicator and closed
position indication of the vacuum breaker was established.
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 4 0 29 NA A 31 Operator Surveillance
7 8 9 10 12 13 44 45 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (33) Z (34) NA 44 45 46 LOCATION OF RELEASE (36) PERSONNEL EXPOSURES
1 7 0 0 0 37 Z 38 NA
7 B 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8 0 0 0 0 (40) NA
LOSS OF CHY AMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA 80
PUBLICITY SSUED DESCRIPTION 45 B303160497 B30307 NRC USE OBLY PDR ADOCK 05000324 S PDR