	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 5) CAT 58
CON'T 0 1 2 8 0 2	REPORT I. 6 05 0 - 0 3 ? 4 7 1 1 2 1 8 1 8 1 2 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During routine surveillance it was discovered that the printing mechanism of primary
0 3	containment atmospheric monitoring recorder, 2-CAC-AR-1259 was driving hard downscale
0 4	when exhibiting indication of hydrogen concentration in the drywell. The other redun-
0 5	dant recorder, 2-CAC-AR-1263 exhibited a normal, expected indication of drywell hydro-
0 6	gen concentration. This event did not affect the health and safety of the public.
0 7	
08	Technical Specifications 3.3.5.3, 3.6.6.4, 6.9.1
	SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SU
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 Instrument drift of the 1259 recorder's respective hydrogen analyzer, 2-CAC-AT-1259-1, 1
1110	Model No. F3M3, resulted in an erroneous recorder input signal. The analyzer was cal-
	ibrated and returned to service. Due to a history of similar events, plant modifica-
1 2	tion 80-33 has been developed which will replace these type analyzers with others of a
1 3	more reliable design during a future unit outage.
	9 ACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 YE 28 0 7 7 7 29 NA A 31 Operator Surveillance
	SCHVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA N
1 7	PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 NA NA NA
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
19	9 11 12 LOSS OF OR DAMAGE TO PACILITY (43) TYPE DESCRIPTION NA NA 80
20	PUBLICITY DESCRIPTION 45 PDR ADDCK 05000324 NA PDR NA S 68 69 80-5
	M. J. Pastva, Jr. 919-457-9521