

U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)  
 /0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT  
 /0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /1/1/1/7/8/1/ (8) /1/2/1/0/8/1/ (9)  
 SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On November 17, 1981, during Mode 1 operation, two valves on the Train B Low Head/  
 /0/3/ / Safety Injection system were found to be closed thereby rendering a single ECCS /  
 /0/4/ / subsystem inoperable contrary to T.S. 3.5.2.C. Since the redundant train remain-/  
 /0/5/ / ed operable and the isolated train was restored within the requirements of the /  
 /0/6/ / action statement, the health and safety of the public were not affected. This /  
 /0/7/ / event is reportable pursuant to T.S. 6.9.1.9.c. /

/0/8/ /  
 SYSTEM CAUSE CAUSE COMP. VALVE  
 CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE  
 /0/9/ /S/F/ (11) /A/ (12) /A/ (13) /Z/Z/Z/Z/Z/Z/ (14) /Z/ (15) /Z/ (16)  
 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION  
 (17) REPORT NO. NO.  
 NUMBER /8/1/ /-/ /0/7/6/ / \ / /0/3/ /L/ /-/ /0/

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT  
 TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  
 /H/ (18) /G/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /Y/ (23) /N/ (24) /A/ (25) /S/4/2/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / This event was caused by operator error. The two valves were not verified open /  
 /1/1/ / following the performance of a periodic test nor were the malpositioned valves /  
 /1/2/ / detected during the first shift turnover. The valves were immediately reopened /  
 /1/3/ / when discovered on the second shift turnover and the operations personnel /  
 /1/4/ / reinstructed. /

FACILITY METHOD OF  
 STATUS %POWER OTHER STATUS (30) DISCOVERY DISCOVERY DESCRIPTION (32)  
 /1/5/ /E/ (28) /1/0/0/ (29) / NA / /B/ (31) / Operator Observation /  
 ACTIVITY CONTENT  
 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
 /1/6/ /Z/ (33) /Z/ (34) / NA / / NA /  
 PERSONNEL EXPOSURES  
 NUMBER TYPE DESCRIPTION (39)  
 /1/7/ /0/0/0/ (37) /Z/ (38) / NA /  
 PERSONNEL INJURIES  
 NUMBER DESCRIPTION (41)  
 /1/8/ /0/0/0/ (40) / NA /  
 LOSS OF OR DAMAGE TO FACILITY (43)  
 TYPE DESCRIPTION  
 /1/9/ /Z/ (42) / NA /  
 PUBLICITY  
 ISSUED DESCRIPTION (45)  
 /2/0/ /N/ (44) / NA /

NRC USE ONLY

/ / / / / / / / / / / / / /

NAME OF PREPARER W. R. CARTWRIGHT

PHONE (703) 894-5151

8112240219 811210  
 PDR ADOCK 05000338  
 S PDR

#### Description of Event

On November, 17 1981, while preparing for shift turnover, the Control Room Operator noted that valves MOV-1862B and MOV-1885D were closed thereby rendering the B train of the LHSI system inoperable.

#### Probable Consequences of Occurrence

The operability of two independent ECCS subsystems ensures that sufficient emergency core cooling capability will be available in the event of a LOCA. Since the redundant train A remained operable and the Train B was restored to service within the time required by the T.S. 3.5.2 action statement, the health and safety of the public were not affected.

#### Cause of Event

This event was caused by the improper performance of a valve operability test on MOV-1860B for inservice inspection requirements. The valve MOV-1885D was manually closed to complete the permissive for opening MOV-1860B and MOV-1862B goes closed when MOV-1860B is full open. The periodic test procedure specifically requires these valves to be reopened when the test is completed. This was not performed as required. Additionally, operations personnel performing the first shift turnover checklist did not detect the malpositioned valves.

#### Immediate Corrective Action

The valves were opened, thereby restoring the Train B LHSI system flowpath. All operations personnel involved were counseled.

#### Scheduled Corrective Action

No further action required.

#### Actions Taken to Prevent Recurrence

The periodic test procedure has been revised to more explicitly require reopening of these valves. The shift turnover checklist was revised to emphasize the requirement that the checklist be performed jointly by both offgoing and oncoming shifts.

#### Generic Implications

There are no generic implications to this event.