
Examination of Failed Studs From No. 2 Steam Generator at the Maine Yankee Nuclear Power Station

Prepared by C. Czajkowski

Brookhaven National Laboratory

Prepared for
U.S. Nuclear Regulatory
Commission

NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, or any of their employees, makes any warranty, expressed or implied, or assumes any legal liability of responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

Availability of Reference Materials Cited in NRC Publications

Most documents cited in NRC publications will be available from one of the following sources:

1. The NRC Public Document Room, 1717 H Street, N.W.
Washington, DC 20555
2. The NRC/GPO Sales Program, U.S. Nuclear Regulatory Commission,
Washington, DC 20555
3. The National Technical Information Service, Springfield, VA 22161

Although the listing that follows represents the majority of documents cited in NRC publications, it is not intended to be exhaustive.

Referenced documents available for inspection and copying for a fee from the NRC Public Document Room include NRC correspondence and internal NRC memoranda; NRC Office of Inspection and Enforcement bulletins, circulars, information notices, inspection and investigation notices; Licensee Event Reports; vendor reports and correspondence; Commission papers; and applicant and licensee documents and correspondence.

The following documents in the NUREG series are available for purchase from the NRC/GPO Sales Program: formal NRC staff and contractor reports, NRC-sponsored conference proceedings, and NRC booklets and brochures. Also available are Regulatory Guides, NRC regulations in the *Code of Federal Regulations*, and *Nuclear Regulatory Commission Issuances*.

Documents available from the National Technical Information Service include NUREG series reports and technical reports prepared by other federal agencies and reports prepared by the Atomic Energy Commission, forerunner agency to the Nuclear Regulatory Commission.

Documents available from public and special technical libraries include all open literature items, such as books, journal and periodical articles, and transactions. *Federal Register* notices, federal and state legislation, and congressional reports can usually be obtained from these libraries.

Documents such as theses, dissertations, foreign reports and translations, and non-NRC conference proceedings are available for purchase from the organization sponsoring the publication cited.

Single copies of NRC draft reports are available free upon written request to the Division of Technical Information and Document Control, U.S. Nuclear Regulatory Commission, Washington, DC 20555.

Copies of industry codes and standards used in a substantive manner in the NRC regulatory process are maintained at the NRC Library, 7920 Norfolk Avenue, Bethesda, Maryland, and are available there for reference use by the public. Codes and standards are usually copyrighted and may be purchased from the originating organization or, if they are American National Standards, from the American National Standards Institute, 1430 Broadway, New York, NY 10018.

Examination of Failed Studs From No. 2 Steam Generator at the Maine Yankee Nuclear Power Station

Manuscript Completed: July 1982
Date Published: February 1983

Prepared by
C. Czajkowski

Brookhaven National Laboratory
Upton, NY 11973

Prepared for
Division of Engineering
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
NRC FIN A3400

TABLE OF CONTENTS

	<u>Page</u>
List of Figures	ii
List of Tables	iii
Abstract	v
1.0 INTRODUCTION	1
2.0 VISUAL INSPECTION/DYE PENETRANT	1
3.0 OPTICAL METALLOGRAPHY	2
4.0 SEM/EDS	3
5.0 DISCUSSION	4
6.0 CONCLUSION	5
7.0 ACKNOWLEDGEMENT	6
8.0 REFERENCES	7

LIST OF FIGURES

<u>Figure</u>		<u>Page</u>
1.	Photograph of first "as received" stud	13
2.	Photograph of second stud	14
3.	Photograph of "cracked" stud	15
4.	Photograph of fracture faces of "cracked" stud	16
5.	Optical photomicrograph of cracked stud's cross section	17
6.	Optical photomicrograph of a secondary crack	18
7.	Optical photomicrograph of stud's microstructure	18
8.	Low magnification SEM photo of the cracked stud's fracture face	19
9.	SEM photo of nodular oxide	20
10.	SEM photo of acicular oxide	20
11.	SEM photo of fracture face prior to deoxidation	20
12.	SEM photo of fracture face and secondary cracking	20
13.	SEM photo of second area depicting secondary cracks	21
14.	SEM photo of base material	21
15.	EDS scan of base material for constituents	21
16.	SEM photo of fibrous particulate	22
17.	EDS scan of fibrous particulate	22
18.	SEM photo of second fibrous particle	22
19.	EDS scan of fibrous particle	22
20.	SEM photo of apparent pit	23
21.	EDS scan of apparent pit	23
22.	SEM photo of smeared material	23
23.	EDS scan of smeared material	23
24.	SEM photo of second smeared area	24
25.	EDS scan of second smeared area	24
26.	WDS scan of second smeared area for Mo	24
27.	WDS scan of second smeared area for S	24

LIST OF TABLES

<u>Table</u>		<u>Page</u>
1	Typical Chemical and Mechanical Properties of ASTM A540-B24 Steel	8
2	Typical Certification for Sealant Used (Lot 505)	9
3	Typical Certification for Sealant Used (Lot 701)	10
4	Typical Certification for Sealant Used (Lot 702)	11
5	Typical Certification for Lubricant Used (Batch 55)	12

ABSTRACT

Three studs removed from service on the primary manway cover from steam generator #2 of the Maine Yankee station were sent to Brookhaven National Laboratory (BNL) for examination. The examination consisted of visual/dye penetrant examination, optical metallography and Scanning Electron Microscopy/Energy Dispersive Spectroscopy (SEM/EDS) evaluation. One bolt was "through cracked" and its fracture face was generally transgranular in nature with numerous secondary intergranular cracks. The report concludes that the environmentally assisted cracking of the stud was due to the interaction of the various lubricants used with steam leaks associated with this manway cover.

1.0 INTRODUCTION

During March 1982, at a maintenance outage of the Maine Yankee Power Plant, 5 of 20 primary manway studs failed during removal of the (cold leg) primary manway cover from steam generator #2.

Prior to this outage, the manway cover had been leaking, with retorquing of the studs and injection of sealant into the stud used by the utility as methods of controlling the leakage.

Since failure of this cover would result in a breach of the primary pressure boundary, the Materials Engineering Branch of the United States Nuclear Regulatory Commission (U.S.N.R.C.) requested that BNL perform an independent failure analysis on three of the bolts from the #2 steam generator manway cover.

The examination for this analysis included:

- 1) Visual inspection/photography/dye penetrant
- 2) Optical metallography
- 3) SEM/EDS analysis

2.0 VISUAL INSPECTION/PHOTOGRAPHY/DYE PENETRANT

The three studs received at BNL were approximately 10 1/2" long, and 1 1/2" in diameter and were surveyed by BNL Health Physics personnel as having a dose rate reading of approximately 2 mR/hr at contact.

The first stud examined (Figure 1) had apparent disruption to the thread area which had the appearance of damage caused by the use of a vise grip-type tool. There was also a white fibrous type coating on the opposing thread area of the stud (discussed in the SEM section).

The second stud examined (Figure 2) appeared to have residue from prior dye penetrant examinations and had a nut threaded on to one end of the stud. This nut was removed prior to dye penetrant examination by cutting (due to the extremely tight fit to the stud).

Figure 3 is a photograph of a "through cracked" stud. The crack is approximately 2 1/2" into the thread area "inserted end" of the stud. The fracture face of the stud (Figure 4) was relatively flat and had a black oxide appearance.

Dye penetrant examination was performed on the first two studs (Figures 1 and 2) using Spotcheck Brand (all Formula B) penetrant type SKL-HF/SKL-S developer type SKD-NF and cleaner/remover type SKC-NF. There were no relevant indications seen on the two studs. It should be noted that there was a tight black adherent film on the thread area of all studs examined, possibly from prior lubricant application (see SEM section).

No attempt was made to dye penetrant examine the cracked stud in order to keep exterior contamination to a minimum prior to SEM/EDS evaluation.

3.0 OPTICAL METALLOGRAPHY

A longitudinal section was made of the small end of the cracked stud, perpendicular to the main fracture face. It was then mounted, etched and polished (Figure 5). It can be clearly seen in the photomicrograph that numerous secondary cracks are present, initiating at the main fracture (areas A-F). These cracks had some fern-like branching associated with them which is normally indicative of environmentally assisted cracking. The major secondary cracks appeared to be generally transgranular in nature. The microstructure of the stud material (Figure 6 & 7) was that of a quenched and tempered martensite with a fine grained microstructural appearance. This microstructure is typical of an ASTM A540-B24 steel (Table 1).

4.0 SEM/EDS

The fracture face and a limited amount of thread area of the "through cracked" bolt was examined by SEM/EDS examination prior to any deoxidizing treatments in hopes of determining if any corrodent species were present.

The "as received" surface of the fracture face had a very flat and heavily oxidized surface (Figure 8) with the oxide varying from a nodular type (Figure 9) to an acicular shape (Figure 10). Initial SEM observations were that the fracture face was predominantly transgranular with no evidence of any ductile tearing. After some sections were deoxidized by an Endox 215 solution, however, various areas of apparently intergranular secondary cracking were revealed (Figures 11-13). This type of secondary cracking would be a definite indication of an environmentally assisted corrosion phenomenon.

An EDS scan of the base metal was performed (Figures 14 and 15) and showed characteristic peaks of Fe, Cr, Mn and Ni. These peaks would be typical for this alloy.

Various particles and areas of apparent material smearing were scanned for constituents using EDS. The first particle scanned from stud No. 2C6 was fibrous in appearance (Figures 16 & 17) and had quite high peaks of silicon and nickel in relation to the Fe alloy background. The scan also showed trace amounts of S, Ca and Cr. The high silicon content is probably related to the use of the silicon base Furmanite sealer used by the utility to seal the leaking stud holes. The high nickel content is attributed to the utility's use of Fel-Pro-5000, a nickel-base lubricant. (For typical certifications of materials used at Maine Yankee (see Tables 2-5.)) A second fibrous particle scanned (Figures 18 & 19), however, showed only peaks of Fe, Cr and Ni.

Another area scanned (Figures 20 & 21) appeared to be a pit and had a lead (Pb) peak in addition to Si, Cr, Fe and Ni. The appearance of lead may be attributed to the Fel-Pro which allows up to 25 ppm total lead in its specification.

EDS analysis of a smeared area (Figures 22 & 23) showed peaks of Si, S, Ca and Fe only.

A second smeared area (Figure 24) had such a high peak in sulfur (Figure 26) that a wavelength dispersive spectrographic scan was accomplished to determine if molybdenum was present with the sulfur. It can be clearly seen (Figures 27 & 28) that this particular area is quite concentrated in Mo which is indicative that a molybdenum disulfide type lubricant may have been used sometime in the service history of the stud.

5.0 DISCUSSION

Since the cracking of the steam generator manway studs was associated with leaking gaskets, it is worthwhile to examine the observed effects of pressurized water reactor (PWR) primary coolant on high strength low alloy bolting materials. A review [1] was performed by BNL on incidents of boric acid wastage corrosion at seven nuclear units. All incidents involved a primary coolant leaking mechanism and in no instance was cracking observed. All degradation occurred by a general wastage/corrosion mechanism.

This being the case; it is therefore logical to assume that the addition of other environmental variables must be made in order to crack these materials in either a transgranular or intergranular manner. The most obvious source of these contaminants is the lubricant applied to these materials in service.

Work done at BNL [2,3] on turbine disc steels has shown that molybdenum disulfide lubricants can have a marked effect on lowering the ultimate tensile strength of high strength low alloy steels when exposed to a steam environment on notched tensile specimens.

A metallurgical failure analysis [4] performed on steam generator manway studs at the Oconee Unit 3 power station ascribed the intergranular attack on the bolts to the use of molybdenum disulfide lubricants.

Kay [5] has cited that MoS₂ can oxidize in the presence of air and moisture to produce molybdenum dioxide and sulfuric acid which would be quite detrimental to a martensitic steel.

Finally, a report issued by the Swansea Tribology Centre [6] on molybdenum disulfide lubrication has listed these precautions on the use of the lubricant:

(quoted in part)

- "1) Always remember that where conditions exist which will tend to cause corrosion, the presence of molybdenum disulphide may increase the extent of the corrosion.
- 2) Wherever possible eliminate the presence of corrosive materials such as acids, brines, or water and use corrosion - resistant substrates."

It is, therefore, logical to assume that some interaction between the leaking steam and the sulfur containing lubricants on the bolts may have led to the premature failure of the bolt by a stress corrosion crack mechanism.

6.0 CONCLUSION

- 1) The cracked bolt failed in a generally transgranular mode with numerous secondary intergranular cracks.
- 2) This cracking is considered environmentally assisted in nature and was typical of a stress corrosion cracking phenomenon.

3) Since prior investigations have shown that high strength low alloy steels in primary coolant will have a wastage-type corrosion only, this cracking is considered to be the result of the interaction of primary water/steam with the use of sulfur containing lubricants.

7.0 ACKNOWLEDGEMENT

The author wishes to thank R. Sabatini for the SEM/EDS work; L. Gerlach and D. Becker for the metallography; O. Betancourt for her typing and Dr. J. R. Weeks for his continuing support.

8.0 REFERENCES

1. Czajkowski, C., BNL-NUREG-31098, March, 1982.
2. Czajkowski, C., BNL-NUREG-28724, October, 1980.
3. Czajkowski, C., BNL-NUREG-29964, March, 1981.
4. Burck, L. H., Foley, W. J., Report No. IE-123, April, 1981.
5. Kay, E., Wear, 12 (1968), 165-171.
6. Lansdown, A. R., Report No. 79/419 ESA (ESTEC) Contract No. 2261/74.

TABLE 1

TYPICAL CHEMICAL AND MECHANICAL PROPERTIES OF
ASTM A540-B24 STEEL

<u>Chemical Requirements</u>		<u>Product Variations %, over or under</u>
Carbon	0.37-0.44	0.02
Manganese	0.70-0.90	0.04
Phosphorous, max.	0.025	0.005
Sulfur, max.	0.025	0.005
Silicon	0.15-0.35	0.02
Chromium	0.70-0.95	0.05
Nickel	1.65-2.00	0.05
Molybdenum	0.30-0.40	0.02
Vanadium	-	-

Mechanical Requirements

Grade	Class	Diameter
B24	3	to 3, incl.

Tensile Strength	Yield Strength	Elongation	% Red. of Area,	Surface Hardness, Brinell	
<u>min.</u>	<u>0.2 offset, min.</u>	<u>% in 2 in.</u>	<u>min.</u>	<u>min.</u>	<u>max.</u>
145 ksi	130 ksi	12	40	293	363

TABLE 2

TYPICAL CERTIFICATION FOR SEALANT USED (LOT 505)

MATERIAL CERTIFICATION
REVISION 1

August 14, 1981


Material: ~~Furmanite Nuclear Grade Compound F-500~~, Lot No. 505

Expiration date for Compound: July 31, 1982

This is to certify that the analysis results of a typical sample of the above compound, analyzed by an independent test laboratory, is as follows:

	TOTAL	LEACHABLE
Chlorine	38	26
Flourine	11	< 1
Sulfur (As S)	14	≤ 2
Antimony	*	≤ 0.03
Arsenic	*	≤ 0.03
Cadmium	*	≤ 0.03
Lead	*	≤ 0.3
Tin	*	≤ 3
Zinc	*	< 0.05
Mercury	*	0.002

Note: Results in microgram/gram
* Not Measured


D. F. Limfoth
Engineering Manager

Ref: CT&E - 8/6/81

DFL/tfm


MAINE YANKEE ATOMIC POWER CO.
QUALITY CONTROL INSPECTED
SAT. UNSAT.
DATE 10/24/81 INSPECTOR 

TABLE 3

TYPICAL CERTIFICATION FOR SEALANT USED (LOT 701)

MATERIAL CERTIFICATION

October 19, 1981

Material: ~~Furmanite Nuclear Grade Compound F700, Lot No. 701~~

Expiration date for Compound: October 16, 1982

This is to certify that the analysis results of a typical sample of the above compound, analyzed by an independent test laboratory, is as follows:

	TOTAL	LEACHABLE
Chlorine	179.5	32.7
Fluorine	19.0	0.88
Sulfur	62	18
Antimony	*	0.11
Arsenic	*	< 0.02
Cadmium	*	< 0.005
Lead	*	< 0.05
Mercury	*	< 0.002
Tin	*	< 0.05
Zinc	*	< 0.05

Note: Results in microgram/gram
* Not Measured

D. F. Limroth
D. F. Limroth
Engineering Manager

Ref: Jennings Laboratories, Inc.

DFL/tfm

MAINE YANKEE ATOMIC POWER CO.
QUALITY CONTROL INSPECTED
SAT. UNSAT.
DATE 10/24/81 INSPECTOR R. Linton

TABLE 4

TYPICAL CERTIFICATION FOR SEALANT USED (LOT 702)

MATERIAL CERTIFICATION

December 4, 1981

Material: ~~Furmanite Nuclear F-700-N, Lot #702~~

Expiration date for compound: December 4, 1982

This is to certify that the analysis results of a typical sample of the above compound, analyzed by an independent test laboratory is as follows:

	Total	Leachable
Chlorine	246.2	29.6
Fluorine	24.0	.65
Sulfur	.15	84.0
Antimony	*	0.18
Arsenic	*	<0.02
Cadmium	*	<0.005
Lead	*	<0.05
Mercury	*	<0.002
Tin	*	<0.05
Zinc	*	<0.05

Note: Results in microgram/gram
* Not Measured

D. F. Limroth
D. F. Limroth
Engineering Manager

REF: Jennings Laboratories, Inc.
12/04/81

DFL/tfm

MAINE YANKEE ATOMIC POWER CO.
QUALITY CONTROL INSPECTED
SAT. UNSAT.
DATE 12-22-81 INSPECTOR *[Signature]*

TABLE 5

TYPICAL CERTIFICATION FOR LUBRICANT USED (BATCH 55)

FEL-PRO N-5000
 NUCLEAR GRADE
 ANTISEIZE LUBRICANT

BATCH NO. 55

DATE OF MFR. 4/10/81

CERTIFICATE OF COMPLIANCE

It is hereby certified that the above batch of Fel-Pro N-5000 meets the following purity standards:

	MAXIMUM ALLOW- ABLE PER N-5000 SPECIFICATION	TEST RESULTS		
		SAMPLE #1	SAMPLE #2	SAMPLE #3
Total Fluorine	200 ppm	25 ppm	24 ppm	15 ppm
Total Chlorine	50 ppm	<20 ppm	<40 ppm	<20 ppm
Total Sulfur	100 ppm	<25 ppm	<25 ppm	<25 ppm
Total Lead	25 ppm	8.5 ppm	7.5 ppm	8.8 ppm
Total Tin	25 ppm	11.6 ppm	---	---
Total Zinc	25 ppm	6.4 ppm	---	---
Total Cadmium	2 ppm	0.8 ppm	---	---
Total Mercury	2 ppm	0.17 ppm	---	---
Total Copper	50 ppm	2.6 ppm	---	---

NOTE: Original test report on this batch of N-5000 is on file at FEL-PRO INCORPORATED. Copies are available upon request. Test results are further shown on each can filled from this batch of materials.

BY: FEL-PRO INCORPORATED
 7450 N. MCCORMICK BLVD.
 Skokie, Ill. 60076

W. L. Schaefer
 Officer of Company

Prod. Mgr., Chem. Prod. Div.
 Title

SUBSCRIBED AND SWORN TO BEFORE ME THIS DATE:

187. Feb 1981
Walter H. G. Sawyer
 Notary Public
 COOK COUNTY, ILL.

MAINE YANKEE ATOMIC POWER CO.
 QUALITY CONTROL INSPECTED
 SAT. _____ UNSAT. _____
 DATE 8-7-81 INSPECTOR *[Signature]*




Figure 1. Photograph of "as received" stud from Maine Yankee. (Bolt had the following numbers stamped on the ends - 2C6, #46500, 6410).




Figure 2. Photograph of second stud received from Maine Yankee. Photo depicts remnants of Dye Penetrant testing. (Bolt had the following numbers stamped on the ends (2C20, #64034)).




Figure 3. Photograph of "cracked" stud from Maine Yankee (Bolt had the following numbers stamped on the ends-2C8, 6418, #64034).



Figure 4. Frontal photograph of the fracture faces of the cracked bolt.






Figure 5. Optical photomicrograph of bolt section depicting extent of secondary cracking (areas A-F). Note fern like branching on larger secondary cracks.



500x
Figure 6. Optical photomicrograph of a secondary crack after etching.



400x
Figure 7. Optical photomicrograph of bolt's structure after etching.







Figure 8. SEM photograph of a quadrant of the "cracked bolt " fracture face.




100x
Figure 9. SEM photograph of "nodular" oxide.




1000x
Figure 10. SEM photograph of "acicular" oxide.



100x
Figure 11. SEM photo of fracture face prior to deoxidation treatments.




500x
Figure 12. SEM photo of fracture face depicting intergranularity of secondary cracks.



500x

Figure 13. SEM photo of second area on the fracture face depicting secondary intergranular cracks.

21



1000x

Figure 14. SEM photo of base material area scanned.





Figure 15. EDS scan of base material for constituents.




500x

Figure 16. SEM photo of fibrous particulate.



Figure 17. EDS scan of fibrous particle.

22



500x

Figure 18. SEM photo of second fibrous particle.





Figure 19. Constituents of second fibrous particle scanned by EDS.



1000x
 Figure 20. SEM photo of apparent pit on thread of the cracked stud.





Figure 21. EDS scan of pit for chemical constituents.



500x
 Figure 22. SEM photo of area of smeared material on thread area of the cracked bolt.




Figure 23. EDS scan of smeared material area.



1000x
Figure 24. SEM photograph of second "smeared" area on bolt.




Figure 25. EDS scan of "smeared" area in Figure 24.




Figure 26. WDS scan of "smeared" area for molybdenum.




Figure 27. WDS scan of smeared area for sulfur.

NRC FORM 335 <small>(11-81)</small>		U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1. REPORT NUMBER (Assigned by DDC) NUREG/CR-2993 BNL-NUREG-51594	
4. TITLE AND SUBTITLE (Add Volume No., if appropriate) Examination of Failed Studs from No. 2 Steam Generator at the Maine Yankee Nuclear Power Station				2. (Leave blank)	
7. AUTHOR(S) C. Czajkowski				3. RECIPIENT'S ACCESSION NO.	
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Brookhaven National Laboratory Upton, NY 11973				5. DATE REPORT COMPLETED MONTH: July YEAR: 1982	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Engineering Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, DC 20555				DATE REPORT ISSUED MONTH: February YEAR: 1983	
13. TYPE OF REPORT Technical				6. (Leave blank)	
15. SUPPLEMENTARY NOTES				8. (Leave blank)	
16. ABSTRACT (200 words or less) <p>Three studs removed from service on the primary manway cover from steam generator #2 of the Maine Yankee station were sent to Brookhaven National Laboratory (BNL) for examination. The examination consisted of visual/dye penetrant examination, optical metallography and Scanning Electron Microscopy/Energy Dispersive Spectroscopy (SEM/EDS) evaluation. One bolt was "through cracked" and its fracture face was generally transgranular in nature with numerous secondary intergranular cracks. The report concludes that the environmentally assisted cracking of the stud was due to the interaction of the various lubricants used with steam leaks associated with this manway cover.</p>				10. PROJECT/TASK/WORK UNIT NO.	
17. KEY WORDS AND DOCUMENT ANALYSIS				11. FIN NO. A3400	
lubricant corrosion threaded fastener degradation transgranular cracking				14. (Leave blank)	
17b. IDENTIFIERS OPEN-ENDED TERMS				19. SECURITY CLASS (This report) Unclassified	
18. AVAILABILITY STATEMENT Unlimited				21. NO OF PAGES	
19. SECURITY CLASS (This page) Unclassified				22. PRICE \$	