

ORIGINAL

**[REDACTED] TRANSCRIPT
PROCEEDINGS BEFORE**

NUCLEAR REGULATORY COMMISSION

COMMISSION MEETING

PUBLIC MEETING

50-272
311

DKT/CASE NO.

TITLE BRIEFING ON SALEM

PLACE Washington, D. C.

DATE March 2, 1983

PAGES 1 - 124



AMERICAN REPORTING

8303160627 830302
PDR 10CFR
PT9.7

PDR J
440 FIRST STREET, N.W.
WASHINGTON, D.C. 20001

1 UNITED STATES OF AMERICA
2 NUCLEAR REGULATORY COMMISSION

3 BRIEFING ON SALEM

4 PUBLIC MEETING

5
6 Nuclear Regulatory Commission
7 Room 1130
8 1717 H Street, N. W.
9 Washington, D. C.

10 Wednesday, March 2, 1983

11 The Commission convened, pursuant to notice,
12 at 9:30 a.m.

13 COMMISSIONERS PRESENT:

- 14 NUNZIO PALLADINO, Chairman of the Commission
- 15 VICTOR GILINSKY, Commissioner
- 16 JOHN AHEARNE, Commissioner
- 17 THOMAS ROBERTS, Commissioner
- 18 JAMES ASSELSTINE, Commissioner

19 STAFF AND PRESENTERS SEATED AT COMMISSION TABLE:

- 20 S. CHILK
- 21 H. PLAINE
- 22 S. TRUBATCH
- 23 G. LAINAS
- 24 D. EISENHUT
- 25 D. ROSS
- R. STAROSTECKI
- E. CASE
- E. JORDAN
- J. ZERBE
- R. ECKERT

AUDIENCE SPEAKERS:

- R. MATTSON
- T. IPPOLITO
- J. SNIEZEK

* * *

DISCLAIMER

This is an unofficial transcript of a meeting of the United States Nuclear Regulatory Commission held on March 2, 1983 in the Commission's offices at 1717 H Street, N.W., Washington, D. C. The meeting was open to public attendance and observation. This transcript has not been reviewed, corrected, or edited, and it may contain inaccuracies.

The transcript is intended solely for general informational purposes. As provided by 10 CFR 9.103, it is not part of the formal or informal record of decision of the matters discussed. Expressions of opinion in this transcript do not necessarily reflect final determinations or beliefs. No pleading or other paper may be filed with the Commission in any proceeding as the result of or addressed to any statement or argument contained herein, except as the Commission may authorize.

P R O C E E D I N G S

1
2 CHAIRMAN PALLADINO: Good morning, ladies and
3 gentlemen.

4 Before we begin we need to vote on having a
5 meeting with less than one week's notice.

6 Will those in favor on the Commission signify
7 by saying Aye.

8 COMMISSIONER GILINSKY: Aye.

9 COMMISSIONER AHEARNE: Aye.

10 COMMISSIONER ROBERTS: Aye.

11 COMMISSIONER ASSELSTINE: Aye.

12 CHAIRMAN PALLADINO: Aye.

13 The purpose of our meeting this morning is to
14 allow the staff to brief the Commissioners on the event
15 that occurred at Salem Unit 1 last Friday. The event
16 involved a failure of the reactor to trip after
17 receiving an automatic trip signal which required
18 operator action to manually trip the unit.

19 Each of the Commissioner offices received
20 preliminary information regarding the event on Friday
21 and our meeting this morning should allow a discussion
22 of more of the details surrounding the event.

23 I understand that the staff met with the
24 licensee for the facility on Monday and I would request
25 that the staff's presentation include a discussion of

1 the results of that meeting.

2 Do any of my fellow Commissioners have
3 additional remarks before we begin?

4 (No response.)

5 CHAIRMAN PALLADINO: If not, then I will turn
6 the meeting over to Mr. Darrell Eisenhut.

7 MR. EISENHUT: Thank you.

8 (Slide presentation.)

9 MR. EISENHUT: If I could have the outline
10 slide.

11 We broke the presentation today into two
12 parts. The first part will address the Salem event, or
13 more accurately the Salem events. There were two
14 different occurrences of the reactor having a failure to
15 automatically scram, one which occurred on February 22nd
16 and one which occurred on February 25th. We will be
17 addressing both of those today.

18 We will break it into two parts. The first
19 part, we will try to go through the event description,
20 what actually happened during these events, which will
21 be covered by Region I today. Rich Starostecki at the
22 Division Director from the Region to cover that. He
23 will be followed by NRR with Gus Lainas making a
24 presentation on the issues relating to restart and the
25 different pieces that flow out of the events.

1 Following that we are going to try to address
 2 and summarize the generic implications with I&E
 3 addressing the results or preliminary results I guess of
 4 a bulletin that was issued last Friday, followed by some
 5 more broader generic implications by a couple of
 6 different aspects.

7 In addition to the meeting that the Chairman
 8 mentioned, there was also a site visit last Saturday
 9 where both representatives from Region I and from
 10 headquarters went to the site and they effectively met
 11 most of the day in discussing the events.

12 So with that, I will turn it over to Rich
 13 Sterostecki who will outline the event factually as it
 14 occurred.

15 MR. STAROSTECKI: If I could have the next
 16 slide, please.

17 I will and present an event description and
 18 include a brief description of the trip breaker, the
 19 solid state protection system, the trip breaker history
 20 and a review of the two events.

21 We are prepared to go into more detail with
 22 Gus Lainas' presentation, if you wish, on the background
 23 information I will be presenting.

24 The next slide, please.
 25 The reactor trip breakers in question, as

1 indicated on the slide, allow power to be provided from
2 a power source, in this case the motor generator sets to
3 the control rod drive mechanisms. That is the system
4 that is normally used to move the rods up and down.
5 Interrupting that power supply train causes a scram.

6 The trip breaker can be mechanically itself
7 opened by a manual button at the breaker, a latch on the
8 cabinet which automatically would trip the breaker when
9 one tries to open the breaker.

10 COMMISSIONER GILINSKY: Where are the breakers?

11 MR. STAROSTECKI: The breakers are in the
12 lower levels of the plant, quite a walking distance away
13 from the control room.

14 MR. CASE: In a cabinet.

15 MR. STAROSTECKI: In a cabinet.

16 CHAIRMAN PALLADINO: Outside containment?

17 MR. STAROSTECKI: They are outside
18 containment. They are not in the vicinity of the
19 control room.

20 CHAIRMAN PALLADINO: Are they mechanical
21 latches or are you still using electrical signals?

22 MR. STAROSTECKI: Well, that is what this is
23 indicating, is that there is one trip bar on the breaker
24 and that one trip bar can be tripped with a manual
25 button at the breaker, the latch on the side of the

1 breaker housing, a shunt coil, an electrical coil and
2 its attachment and an undervoltage coil and its
3 attachment. All these devices work on one common trip
4 bar.

5 MR. EISENHUT: We will be discussing that in a
6 little more depth in a little bit, and we actually have
7 an undervoltage relay with us and we have some slides
8 which hopefully will explain the mechanism.

9 CHAIRMAN PALLADINO: But if the problem is
10 friction on the latch, is there a way to overcome that?

11 MR. EISENHUT: Right.

12 MR. STAROSTECKI: What I am trying to present
13 here are the mechanisms and how they influenced the
14 sequences of events and then we can go back and talk
15 about the individual pieces as to friction, et cetera.

16 The next slide, please.

17 This slide is entitled "Solid State Protection
18 System," and the point to be made here is that this is
19 really the reactor protection system. There is a logic
20 associated with it bistables. It is maintained by
21 instrumentation and control technicians.

22 I distinguished that intentionally to make the
23 point that the trip breaker is a mechanical device and
24 the reactor protection system is an electrical type of
25 device. It has a logic and status indicator in the

1 control room at Salem and upon a valid reactor
 2 protection system signal, the protection system stops
 3 providing the holding of electrical voltage for the
 4 undervoltage coil and that deenergizes the coil
 5 resulting in a scram.

6 If the trip breaker physically does not open,
 7 the control room operators are required to initiate
 8 certain immediate actions. These I reflect on this
 9 slide as ATWS instructions and this represents the order
 10 of the trips in accordance with the instructions to the
 11 operator.

12 On February 25th, the first step, as you can
 13 see, was the manual trip from the control room. There
 14 is a switch that deenergizes both the undervoltage coil
 15 and energizes the shunt coil. Both of these steps
 16 result in a reactor trip, and we will go into more
 17 detail if you wish later on.

18 In addition, in the control room there are
 19 separate push buttons for each of the two reactor trip
 20 breakers. They both can be used to open and to close
 21 those trip breakers.

22 In the event of an anticipated transient
 23 without scram, the operators are directed to inject
 24 boron into the system and that is the next step to
 25 initiate safety injection.

1 CHAIRMAN PALLADINO: Is that a rapid boron
2 insertion?

3 MR. STAROSTECKI: That is the boron injection
4 tank and that gets inserted first, yes, sir.

5 The next step is obviously if the above steps
6 haven't been successful or even if they have been
7 carried out, they would then go to the local mechanical
8 push button on the individual breakers and physically
9 trip them there.

10 COMMISSIONER GILINSKY: How long would it take
11 to get there?

12 MR. STAROSTECKI: I haven't timed it, but I
13 would presume a few minutes. Walking up from that area
14 to the control room took us a few minutes. An
15 experienced operator may know a faster way than the way
16 we went on Saturday.

17 As a final point, the local breakers providing
18 supply power to the motor generator sets and also the
19 output of the generator motor sets can be locally
20 tripped to also secure power to the control rod drive
21 motors.

22 COMMISSIONER GILINSKY: And what other
23 consequences does that have?

24 MR. STAROSTECKI: The consequences of the
25 generator motor sets is to interrupt power to the

1 control rod drives. They are dedicated for the control
2 rod drives.

3 CHAIRMAN PALLADINO: This boron injection, is
4 it rapid and how rapid does it shut it down?

5 MR. STAROSTECKI: I don't have that detailed
6 information right now. The boron injection tank is
7 about 20,000 ppm boron, and I don't recall the exact
8 number for the concentrations required.

9 CHAIRMAN PALLADINO: Is that an effective
10 scram?

11 MR. EISENHUT: It is effective. The timing is
12 the question that you asked, and it is something that we
13 will have to get the answer to.

14 MR. CASE: It is not an effective way of
15 shutting the reactor down rapidly. It doesn't come in
16 that fast. You rely on the control rods for that.

17 MR. MATTSON: About five to ten minutes to
18 empty the big tank.

19 COMMISSIONER AHEARNE: Rich, the manual trip
20 No. 1, do they do that even if the system has
21 automatically tripped?

22 MR. STAROSTECKI: At Salem there has not been
23 a requirement to do that, and we will talk about this in
24 one of the corrective actions.

25 The next slide, please.

1 Just very briefly, we wanted to get some
2 information to show you what kind of information is
3 presented to the control room operator upon a reactor
4 trip. The positive indication that I have labeled
5 "Positive" is that there are two indicators, one from
6 the reactor protection system as displayed on that
7 status board and also on the breaker control push
8 button. There are lights that are physically actuated
9 by mechanical devices on breaker position. So that is a
10 positive indication of breaker position.

11 Rod position indicators indicating various
12 elevations of the rods, these are separate from what we
13 refer to as the rod bottom lights. Nuclear
14 instrumentation obviously would show reduction in power
15 and the plant computer prints the alarm signals.

16 CHAIRMAN PALLADINO: Is that item No. 1 such
17 that you get a direct signal and not just that the
18 current has been interrupted?

19 MR. STAROSTECKI: It is a direct signal based
20 on the position of the breaker itself.

21 The next slide, please.

22 This slide is intended to represent some of
23 the other alarms that the operators would be made aware
24 of in the event of a trip. The secondary reactor trip
25 alarms, obviously we would be getting the enunciators

1 for the negative rate trip, low-low levels in all steam
2 generators would occur and there would be an associated
3 turbine trip. The turbine trip itself can be noted with
4 several of its indicators, such as turbine speed
5 decreasing.

6 These two slides are solely provided to
7 indicate the kind of information associated with
8 legitimate reactor scram.

9 The next slide, please.

10 I would like to very briefly go over a trip
11 breaker history at Salem.

12 The reactor trip breakers at Salem arrived at
13 the site in approximately 1974. They are
14 interchangeable between units, and until 1982 the trip
15 breakers had no apparent problems.

16 It is not clear to us at this time as to
17 whether the trip breakers were treated as safety grade
18 and whether they had the appropriate preventive
19 maintenance, storage conditions and corrective
20 maintenance.

21 COMMISSIONER AHEARNE: I guess I am not really
22 clear about what you meant. Did you ask the licensee
23 did they class it as safety grade?

24 MR. STAROSTECKI: The licensee states that
25 they are classifying them as safety related.

1 COMMISSIONER AHEARNE: They did classify them
2 as safety related.

3 MR. CASE: Yet, some of the maintenance
4 instructions that were issued for those pieces of
5 equipment were checked non-safety grade. So there may
6 be discrepancy between intent and practice.

7 COMMISSIONER GILINSKY: What is the practice
8 throughout in the industry?

9 MR. CASE: I can speak as to what our position
10 is. I don't know that we have universal practice.

11 Roger, do you want to talk about safety grade
12 here?

13 MR. MATTSON: The trip system, and let me
14 state it generally and then try to state some
15 qualifications, is clearly part of the safety related
16 complement of equipment unequivocal in the licensing
17 history of PWRs and BRWs. The trip system is safety
18 related. Now I am talking about the Westinghouse design.

19 COMMISSIONER GILINSKY: Do you distinguish
20 that from safety grade?

21 MR. MATTSON: No. They use safety grade and
22 safety related interchangeably. In the Westinghouse
23 design there are a couple of what people will call
24 attachments when you get into this in a little depth.
25 One is the UV coil, the uncervoltage coil that causes

1 the breaker to open. That portion of the Westinghouse
2 design is safety grade, safety related.

3 There is a shunt coil, which you are going to
4 hear more about as this briefing goes on, that portion
5 is not safety related. You will see that it is
6 associated only with the manual scram in the
7 Westinghouse design.

8 It gets a little confusing when you broaden
9 your interest in scram systems because in some other PWR
10 designs both the shunt coil and the undervoltage coil
11 are part of the scram system, that is part of the safety
12 related portion of the scram system, but not in the
13 Westinghouse design. It meets the regulations with just
14 the UV portion being safety related, that is IEEE 279
15 single failure and all the things that go with a safety
16 grade system.

17 COMMISSIONER AHEARNE: And since there are two
18 of them you have redundancy.

19 MR. MATTSON: That is right.

20 COMMISSIONER GILINSKY: Can you activate the
21 UV coil manually?

22 MR. MATTSON: Yes.

23 CHAIRMAN PALLADINO: In what way is the shunt
24 not safety related?

25 MR. MATTSON: Well, it is used only in the

1 manual scram. Now the manual scram is not a safety
2 related scram. The safety related scram is an automatic
3 scram.

4 CHAIRMAN PALLADINO: I understand that. In
5 what way is that shunt not safety related?

6 MR. MATTSON: In the sense that it is not
7 automatic. That is one way it is not safety related.
8 In the sense that it is not required to be seismic. It
9 may be, but it is not required to be. In the sense that
10 its power supply need not be safety related, safety
11 grade.

12 Does somebody want to add one?

13 It is not fail safe. You have to energize it
14 to trip and it is not fail-safe.

15 COMMISSIONER GILINSKY: The manual system is
16 not under our requirements of safety related systems?
17 It does not have to be?

18 MR. MATTSON: In this design that is true. I
19 guess I shouldn't qualify it to this design. The manual
20 portion in any design is not.

21 COMMISSIONER GILINSKY: Does not have to be.

22 MR. MATTSON: That is right.

23 MR. CASE: Now I hesitate to get into this,
24 but you must understand that there are two groups of
25 equipment that are important to safety, one more

1 important to safety than the other. Safety related is
2 most important to safety and then there is another group
3 of equipment that is important to safety.

4 COMMISSIONER GILINSKY: I recognize that.

5 MR. MATTSON: I should correct something while
6 we are here on the record. IEEE 279 does require a
7 manual scram and that manual scram just be safety
8 related. The UV manual scram on the Westinghouse design
9 satisfies that requirement.

10 COMMISSIONER GILINSKY: So it is a safety
11 related manual scram, but it is just that they have an
12 additional feature on it which, since they already have
13 a safety related manual scram, they do not have to make
14 the other one safety related.

15 MR. MATTSON: Yes. I wasn't following your
16 question very well. Others were, and I apologize.

17 COMMISSIONER AHEARNE: Now getting back to
18 what it was or what it wasn't that they treated as
19 safety related, Rich, could you mention which piece of
20 it now. Is it the breaker itself that they weren't
21 treating as safety related?

22 MR. STAROSTECKI: We are not clear that the
23 other voltage attachment got the pedigree treatment in
24 terms of storage, corrective maintenance and preventive
25 maintenance.

1 MR. CASE: And traceability.

2 MR. STAROSTECKI: And traceability.

3 COMMISSIONER AHEARNE: But it is clear to the
4 NRC that it should have?

5 MR. STAROSTECKI: Yes, it is clear to us it
6 should have.

7 MR. CASE: And the licensee now states that it
8 is and should have been treated as safety related.

9 COMMISSIONER GILINSKY: Let's see, that is
10 part of the automatic system, too, though. So how could
11 there be any question about it?

12 MR. CASE: I don't think there is any
13 question. I just think in implementing the requirement
14 the licensee may have been ---

15 COMMISSIONER GILINSKY: Isn't that a pretty
16 serious lapse because it seems to me that is something
17 which isn't remotely in a gray area.

18 MR. CASE: It should be safety related.

19 MR. EISENHUT: Well, in our mind it is a very
20 significant device. So I say, yes, I agree. Secondly,
21 the question we are looking at and, as Rich said, we are
22 not clear to the degree to which from 1974 through last
23 weekend this undervoltage relay, which happens to be
24 this device that is sitting here on the table, had the
25 pedigree, was maintained as a safety related component,

1 et cetera, and that is something we are still pursuing.

2 COMMISSIONER GILINSKY: It is not clear at
3 this point whether in fact it did or didn't receive that
4 treatment?

5 MR. EISENHUT: That is right. There are a
6 number of questions that have been raised and that is
7 why today we are saying it is not clear.

8 MR. CASE: There is no doubt in my mind that
9 it was not in certain instances.

10 MR. EISENHUT: In certain instances there is
11 at least some instances where we have this problem. So
12 it is an area that we are still reviewing.

13 COMMISSIONER AHEARNE: Where does the Region
14 come out on that?

15 MR. STAROSTECKI: I think when you look at
16 some of the older plants and when you are talking
17 earlier than '74 when some of these things were being
18 bought, I think on the part of the licensee's behalf
19 they may not have been having the stringent requirements
20 in that day to apply the necessary pedigree to these
21 kinds of devices. So I think there is a gray area in
22 that we have gotten smarter about what kind of care we
23 ought to give to safety related equipment, and I think
24 we are looking at a problem that started over ten years.

25 COMMISSIONER AHEARNE: But the Region at the

1 moment is not yet certain whether or not they did give
2 the quality care to this equipment?

3 MR. STAROSTECKI: I have got a team of six
4 people on site now looking at the traceability aspects
5 and the history associated with the breakers and their
6 attachments. Right now I can't answer that, but I hope
7 to have that answered within about a week.

8 I will try and get through the rest of the
9 trip breaker history. Very quickly, they encountered no
10 real problems until August 20th of '82. During a
11 routine surveillance test they found that one of their
12 breakers, specifically the "B" breaker had a problem and
13 they replaced it with what is referred to as a bypass
14 breaker. During tests the bypass breaker is inserted
15 into the train.

16 COMMISSIONER GILINSKY: Let's see, did they
17 switch the breakers?

18 MR. STAROSTECKI: Yes. This means physically
19 they pulled two breakers out and swapped.

20 CHAIRMAN PALLADINO: What do you mean they
21 swapped?

22 MR. STAROSTECKI: They had a breaker in a
23 position called "A", reactor trip breaker "A" bypass,
24 and they put that into the reactor trip breaker "A"
25 position. The one they pulled out of the reactor trip

1 breaker "A" position they put into the bypass position
2 physically.

3 COMMISSIONER GILINSKY: Did they then test the
4 bypass breaker?

5 MR. STAROSTECKI: And they also replaced the
6 undervoltage attachment and then replaced the so-called
7 faulty breaker into the bypass position.

8 CHAIRMAN PALLADINO: I don't understand. If
9 you have a faulty breaker, why wouldn't you just replace
10 it with an unfaulty breaker?

11 MR. STAROSTECKI: My understanding is that
12 they do not have large spare breakers on site. They
13 determined that it was the undervoltage attachment that
14 was faulty. So they took out the bad breaker and put a
15 good one in.

16 MR. EISENHUT: There is a breaker and the
17 breaker is actuated by two devices. One is called an
18 undervoltage relay and one is a shunt relay.

19 The questions all related to the undervoltage
20 relay at this point, correct, Rich?

21 MR. STAROSTECKI: Yes.

22 MR. EISENHUT: And not to the breaker itself.
23 On semantics we get hung up here quite a bit. The
24 entire discussion that we are going to be going through
25 is really relating to an undervoltage relay and that is

1 a unit, not the coil, not the breaker but really the
2 whole piece of the undervoltage relay.

3 CHAIRMAN PALLADINO: Are you going to give us
4 a line diagram?

5 MR. EISENHUT: Yes, we are. We have a cartoon
6 even.

7 MR. STAROSTECKI: In summary then, in August
8 the breaker failed and the breaker failed because the
9 undervoltage coil was binding. The undervoltage coil
10 was replaced and in the process there was an interchange
11 of breakers at Unit 2.

12 COMMISSIONER GILINSKY: Did they know the
13 other one was good?

14 MR. STAROSTECKI: Before they returned it to
15 service, yes, they did surveillance testing on it.

16 COMMISSIONER AHEARNE: So it was an actual new
17 undervoltage coil they put in?

18 MR. STAROSTECKI: That is my understanding,
19 correct.

20 COMMISSIONER GILINSKY: How frequent an event
21 is that, for a breaker to fail a surveillance test?

22 MR. STAROSTECKI: Well, this is the first time
23 it happened at Salem.

24 MR. CASE: We have some slides later on on
25 voltage relay failures.

1 MR. STAROSTECKI: For all plants. This is the
2 first time it happened at Salem.

3 COMMISSIONER GILINSKY: Could you just give me
4 a hint of how frequent an event that is?

5 MR. MATTSON: There have been 35 since 1973 in
6 all PWRs.

7 CHAIRMAN PALLADINO: Thirty-five what?

8 MR. MATTSON: Breaker failures in the scram
9 system.

10 CHAIRMAN PALLADINO: In how long a period?

11 MR. MATTSON: 1973 to today.

12 MR. EISENHUT: How often are these tested,
13 Rich, the device here?

14 MR. STAROSTECKI: Their practice at Salem was
15 testing the device approximately once every two months.

16 MR. LAINAS: That is the undervoltage.

17 MR. STAROSTECKI: This is the undervoltage
18 attachment that trips the breaker. The breaker itself
19 may have been tested through the shunt mechanism for
20 other reasons.

21 CHAIRMAN PALLADINO: Roger, those 35 failures,
22 were those on surveillance tests?

23 MR. MATTSON: The 35 come from our LER data.
24 Do we have a feel for how many were on demand where they
25 had the single breaker failure?

1 (No response.)

2 MR. MATTSON: We can get that answer, but we
3 are not prepared today.

4 MR. STAROSTECKI: So the first indication at
5 Salem was in August of 1982 at Unit 2. In January of
6 this year Unit 2 again was at about 46 power and
7 encountered a low-low steam generator level trip. The
8 plant did trip and the "B" trip breaker did in fact
9 open. However, they discovered that the "A" trip
10 breaker failed to open. They decided to leave it in the
11 fail position for subsequent investigation and 25
12 minutes later the breaker itself opened automatically.

13 After they replaced the breakers in Unit 2
14 using the breakers from Unit 1, they did surveillance
15 testing and this is the first time that the licensee in
16 his evaluation had determined that they were not in fact
17 doing preventive maintenance on these breakers.

18 During this time period in January of 1983 ---

19 COMMISSIONER GILINSKY: Let's see, is that a
20 requirement or practice?

21 MR. STAROSTECKI: There should have been a
22 preventive maintenance program for safety related
23 equipment and this is the first time that such a program
24 was not in existence, or was determined not to be at
25 Salem.

1 MR. EISENHUT: Well, it is not the first time
2 that it was not in existence. It was the first time
3 that it was detected that from the window of time in
4 1974 through 1983 there had not at any time been a
5 preventive maintenance program which would in fact be
6 required for a safety related component.

7 Did I say that right?

8 COMMISSIONER GILINSKY: Let's see, how come
9 that doesn't get picked up our inspection?

10 MR. STAROSTECKI: We are now talking about a
11 sampling program and a large list of items. A computer
12 printout is about five inches thick as to requiring ---

13 COMMISSIONER GILINSKY: Well, was it
14 preventive maintenance on just this item?

15 MR. STAROSTECKI: It is just this particular
16 item. We are talking about the component specific
17 preventive maintenance and that is the safety related
18 aspect of the breaker. It is a very small piece of
19 equipment that we are now focusing in on.

20 COMMISSIONER GILINSKY: In other words, they
21 had a preventive maintenance program which overlooked
22 this one piece of equipment?

23 MR. STAROSTECKI: That is what we are saying,
24 yes.

25 COMMISSIONER GILINSKY: Somebody is shaking

1 his head back there.

2 MR. SNIEZEK: I think that is a question that
3 we ought to ask the licensee of what else in the plant
4 isn't being maintained that is safety related. I don'
5 think we can say it is just this breaker.

6 MR. CASE: As you will see, that is one of the
7 issues we are going to look into, and we are looking
8 into as it is listed later on.

9 COMMISSIONER AHEARNE: Did you intend in
10 covering that then to address the Westinghouse letter of
11 1974?

12 MR. EISENHUT: Yes.

13 MR. STAROSTECKI: That is later in the
14 presentation. The point to mention is is that it is in
15 the January time frame, as Darrell said, that this
16 information is coming out.

17 MR. CASE: Let me just answer it. The
18 licensee did not have the letter and therefore it was
19 not followed.

20 CHAIRMAN PALLADINO: Who didn't have the
21 letter?

22 MR. CASE: The licensee.

23 MR. EISENHUT: The licensee has stated that he
24 had no records of receiving or any knowledge of the 1974
25 Westinghouse guidance letter and accordingly it was not

1 followed.

2 COMMISSIONER GILINSKY: We are going to get to
3 that?

4 MR. EISENHUT: Yes, we are.

5 COMMISSIONER GILINSKY: Let me just ask you
6 about these failures to trip. Having two of them sounds
7 like a pretty unusual occurrence, and that there were 35
8 altogether since 1973 or '74 with two of them in one
9 plant fairly close together. Does that get picked up in
10 our system at all by AEOD or anybody?

11 MR. JORDAN: Yes, it was picked up and we were
12 in the process of reviewing it with Westinghouse. There
13 had been identified in the I&E reviews of those events
14 the failure and the discussion with Westinghouse over
15 the current instructions for lubrication for maintenance.

16 CHAIRMAN PALLADINO: Were all 35 Westinghouse
17 designs?

18 MR. CASE: No.

19 MR. JORDAN: No. This was based on Salem's
20 current history at that particular point.

21 MR. EISENHUT: Let's see, as it turns out we
22 had I believe, following on what Mr. Jordan said, we had
23 the February 22nd and these type failure events under
24 review at the very time of the February 25th review.

25 MR. IPPOLITO: I am Tom Ippolito of the

1 Operating Assessment Branch. Each morning we review
2 with I&E the events of the day before. When this Salem
3 transient happened on the 22nd, a number of things
4 happened which appear shortly. But one of the things
5 that caught our eye was a parenthetical phrase that said
6 something like however, the automatic scram preceded the
7 manual scram. That raised questions in our mind and we
8 were beginning to proceed to understand what that
9 actually meant.

10 Unfortunately, sometimes the data that you get
11 in these morning reports is garbled. So many of them
12 require us to follow up on them.

13 COMMISSIONER GILINSKY: This is something they
14 called in or what?

15 MR. IPPOLITO: Yes.

16 MR. STAROSTECKI: Every morning the Region
17 prepares what is called a daily report where we
18 summarize all the technical aspects and it is
19 distributed throughout the agency.

20 From a site specific basis, the residents were
21 in fact following these events and in fact we found that
22 the initial licensing event report for the first failure
23 was not adequate and therefore the licensee had
24 supplemented it in the January time frame. So there
25 were two things going on, the follow-up on the specific

1 action being taken at the site, plus there were
2 discussions in headquarters as to what this was meaning.

3 COMMISSIONER GILINSKY: How long does it take
4 for us to get informed about, well let's say, a
5 surveillance test failure or the more serious event, the
6 first of the events on the 22nd? Do they call that in
7 or is that just sent in?

8 MR. JORDAN: The reporting requirement is for
9 notification within an hour of a plant trip. So the
10 event of the 22nd was required to have been reported in
11 one hour. A surveillance test in which one breaker
12 would fail would presently be required to be reported
13 under the tech specs, Reg. Guide 116, which requires a
14 30-day report for that single breaker failure in a
15 surveillance test.

16 MR. CASE: But the licensee did not understand
17 on the 22nd that he had a failure to automatically
18 scram. That realization did not come to him until
19 sometime on Friday the 25th.

20 COMMISSIONER GILINSKY: Well, how was it that
21 they informed us, or did they inform us immediately?

22 MR. STAROSTECKI: Well, I really haven't
23 gotten that far. Let me just continue on the breaker
24 history.

25 COMMISSIONER GILINSKY: Good idea.

1 CHAIRMAN PALLADINO: Why don't we let him go
2 for a while.

3 MR. STAROSTECKI: What I am trying to do is
4 paint the situation as it happened, that is on August
5 20th was the first indication of a problem and on
6 January 6th the second indication of a problem. In the
7 January time frame I think it is important to recognize
8 that Unit 2 is shutting down for its first refueling
9 outage and in fact did shut down on January 21st. Unit
10 1 was in a shutdown condition at that time for its
11 fourth outage and they were preparing to bring it back
12 out of the outage.

13 During the January 13th through the 18th time
14 frame the Unit 1 breakers were being what one might call
15 overhauled for subsequent use as they come out of the
16 outage. This appears to be the first time that the
17 breakers are lubricated. There is some question, since
18 they didn't follow the 1974 Westinghouse guidance, as to
19 whether a solvent or a lubricant was used on the voltage
20 trip attachment.

21 COMMISSIONER GILINSKY: The first time since
22 when?

23 MR. STAROSTECKI: Since 1974 as best as we can
24 determine today.

25 So during the February '83 time frame the

1 breakers for Unit 1 were tested prior to coming out of
2 the outage.

3 As a result of problems with the feedwater
4 control system, Unit 1 at Salem has experienced a number
5 of trips due to the low-low steam generator level. The
6 first one of these was on February 20th where the trip
7 breakers functioned properly on two occasions. One time
8 was low-low steam generator level and the other
9 high-high.

10 CHAIRMAN PALLADINO: Excuse me. Is anybody
11 looking at that control system on the steam generator
12 level? Is that a source of another problem?

13 MR. STAROSTECKI: That is another problem that
14 the licensee had recognized and, as I indicate on
15 February 22nd, this problem relates somewhat to the
16 sluggishness of the feedwater control bypass valves
17 during manual operation from the control room. It is a
18 tricky operation and the licensee had done more
19 investigation into that. We will look at the role that
20 played next week.

21 Following the two successful trips on February
22 20th, there were two trips on February 22nd, with one
23 earlier in the day. The one earlier in the day again
24 involved the trip on low-low steam generator level.
25 They encountered problems upon restart in the fact that

1 they could not close one of the trip breakers and this
2 was due to the fact that there was a loose dust cover in
3 the breaker. So the "B" reactor trip breaker cover
4 plate problem simply is a reflection in my mind on the
5 fact that there was some loose material in there that
6 shouldn't have been.

7 CHAIRMAN PALLADINO: Was this dust cover
8 inside?

9 MR. STAROSTECKI: It sits on top of the
10 breaker.

11 CHAIRMAN PALLADINO: Can it interfere with
12 operation?

13 MR. STAROSTECKI: It interferes with closing
14 the breaker obviously. We don't know if it interferes
15 with the opening.

16 At this time they removed the feed bypass
17 valve position indicators. Again, they have recognized
18 that the source of the problem here from an operational
19 standpoint is the feedwater controls.

20 What I would like to very briefly do is
21 acknowledge that the next two events on February 22nd
22 and February 25th I in fact have summarized on the next
23 viewgraphs and I would like to defer a discussion to the
24 more detailed viewgraphs on those days.

25 The next slide, please.

1 The February 22nd event sequence was
2 associated with several problems in the plant. The root
3 cause of the problem was a faulty limit switch on some
4 electrical bus breakers. During the start-up the plant
5 is shifting certain buses from off-site sources of power
6 to the on-site sources of power since the reactor is
7 using about 20 percent.

8 During this transfer they encounter a number
9 of problems. The net result is they encounter a low-low
10 steam generator level in the auxiliary feedwater pump
11 start. At about the same time the operators had noted
12 that they had a deteriorating situation due to the
13 difficulty in transferring electrical buses and the
14 feedwater problems affecting steam generator level. So
15 they initiated at the direction of the shift supervisor
16 a manual reactor trip. The reactor tripped and the
17 turbine was tripped.

18 COMMISSIONER GILINSKY: What was this
19 degrading condition they were talking about?

20 MR. STAROSTECKI: Low steam generator levels
21 dropping with a recognition that if you add more water
22 it would be called and you would cause a further drop in
23 indicated steam generator level. So they were
24 anticipating the situation that they would trip on
25 low-low steam generator level and decided to manually

1 scram the plant rather than wait for the protection
2 system to do it. That was their logic.

3 CHAIRMAN PALLADINO: Aren't you supposed to
4 add more water when you get low?

5 MR. STAROSTECKI: You get an alarm at low
6 level.

7 CHAIRMAN PALLADINO: And what would you
8 normally do, not add water?

9 MR. STAROSTECKI: Well, you would add water at
10 that point, but if you are going down and you go through
11 the low-level alarm set point, I think an operator can
12 use his judgment and say I am not going to catch it.

13 COMMISSIONER GILINSKY: Let's see, why
14 wouldn't he try to ride it out, or was it absolutely
15 clear that they were going to trip?

16 MR. STAROSTECKI: Based on the discussions
17 with the operators, it was clear to them that they were
18 going to trip. If they didn't do anything they were
19 going to trip.

20 COMMISSIONER AHEARNE: You say the reactor
21 trip signal, was that the automatic trip signal?

22 MR. STAROSTECKI: The reactor protection
23 system logic sensed the low-low level and in fact called
24 for a trip signal and did generate a trip signal.

25 COMMISSIONER AHEARNE: Are you talking about

1 internal to the logic or something audible or visual?

2 MR. STAROSTECKI: You get both. You will get
3 the logic and the status board will indicate that the
4 logic is made up and then you will get the alarm and
5 enunciator saying you have a reactor trip.

6 COMMISSIONER AHEARNE: But the operator four
7 seconds later wasn't in response to that.

8 MR. STAROSTECKI: These are approximately four
9 seconds now. Let me just clarify that the time
10 difference of three and a half to four seconds we have
11 gotten looking at the computer printout after the fact.
12 On the day of the occurrence the operators believe that
13 they had almost simultaneously tripped the plant
14 manually. We make the distinction of three and a half
15 to four seconds based on an after-the-fact analysis of
16 the computer printout.

17 COMMISSIONER GILINSKY: Well, presumably they
18 thought they had manually tripped it in advance of the
19 automatic trip.

20 MR. STAROSTECKI: One of the operators had
21 believed that he had manually tripped the plant and he
22 believed that the automatic trip came in next.

23 MR. EISENHUT: Let's see, I should make it
24 clear that in fact the finding out that the reactor trip
25 signal got there and did not do the job first was found

1 last Saturday on the 26th. On February 26th it was
2 found during the discussions where the NRC team was at
3 the site. Up to that time the utility thought the
4 manual scram actually scrambled the plant. It came out
5 of an analysis of a computer printout off the plant
6 computer which tracks things in cycles and not even in
7 seconds, but it is a very accurate printout.

8 CHAIRMAN PALLADINO: Didn't the manual
9 actually scram?

10 MR. EISENHUT: The manual scram of the plant
11 after ---

12 MR. CASE: The automatic came in first.

13 MR. EISENHUT: The automatic signal should
14 have scrambled it, but in fact this is the first event
15 which was a failure to scram on a valid automatic signal.

16 COMMISSIONER GILINSKY: Well, let's see, you
17 don't have anything about that up there.

18 MR. STAROSTECKI: As we were going through
19 here what I wanted to do was indicate that the computer
20 printout had called for a reactor scram at a certain
21 point in time and the operators believed they had
22 manually scrambled the plant. When you look at the plant
23 computer, it records the plant trip signal from the
24 automatic system, then a manual trip initiated by the
25 scram switch and then a reactor trip.

1 COMMISSIONER GILINSKY: Is it common for
2 operators to scram the plant in advance of an automatic
3 scram?

4 MR. STAROSTECKI: That really reflects on the
5 training program and attitude of the management and
6 staff. Based on our discussions, this is what Public
7 Service Electric and Gas would expect from their
8 operators.

9 MR. EISENHUT: Commissioner, the two items up
10 there, the reactor trip signal from low-low, which was
11 enough to get the aux feedwater to start, indicates that
12 you do have a real RPS signal, but then four seconds
13 later the reactor trip breakers physically opened, which
14 is the indicator to us that there was in fact a failure
15 to scram on a valid RPS signal to the undervoltage
16 relays. In fact, that is the significance, the manual
17 scram system actuates both the undervoltage relay and
18 the shunt relay. Either one can do the job, and we will
19 be getting to that in a little diagram in just a couple
20 of moments.

21 MR. STAROSTECKI: Let me explain what the 54
22 seconds and the 58 seconds means after 2156. Upon
23 receipt of a reactor trip signal, it is a fraction of a
24 second later that the trip breakers should open. When
25 you see three to four seconds, it means that the first

1 trip didn't do the job.

2 Now on the 22nd because of the additional
3 complications, there was a combination of a loss of
4 reactor coolant pumps and feedwater pumps that resulted
5 in one steam generator being at a lower pressure than
6 the others creating a signal which thought there was a
7 main steamline break. This main steamline break
8 indication generates safety injection.

9 Safety injection was putting more water in the
10 plant and due to the loss of reactor coolant pumps the
11 pressurizer spray valve didn't have a driving head. So
12 the plant increased in pressure and the power operator
13 relief valves lifted at 2206 to relieve the excess
14 volume being given to the system by the safety injection.

15 When pressurizer level was up to 22 percent,
16 and it had previously dipped to about one percent, the
17 operators satisfied their criteria for terminating
18 safety injection. At that time the power operator
19 relief valves closed and the plant was shut down and in
20 hot standby.

21 NRC was notified at 2346.

22 The next slide, please.

23 MR. CASE: And I believe the block valve was
24 closed.

25 MR. STAROSTECKI: That is the next slide.

1 The occurrences, as you can see on February
2 22nd, were finished in the time frame of about 11
3 minutes after 10. At about 6:30 the next morning they
4 had excessive temperature indications on their tailpipes
5 and they closed the block valve because of the seat
6 leakage.

7 The licensee had done his evaluation on
8 February 23rd and had in fact started the plant back up
9 to power at 8:30 p.m. on the evening of February 23rd.
10 The initial licensee evaluation recognized that the
11 automatic trip signal was received first by the
12 protection system and they recognized that the manual
13 trip occurred second. They concluded based on that that
14 the plant had tripped on the automatic signal.

15 I mention this simply because of the need, as
16 we discuss later on, of the recognition of the time
17 frame that one should expect between receipt of a signal
18 and actual opening of the breaker.

19 COMMISSIONER GILINSKY: Let's see, they were
20 aware of this several second difference?

21 MR. STAROSTECKI: They obviously, based on
22 analysis today, did not recognize the fact that the
23 breakers physically had tripped as a result of the
24 manual trip. They saw a sequence which involved
25 protective system trip, manual trip and reactor trip.

1 This is somewhat speculative, but they looked at and saw
2 a reactor trip and they saw the trip signal first. The
3 presumption is that the protective system had opened the
4 breaker, and it is only upon subsequent evaluation after
5 the 25th where it was clearly a delayed response. It
6 only after you recognize the time frame between the
7 generation of the trip signal and the opening of the
8 breaker to be a fraction of a second that you would look
9 for it. They were not looking for it.

10 COMMISSIONER GILINSKY: I think it would be
11 useful at the end of this session if the company had a
12 few words just to comment on anything that may have been
13 said during the course of our meeting.

14 MR. EISENHUT: The company is here and I think
15 they are prepared to do that.

16 CHAIRMAN PALLADINO: Well, why don't we move
17 along and see where we come out.

18 MR. STAROSTECKI: The next slide, please.

19 The sequence of events for February 25th,
20 again this is Unit 1. The reactor is being started up
21 and they were synchronized with the grid. The feedwater
22 system again is in manual control and again the
23 feedwater system was giving them difficulty.

24 They generated a low-low level, the reactor
25 trip signal ---

1 COMMISSIONER GILINSKY: Let me just take you
2 back. You said earlier that the fact that there was a
3 several second difference between those two events made
4 it clear that the plant hadn't tripped on the automatic
5 signal. Was that self-evident and, if so, why wasn't it
6 clear to the company?

7 MR. STAROSTECKI: As you go through the
8 February 25th event, it is very clear that people
9 recognized that the plant didn't automatically trip.
10 Now when you look at the plant computer it records time
11 in cycles, 60 cycles per second. When you look at
12 February 25th you find that it is about three to four
13 cycles between trip signal manually and reactor trip
14 breaker opening. So it is about four cycles.

15 When you go back and look at the February 22nd
16 event, the same situation exists. There was a trip
17 signal and a certain number of cycles, four cycles
18 later, that the reactor trip breakers opened.

19 COMMISSIONER GILINSKY: When you say four
20 cycles ---

21 MR. STAROSTECKI: It is four cycles on the
22 computer that is indicative of a successful trip breaker
23 opening upon receipt of a valid demand signal. So if
24 there is a signal one should expect four cycles later in
25 computer time to see the trip breaker open.

1 COMMISSIONER GILINSKY: And the cycle you say
2 is a 60th of a second?

3 MR. STAROSTECKI: Yes. Now on February 22nd
4 it is on the order of 150 cycles and I can't quote the
5 number.

6 MR. EISENHUT: It is about three and a half
7 seconds.

8 MR. STAROSTECKI: It is about three and a half
9 seconds, so it is about 190 cycles or thereabouts. But
10 it is the disparity between three and four cycles and
11 several hundred cycles.

12 MR. EISENHUT: Rich, I think one thing that
13 helps is on Monday when we met with the utility, the
14 utility's explanation of going back actually and walking
15 us through this with his own viewgraphs, and the
16 explanation that Rich is giving, the factual series of
17 numbers, is in fact the utility's understanding, too.

18 The missing of it is something that is going
19 to have to be continued to be evaluated. However, the
20 fact that, and I don't think there is any debate, that
21 the utility is in fact presenting the information that
22 says that upon detailed evaluation of the computer
23 printout in terms of cycles, which he presented Monday,
24 there was a valid signal that would have indicated that
25 the breakers should have opened and they did not open,

1 and they now believe that the breakers opened as a
2 result of the manual scram when they should have opened
3 as a result of the RPS automatic scram.

4 COMMISSIONER GILINSKY: But that was not
5 recognized until after ---

6 MR. CASE: And the fact that it wasn't
7 recognized is one of the issues we are looking at in
8 this evaluation.

9 MR. EISENHUT: It still needs to be
10 evaluated. At this point it is pretty well zeroed in
11 that in fact that factually happened. We first heard
12 about it on Saturday, as I said, when there was an NRR
13 regional team at the site and the utility presented the
14 data on Monday in support of that.

15 MR. CASE: But it is also fair to say that
16 when we got the daily report on Wednesday or Thursday,
17 we were suspicious and we are looking into that very
18 matter.

19 MR. EISENHUT: For the February 22nd event.
20 We in fact already had a meeting on the very issue.

21 COMMISSIONER GILINSKY: That was the thing Tom
22 was referring to?

23 MR. CASE: Yes, sir.

24 MR. EISENHUT: Yes.

25 MR. LAINAS: I think it is fair to say that as

1 far as the February 22nd event that what the utility
2 said was it was more or less of an anticipatory type of
3 scram by the operator. He saw his level getting away
4 from him. So he went and hit the scram before he got an
5 automatic scram, and when it occurred it assumed that it
6 was simultaneous or very close together.

7 On the February 25th event there was a longer
8 time period there where he knew he didn't have a scram
9 automatically.

10 CHAIRMAN PALLADINO: Why don't we go on.

11 MR. STAROSTECKI: Let me just very quickly go
12 through the February 25th event. After they determined
13 that they had a problem with the scram system, they
14 satisfied themselves by testing the protection system
15 five times. They installed artificial trip signals into
16 the protection system and satisfied themselves that the
17 logic circuitry was correct. Trip breaker "A" failed
18 three times to open and "B" breaker failed five times.

19 Upon determining that they had faulty trip
20 breakers, they declared the alert, make the
21 notifications and then terminated the alert at 2 o'clock
22 in the morning.

23 Subsequent to this, about 3:30 in the morning
24 they replaced the trip breakers in Unit 1 with the trip
25 breakers from Unit 2 and ran three more tests and

1 satisfied themselves that the logic circuitry was still
2 working properly and the trip breakers from Unit 2 in
3 fact did work satisfactorily three times.

4 COMMISSIONER ROBERTS: Let me ask a question.
5 The undervoltage trip mechanisms for Unit 1 were given
6 maintenance in January?

7 MR. STAROSTECKI: Yes, sir.

8 COMMISSIONER ROBERTS: It is unclear whether
9 they had ever had any previous maintenance.

10 MR. STAROSTECKI: That is correct. In a
11 nutshell the breakers that failed to trip on February
12 22nd and 25th had successfully tripped previously within
13 a matter of weeks and these were the breakers that were
14 so-called overhauled, had maintenance performed and were
15 reassembled.

16 CHAIRMAN PALLADINO: Are you looking into
17 whether or not the maintenance was appropriate?

18 MR. EISENHUT: Yes.

19 MR. STAROSTECKI: Yes, we are, and one of the
20 questions there obviously is what kind of lubricant or
21 solvent was in fact used. That is one of the issues
22 outstanding.

23 MR. EISENHUT: Perhaps we could switch now to
24 Gus Lainas who is going to be addressing some of the
25 design aspects.

1 CHAIRMAN PALLADINO: You started to tell me
2 about something you were going to tell us about
3 something at 3:30 and I didn't pick that up.

4 MR. STAROSTECKI: Well, at 3:20 in the morning
5 after 0200, after they terminated the alert, they took
6 the breakers from Unit 2, which is now in a refueling
7 outage, and installed them in Unit 1 to further satisfy
8 themselves that the logic circuitry was correct and in
9 fact the Unit 2 breakers had operated satisfactorily.

10 CHAIRMAN PALLADINO: Okay, thank you.

11 MR. EISENHUT: If I could then, we will go to
12 the summary of the event and we will be at least
13 itemizing and discussing some of the areas we are going
14 to continue to evaluate prior to a restart decision on
15 the plant, but we recognize that our review in all those
16 areas is not complete since it is still unfolding. We
17 will try to give you a graphic description here of what
18 the system looks like to explain some of the confusion
19 of questions before.

20 COMMISSIONER GILINSKY: Let's see, you are
21 going to go into more detail on the February 25th event
22 now?

23 MR. EISENHUT: Yes. Well, we will start from
24 the system approach ---

25 MR. CASE: Not into the event itself.

1 MR. EISENHUT: Not into the event sequence
2 itself, but into the explanation of how the system works
3 and the areas and the issues we are looking at, so to
4 speak, prior to any restart decision.

5 COMMISSIONER GILINSKY: In that case let me
6 just ask a question. I am not sure I understood what
7 you meant when you said each breaker tested five times.

8 MR. STAROSTECKI: The individual breakers were
9 tested as a result of the instrumentation control staff
10 performing surveillance tests on the protection system
11 logic. They insert false signals to generate low-low
12 steam generator trip signals that in fact product the
13 loss of voltage for the UV coil to trip. As part of
14 this test they verify that they generate the signal,
15 they get the trip signal from the logic and they verify
16 that the breakers are open.

17 They did the test for each of the low-low
18 steam generator's protection system logic plus one spare
19 giving them five tests. For those five tests they
20 looked at each individual breaker. I don't want to
21 create the misimpression that each individual breaker
22 was approached and tested separately five times. That
23 is not the case. Each breaker was tested five times as
24 a result of testing the protection system logic five
25 times.

1 COMMISSIONER GILINSKY: Let's see, why was an
2 alert declared?

3 MR. STAROSTECKI: An alert was declared
4 because, in accordance with the Salem precedures, when
5 they have a plant trip called for and the rods don't go
6 in they are required to call an alert.

7 COMMISSIONER GILINSKY: But at this point the
8 rods had gone in.

9 MR. STAROSTECKI: At this point the rods had
10 gone in but they had satisfied themselves as result of
11 the testing that the rods had not gone in.

12 MR. EISENHUT: Originally on demand.

13 MR. STAROSTECKI: As originally required on
14 the demand of the protection system, they satisfied
15 themselves that it was not a protection system logic
16 failure and it was truly reactor trip breaker failure.

17 MR. JORDAN: The notification was that they
18 had had an alert situation and they were advising us
19 that they had met the threshold from NUREG 0654
20 classifying it as an alert, but it was an administrative
21 condition and the plant was not in jeopardy at that
22 point.

23 COMMISSIONER GILINSKY: I wonder if you could
24 just go through the event in a little more detail.

25 COMMISSIONER AHEARNE: Before they go into

1 more detail in the event, could we take a minute and
2 have Gus go through the system.

3 CHAIRMAN PALLADINO: Yes, I am waiting for
4 that. That is one of the problems I am having, I am
5 waiting until I understand the system a little bit.

6 (Laughter.)

7 MR. LAINAS: Why don't you put the next slide
8 on.

9 What I will try to do is go through a series
10 of functional diagrams to try to give a better
11 perspective of what is going on.

12 On the right-hand side of the diagram you can
13 see where the trip breakers are located. I mean there
14 are two breakers in series that separates the power
15 sources from the power to the control rods and the
16 control rods are bound in scram.

17 The signals to those breakers come from the
18 automatic protection system and they can also be
19 manually actuated. Each of the trip breakers have two
20 tripping devices on them and when you deenergize the
21 control rods drive in. One is an undervoltage relay
22 that we were talking about this morning, and I will
23 start passing this around.

24 MR. EISENHUT: You might want to go through
25 the explanation first.

1 MR. LAINAS: So we have two, the undervoltage
2 relay and the shunt trip. The automatic protection
3 system goes to the undervoltage relay as shown over
4 here. What happens is when the automatic protection
5 system is actuated, voltage is removed from this device
6 and the breaker is tripped.

7 Now when you look at the manual protection
8 system, we have two ways of doing that from the control
9 room. You have the manual scram and you have individual
10 breaker controls. The manual scram, which is a scram
11 switch in this case, goes to both the undervoltage and
12 the shunt trip. The reactor breaker controls located at
13 the control panel go to the shunt.

14 MR. EISENHUT: They go to the shunt trip on
15 either breaker. The little cartoon here is missing one,
16 but it goes to both of them.

17 CHAIRMAN PALLADINO: What is missing?

18 MR. EISENHUT: Each one of the three controls
19 goes to a shunt trip on both of them.

20 MR. LAINAS: For each breaker the manual scram
21 actuates both devices. The reactor breaker controls
22 actuate just the shunt trip.

23 On the next diagram which is a little bit busy

24 ---

25 CHAIRMAN PALLADINO: I am sorry, you said

1 something at the end that negated what you just said
2 before. You said the breaker only goes to one.

3 MR. LAINAS: It goes to the shunt trips of
4 each breaker. There is a line missing.

5 The next diagram is a little bit busy, but if
6 you will again look at the right side of the diagram
7 there are MG sets which convert the power to 280 volt
8 AC. The significant difference that I show on the
9 right-hand side is that there are bypass breakers that
10 are put into service when you are periodically testing
11 the main breakers.

12 CHAIRMAN PALLADINO: And that is their only
13 purpose?

14 MR. LAINAS: That is their only purpose, that
15 is correct. And while the testing is going on the
16 bypass breakers can be actuated by the automatic
17 protection system.

18 As long as we are talking about testing ---

19 COMMISSIONER ROBERTS: Or by the manual,
20 either.

21 MR. LAINAS: Oh, yes, they are completely
22 functional. There are separate switches in the control
23 room by which you can manually trip the bypass breakers,
24 and of course the scram switch also actuates it. So you
25 have full protection.

1 CHAIRMAN PALLADINO: By while the bypass
2 breakers are in service they get the same kind of
3 treatment as the other?

4 MR. LAINAS: That is right.

5 Now as long as we are talking a little bit
6 about the difference between the undervoltage and the
7 shunt, maybe we can say a little something about the
8 testing.

9 Periodically the undervoltage is tested at
10 bi-monthly intervals where they actually go in, an I&C
11 technician goes in and simulates undervoltage from the
12 automatic system and watches that the breaker trips.

13 The shunt coil is actuated from the control
14 room manually on a seven-day period. That becomes
15 significant later on where the licensee is proposing to
16 increase the frequency of the testing of the
17 undervoltage.

18 CHAIRMAN PALLADINO: By bi-monthly you mean
19 every other month?

20 MR. CASE: Every other month.

21 MR. LAINAS: It was every other month.

22 CHAIRMAN PALLADINO: You say the shunt is
23 tested every ---

24 MR. LAINAS: Every seven days.

25 MR. JORDAN: I guess maybe for clarity there

1 was a statement that the bypass was as good as the
2 normal breaker. The bypass is actuated by only half of
3 the ---

4 MR. LAINAS: A single channel.

5 MR. JORDAN: That is right. So you don't have
6 the full protection since you only have one channel
7 feeding it.

8 MR. LAINAS: That is right.

9 CHAIRMAN PALLADINO: But you don't bypass both
10 of those?

11 MR. LAINAS: You don't do them both at the
12 same time.

13 COMMISSIONER GILINSKY: Is the bi-monthly test
14 specified in the tech specs?

15 MR. LAINAS: Yes.

16 MR. EISENHUT: You really test one monthly and
17 you alternate so that you end up in essence getting each
18 device every 60 days. That is what the tech specs say.

19 MR. LAINAS: The upper-left-hand corner of the
20 automatic protection system shows from the sensors
21 through the actuation logics to the breaker controls
22 themselves.

23 As you can see, there are computer signals for
24 each of the bistables which would indicate what gave you
25 the trip.

1 COMMISSIONER GILINSKY: Say that again.

2 MR. LAINAS: The computer signals that you see
3 there, the "C's", that is what was used in the event
4 recorder which was checked after the event.

5 COMMISSIONER GILINSKY: Is there an indication
6 on the control board what the cause of the trip was,
7 whether it is automatic or manual?

8 MR. STAROSTECKI: In the control room there is
9 a status board which shows a mimick of the logic diagram
10 to show you the generation of the input signals.

11 MR. LAINAS: We can show you a diagram on that.

12 COMMISSIONER GILINSKY: Well, does it indicate
13 whether it was manual or automatic?

14 MR. STAROSTECKI: No, it just indicates
15 whether the protection system thought there was a trip
16 signal generated or not. Then there are separate lights
17 for whether the breaker actually is opened or not.

18 COMMISSIONER GILINSKY: What you are saying is
19 that there is no indication whether the actual trip was
20 caused by the manual trip or by the automatic trip?

21 MR. STAROSTECKI: There is no enunciator that
22 gives you that information. That requires analysis of
23 the computer printout.

24 MR. LAINAS: There is an indication of a
25 breaker trip. When the breaker trips there is a limit

1 switch and on the panel there is an indication of when
2 that tripped.

3 COMMISSIONER GILINSKY: Just to repeat the
4 question, there is not an indication of whether it was
5 the automatic or manual scram that actuated the trip?

6 MR. LAINAS: No, but there is an indication on
7 the panel which indicates whether the breaker is open.

8 MR. STAROSTECKI: The answer is no, there is
9 no device to discriminate between automatic and manual.

10 MR. LAINAS: The next slide is trying to get
11 into the mechanical aspects of the trip breaker. As you
12 can see, again repeating, there is a shunt trip and an
13 undervoltage trip. Significantly here there is a
14 mechanical linkage as you can see from the device itself.

15 CHAIRMAN PALLADINO: Where is the device?

16 MR. LAINAS: Between the undervoltage trip
17 coil and the trip bar.

18 MR. EISENHUT: We will pass this around. It
19 suffices to say that basically the breaker, which we
20 have a picture of, has a bar in it.

21 Why don't you go to the next slide.

22 This device is reset by a bar which in essence
23 cocks the relay and the bar on the breaker sets on the
24 bottom device, this little tab here on the bottom.
25 There is, besides the undervoltage relay, there is also

1 a shunt relay. So either one of the two devices can
2 flip the bar up.

3 The device, just to show you, there is a
4 little arm in here, that Gus will be talking about in a
5 minute, which when you pull it back actually cocks the
6 device and this is, incidentally, one of the faulty
7 devices that was taken out of the plant. This
8 particular device we are going to be talking to the
9 utility about and we are trying to get a contractor to
10 examine it. But this is one of the devices that can
11 actually hang up.

12 CHAIRMAN PALLADINO: Is that what happened?

13 MR. EISENHUT: Basically, as Gus will explain
14 in a minute, that is what is believed to have happened,
15 but it is the linkage between the cocking arm and when
16 this becomes deenergized it is supposed to flip up and
17 trip the bar.

18 CHAIRMAN PALLADINO: This happened on both of
19 these breakers?

20 MR. EISENHUT: Yes.

21 MR. LAINAS: Yes.

22 CHAIRMAN PALLADINO: There is something I have
23 not yet understood. It sounds to me like, since the
24 manual works on the same mechanical devices, were we
25 just lucky that when we called for manual scram we got

1 it?

2 MR. EISENHUT: The manual works on both the
3 undervoltage and the shunt at the same time. Either one
4 of the two will actuate and lift the bar. So it is
5 believed that the shunt device ---

6 CHAIRMAN PALLADINO: If it was a mechanical
7 failure, then neither ---

8 COMMISSIONER GILINSKY: The Chairman is saying
9 if it was stuck.

10 (Laughter.)

11 MR. EISENHUT: The way it is designed, if it
12 stuck, it can remain stuck and the shunt coil can
13 operate it because the bar sets on the piece of metal.
14 The bar can be flipped up by the shunt coil and this
15 could be locked or frozen or whatever and would have no
16 effect if the shunt coil actually fulfilled its function.

17 COMMISSIONER GILINSKY: It depends on what is
18 stuck.

19 MR. EISENHUT: No, this device could be frozen.

20 CHAIRMAN PALLADINO: Are there two ways of
21 breaking the current?

22 MR. LAINAS: Why don't you put the next
23 diagram on.

24 MR. EISENHUT: We have a cartoon here.

25 COMMISSIONER GILINSKY: Well, if the

1 mechanical failure is in this device ---

2 MR. EISENHUT: If the undervoltage relay is
3 what is frozen or hanging up, then the device will still
4 work. If the failure were in the breaker itself, then
5 you would not have gotten a scram even on the manual
6 button.

7 COMMISSIONER GILINSKY: And you are saying the
8 difficulty is in here? '

9 MR. EISENHUT: Well, the belief right now from
10 the utility is that they have identified the failure in
11 this device because when they actuated the manual scram
12 button the breaker did function. In fact, as Rich
13 Starostecki pointed out, when they then tried to test
14 these devices they have in fact been found to be hanging
15 up.

16 MR. CASE: Could we return to Commissioner
17 Gilinsky's questions.

18 CHAIRMAN PALLADINO: Can you answer my
19 question. Were we lucky that it opened or was it such
20 that the interruption of the current was forced?

21 MR. EISENHUT: Well, I don't know.

22 CHAIRMAN PALLADINO: I don't know what this
23 shunt is doing. I pictured the shunt as something that
24 shunts the current away.

25 MR. STAROSTECKI: Let me just say that the

1 shunt attachment looks physically similar to what you
2 are holding in your hand with the exception that you
3 don't have an elaborate mechanical linkage. The shunt
4 relay is a coil that energizes to lift that little
5 mechanism on the bottom which is a trip latch.

6 MR. EISENHUT: But, Rich, not to lift any
7 piece on there.

8 MR. STAROSTECKI: There are no other
9 mechanisms on the shunt coil. It only has a little trip
10 latch on the bottom with a spring and when you energize
11 the shunt it lifts that latch.

12 CHAIRMAN PALLADINO: I see.

13 MR. STAROSTECKI: This device, because it is
14 deenergized to function, has additional features on it
15 to make it fast acting and to perform its function.

16 MR. EISENHUT: Following on what Rich was
17 saying, the breaker itself has a bar on it, and under
18 that bar there are basically two tabs. One tab comes
19 off the undervoltage relay and one tab comes off the
20 shunt relay. Either one of the two is believed to be
21 able to lift the breaker arm and in fact break the
22 circuit.

23 This device is believed to have failed and not
24 lifted the bar, but upon pressing the manual scram you
25 give a signal to both and the shunt relay is believed to

1 have been the one that raises the arm.

2 COMMISSIONER ROBERTS: To go back to your
3 previous slide, what is the mechanical push bar? Is
4 that physically on the piece of equipment?

5 MR. LAINAS: Yes, it is on the breaker itself.

6 MR. EISENHUT: Gas has a cartoon here which
7 may help.

8 MR. LAINAS: I don't know if it will help or
9 not.

10 (Laughter.)

11 COMMISSIONER GILINSKY: Actually if we
12 understand that what you are giving us is the correct
13 explanation, then to follow the Chairman's question, I
14 suppose we are lucky they had a shunt trip coil.

15 MR. EISENHUT: I think that is correct.

16 CHAIRMAN PALLADINO: Even though that is not
17 safety grade.

18 COMMISSIONER GILINSKY: Even though that is
19 not safety grade or required.

20 MR. CASE: It was put there deliberately to
21 provide a diverse way of scrambling the reactor.

22 COMMISSIONER GILINSKY: That is right.

23 MR. CASE: I don't quite consider that luck.
24 It was deliberately done.

25 CHAIRMAN PALLADINO: I agree. That is not

1 what I was referring to when we taked about it.

2 Okay, do you want to move on.

3 MR. LAINAS: This is again I guess repeating
4 some of what was said. The first thing you should look
5 at is the shunt trip coil in the upper-right-hand corner
6 of the slide and the undervoltage trip mechanism on the
7 left. Those again at the two tripping devices for the
8 breaker.

9 COMMISSIONER AHEARNE: If you could just walk
10 me through your device. The circuit that you are trying
11 to break is the -- (Inaudible).

12 MR. LAINAS: That is right.

13 COMMISSIONER AHEARNE: So you are trying to
14 show the trip as you are pulling away ---

15 MR. LAINAS: Opening the contact, right.

16 COMMISSIONER AHEARNE: And there is a spring
17 bolted device that is going to ---

18 MR. LAINAS: --- kick the trip release bar.

19 COMMISSIONER AHEARNE: Where it says trip
20 release bar, you have got to pull that bar out of the
21 way and that spring activates the device ---

22 MR. LAINAS: Exactly.

23 COMMISSIONER AHEARNE: And now you are talking
24 about the various ways to lift that trip release bar?

25 MR. LAINAS: That is right.

1 COMMISSIONER AHEARNE: Now the mechanical trip
2 push bar, that is at the cabinet?

3 MR. LAINAS: That is at the cabinet, yes.

4 CHAIRMAN PALLADINO: That is what I was
5 worried about when I asked you before. All these other
6 things on the right still have to go the electrical
7 circuits.

8 MR. LAINAS: That is exactly right.

9 COMMISSIONER AHEARNE: The straight mechanical
10 trip ---

11 MR. LAINAS: Is local.

12 CHAIRMAN PALLADINO: The straight mechanical
13 trip is that bar up at the top?

14 MR. LAINAS: Yes. What I will do is I will
15 send around pictures of the breaker itself, the entire
16 breaker.

17 CHAIRMAN PALLADINO: I might get more out of
18 the cartoon.

19 MR. LAINAS: Okay, sure.

20 CHAIRMAN PALLADINO: The mechanical trip is
21 that bar up at the top?

22 MR. LAINAS: Yes.

23 CHAIRMAN PALLADINO: And that actually pushes
24 down and trips the release button.

25 MR. LAINAS: Right.

1 MR. EISENHUT: And the release bar over here
2 on the side, the trip release bar, is the bar that has
3 both the undervoltage and the shunt.

4 MR. LAINAS: The point that should be made is
5 that for the undervoltage trip mechanism itself, there
6 is a linkage involved that you can see from what we
7 passed around. The shunt trip coil is more positive.

8 COMMISSIONER AHEARNE: Let's see, the shunt
9 trip coil you have to energize, correct?

10 MR. LAINAS: That is right. One way of doing
11 it is with the manual scram switch.

12 COMMISSIONER AHEARNE: Or the breaker manual.

13 MR. LAINAS: I am sorry, or the breaker
14 manual, right.

15 CHAIRMAN PALLADINO: Could you use the shunt
16 if you had no power?

17 MR. LAINAS: No.

18 MR. CASE: The shunt requires power.

19 MR. LAINAS: The shunt coil.

20 COMMISSIONER AHEARNE: What is the automatic
21 scram contact?

22 MR. LAINAS: That is from the protection
23 system. As you can see, the automatic protection system
24 throws the undervoltage.

25 COMMISSIONER AHEARNE: The manual scram switch

1 that you have indicated there ---

2 MR. LAINAS: That does both.

3 COMMISSIONER AHEARNE: --- its normal
4 condition is that it has closed the circuit to the
5 undervoltage mechanism and when you push the man scram
6 switch you open the undervoltage or you cut out the
7 undervoltage?

8 MR. LAINAS: That is right.

9 MR. CASE: And provide current to the shunt
10 trip.

11 MR. LAINAS: That is how in fact the reactor
12 was scrambled.

13 The next one is just a little more detailed
14 than the first one.

15 COMMISSIONER AHEARNE: But if you have lost
16 all power, the only way to do it is by the mechanical
17 trip?

18 MR. LAINAS: But you lose power to the drives,
19 in other words, if you lost MG power.

20 CHAIRMAN PALLADINO: If you lost all power I
21 thought you would deny yourself the shunt, but wouldn't
22 you get it to scram?

23 MR. LAINAS: Well, it depends on where you are
24 talking about loss of power. Loss of control power?

25 COMMISSIONER AHEARNE: Yes.

1 MR. LAINAS: Loss of control power, well
2 again, it depends on where the failure is.

3 CHAIRMAN PALLADINO: Let's just assume they
4 had no failure, just to understand how it works.

5 MR. LAINAS: Well, if I had a loss of off-site
6 power, let's say, a loss of all incoming power to the
7 MG's. The MG sets would stop and you drop down. If you
8 had specific loss of power to the shunt coil, you
9 couldn't use that.

10 CHAIRMAN PALLADINO: Suppose I lost power to
11 the undervoltage trip mechanism.

12 MR. EISENHUT: That is a design that is in
13 fact supposed to drop the rods.

14 MR. CASE: Unless there is a hang up in the
15 mechanism.

16 COMMISSIONER AHEARNE: The 48 volt DC system
17 which you have listed here, if you lost that, then it
18 looks by your diagram that the only thing you would have
19 is the mechanical trip.

20 CHAIRMAN PALLADINO: That is what I was asking
21 before.

22 COMMISSIONER ASSELSTINE: If you lost power
23 during this incident.

24 MR. LAINAS: Yes.

25 CHAIRMAN PALLADINO: Say that again.

1 MR. LAINAS: If you loss 48 volt ---

2 COMMISSIONER AHEARNE: Right, that takes out
3 both your undervoltage ---

4 MR. STAROSTECKI: I think that needs some
5 clarification. This is a functional diagram. The power
6 source of 48 volt DC going to the undervoltage coil is
7 separate from the power going to the shunt coil.

8 COMMISSIONER AHEARNE: Okay.

9 MR. STAROSTECKI: This just represents a power
10 source.

11 MR. LAINAS: Yes.

12 COMMISSIONER AHEARNE: Okay.

13 MR. LAINAS: I didn't plan to go into the next
14 one. It is just a little bit different.

15 MR. EISENHUT: There is one thing on this on
16 this diagram or cartoon here, the latch paw. The
17 culprit, so to speak, is that this latching mechanism
18 has been believed by the utility as what is hanging up.
19 In fact, the device that we sent around was one that you
20 could almost hang up if you cock it. In fact, it will
21 sometimes almost hang up before it releases, and there
22 is a little latching mechanism when you cock it.

23 COMMISSIONER AHEARNE: So you think that is
24 what ---

25 MR. EISENHUT: That is in fact what the

1 licensee attributes the problem to, and it is fair to
2 say it is something we are still looking at.

3 Before we go on to the corrective actions, we
4 had one point on what is available in the control room
5 and what kind of indications you get in response to
6 Commissioner Gilinsky's question.

7 Roger, I wonder if you want to amplify that.

8 MR. MATTSON: I wonder if we could go back to
9 the slide that is the reactor trip system. I believe it
10 was the second in this series of pictures.

11 Commissioner Gilinsky was asking what was
12 available in the control room for the operator to know
13 after the February 22nd trip what was the source of the
14 trip. We talked about the computer printout from the
15 event recorder being available but not being studied and
16 analyzed until some time later, and that clearly showed
17 that it was the manual that caused the trip even though
18 the automatic had come in earlier and should have caused
19 the trip.

20 There is another indication of the fact that
21 this electronics sends a signal wanting a trip, and that
22 is an enunciator that goes in the control room. We
23 could ask the Salem people. Most control rooms have a
24 first in light, and it is after the trip signal has been
25 received a light goes on that tells the operator what

1 the signal originated from. That probably went on, or
2 something like that, in the Salem control room.

3 The point that Mr. Starostecki was making is
4 that these breakers over here don't send the signal to
5 anything in the control room other than the computer
6 saying what they opened on. Once they open, then the
7 operator says well, I see this, but I also know I
8 scrambled with the manual button. The only way he is
9 going to be able to tell the difference we think is by
10 either detecting that this went off four seconds before
11 he hit the botton, which is a pretty close call, or by
12 reading the computer.

13 COMMISSIONER GILINSKY: Well, let's see, four
14 seconds, isn't all that short if there is an enunciator.

15 CHAIRMAN PALLADINO: It depends on how busy
16 you are.

17 MR. MATTSON: I didn't want to close the
18 review. I just wanted to straighten out that it appears
19 that we were saying there wasn't any indication that
20 there was an automatic trip signal other than the
21 computer printout, and that is not right. There is
22 another automatic trip signal and that is this
23 enunciator I just pointed to. Whether or not the
24 operator should have know that or not, we need to know
25 more about what was going on and we need to study it a

1 little further.

2 MR. STAROSTECKI: The fact that the protection
3 system got a valid trip signal was recorded on the
4 indicating lights. So the information was presented to
5 the operator that the protection system called for a
6 low-low steam generator level trip and that was
7 indicated. Because the operator thought he manually
8 tripped the plant first before that signal got locked
9 in, in response to that question of whether he could
10 discriminate whether he tripped the plant or whether the
11 protection system tripped the plant, there is no
12 automatic device to tell him that. That requires
13 evaluation.

14 CHAIRMAN PALLADINO: Is this an audible
15 indication or a light, the one that indicates that the
16 signal is going on?

17 MR. STAROSTECKI: The actuation logic that
18 comes out two out of four and logs in the control room,
19 is audible. That is your reactor trip alarm and that is
20 audible.

21 COMMISSIONER GILINSKY: Were there other
22 alarms on at that time or enunciators? I suppose we can
23 hear from the licensee.

24 CHAIRMAN PALLADINO: Well, if we are going to
25 hear from the licensee we ought to move on.

1 MR. EISENHUT: That was meant to help clarify
2 the previous question.

3 COMMISSIONER AHEARNE: If you are going to get
4 into the corrective actions, I wonder if you could make
5 one comment. In looking ahead and looking at what you
6 have labeled back-up slides and your statistics, it
7 seemed that you have had 21 Westinghouse scram breaker
8 failures since 1973, but I think what you just said is
9 that there are four here. Is that 4 out of 21?

10 MR. MATTSON: You are looking at this slide
11 way in the back.

12 COMMISSIONER AHEARNE: Yes.

13 MR. MATTSON: One of the things we would have
14 said if we had introduced this slide rather than you
15 reading ahead ---

16 (Laughter.)

17 MR. MATTSON: --- is the following. This
18 comes from LER data, and LER information, as you know,
19 requires some follow-up. This has not been followed up
20 yet. This is raw analysis of LER. This is something we
21 put together actually in advance of this event last
22 November for the ATWS rulemaking. People wanted to know
23 what does the recent LER data show.

24 We updated it yesterday and in the 21
25 Westinghouse events there are six counted for Salem, one

1 in August, one in January and four from the two doubles
2 in February. Now that may not be a fair count and I
3 recognize that.

4 COMMISSIONER AHEARNE: So it is six out of 21.

5 MR. MATTSON: Six of the 21 are Salem, that is
6 right.

7 COMMISSIONER AHEARNE: So I imagine one of the
8 things you are looking at is why Salem.

9 MR. MATTSON: I guess I should have said the
10 words I left out. Two times two, the doubling of that
11 count for February is very crucial, this point about
12 should it have been detected on the 22nd, and had it
13 been detected on the 22nd it wouldn't have been two
14 times two.

15 COMMISSIONER AHEARNE: Then it would only have
16 been what, four out of 19?

17 MR. MATTSON: Yes.

18 COMMISSIONER AHEARNE: Four out of 19 is still

19 ---

20 MR. MATTSON: I don't know, it is kind of
21 interrupting the flow, but of the 35 failures that you
22 are seeing on that page, those 35 failures have occurred
23 at ten plants, not 35 plants, and really at seven
24 sites. I count here one other sites with four failures,
25 Zion. Ccone Unit 1 had four failures and Ocone Unit 3

1 had three failures. So there are 7 for the Oconee units
2 alone.

3 COMMISSIONER AHEARNE: I am not sure whether
4 that means we shouldn't therefore look hard at Salem as
5 well as the others.

6 MR. MATTSON: It tends to point to maintenance
7 which we are attributing here as the cause as something
8 that could be systemic.

9 COMMISSIONER AHEARNE: Yes, and it might lead
10 one to look more closely at a few of those other plants
11 to understand what they aren't doing.

12 CHAIRMAN PALLADINO: Also, the nature of the
13 maintenance is very important.

14 MR. CASE: Indeed.

15 CHAIRMAN PALLADINO: I know in the Army we
16 never seemed to have trouble with our tank transporters
17 until we did preventive maintenance, and almost every
18 one of them gave us trouble after preventive maintenance
19 because they didn't do it right..

20 (Laughter.)

21 CHAIRMAN PALLADINO: Well, why don't you go on.

22 MR. LAINAS: I am going to go through the
23 corrective actions and I will try to go very quickly.

24 COMMISSIONER GILINSKY: I wonder if you could
25 go back over the event. I think as a practical matter,

1 we are not going to be able to have our other meeting
2 this morning.

3 CHAIRMAN PALLADINO: Well, I was hoping we
4 still could.

5 COMMISSIONER GILINSKY: Well, I think we have
6 a good bit to cover on this one.

7 COMMISSIONER AHEARNE: It looks like it.

8 COMMISSIONER GILINSKY: I just don't think we
9 are going to get to the other one and this seems to me
10 more urgent than the other one.

11 CHAIRMAN PALLADINO: Well, I think it is
12 important for us to understand it.

13 What is the Commission pleasure, to keep on
14 going on this?

15 COMMISSIONER ASSELSTINE: Yes.

16 COMMISSIONER AHEARNE: (Nodding affirmatively.)

17 COMMISSIONER ROBERTS: (Nodding affirmatively.)

18 CHAIRMAN PALLADINO: All right, let's keep on
19 going.

20 COMMISSIONER GILINSKY: I wonder if you could
21 just run through the events briefly on February 25, Rich.

22 MR. STAROSTECKI: The February 25th event is a
23 lot easier to explain.

24 If I could have the slide for the sequence of
25 events for February 25.

1 On February 25th, again the feedwater control
2 system is in manual control during a power ascension of
3 Unit 1. They encounter problems with the feedwater
4 control. The protection system senses a low-low water
5 level in No. 12 steam generator. The reactor trip
6 signal is generated by the reactor protection system,
7 what we refer to as SSPS, the solid state protection
8 system, and is indicated in the control room. So the
9 control room has gotten an alarm saying reactor trip.
10 An enunciator goes off and the status board indicates a
11 low-low bistable trip and that is all.

12 Plant parameters are not consistent with the
13 scram. The other enunciators normally associated with a
14 scram do not come in. The rod bottom lights do not come
15 on. The nuclear instrumentation does not decrease. You
16 do not get a negative start-up rate trip alarm. You
17 don't see the indications in the secondary plant as to a
18 reactor scram, specifically the turbine doesn't trip and
19 you are still tied to the grid.

20 In about 25 to 30 seconds the operators in the
21 control room scan their boards, satisfy themselves that
22 the situation they have involves a reactor scram with no
23 trip and they manually call for a scram with a scram
24 switch.

25 COMMISSIONER GILINSKY: Now why do you say

1 approximately. Is there no record of that?

2 MR. STAROSTECKI: No. It is simply
3 simplifying for the viewgraph it is approximate. When
4 you go to the computer printout we will count the number
5 of cycles, divide by 60 and we will know exactly how
6 much.

7 COMMISSIONER GILINSKY: Okay.

8 MR. STAROSTECKI: But it is an approximate
9 time order. It is something less than 30 second.

10 COMMISSIONER AHEARNE: I realize it is very
11 preliminary and perhaps that is the right answer, but it
12 seems somewhat anomalous that in the first case on the
13 22nd you have a situation where the operator reactor so
14 quickly that it was hard to tell whether the operator
15 beat the automatic scram or not. In this particular
16 case, the automatic scram goes on and 30 seconds go by
17 before the operator scrams. Would you say that 30
18 seconds is about the time you would expect the operator
19 to take?

20 MR. STAROSTECKI: I think that is something we
21 are going to have to study a little bit more, but I
22 would also caution you that the feedwater control system
23 is a complicated operation in manual. The shift
24 supervisors and the individuals involved, I think you
25 have to look at their training and their backgrounds as

1 to the decisions they made.

2 On the 22nd I believe that the shift
3 supervisor gave the order to trip the plant manually.
4 On the 25th he apparently did not and they were scanning
5 the boards to satisfy themselves.

6 I would say in very preliminary sense it is
7 judgment as to the rate at which, or the speed with
8 which the steam generator level drops. If in this case
9 they thought they were going to catch it and were trying
10 to catch it and didn't, then they would have to satisfy
11 themselves of what did we do wrong, what else is going
12 on.

13 COMMISSIONER AHEARNE: I guess what I am
14 asking is that in the first case you were talking about
15 the operator trying to judge whether or not they were
16 going to catch the steam generator and concluding that
17 they probably couldn't and so they manually tripped it.
18 There it was a judgment not that the plant had
19 automatically called for a scram, but it was a judgment
20 that it probably made sense to scram it.

21 In this case the automatic system had called
22 for a scram, and you are saying that rather than
23 scrambling the plant they were then, it sounds like,
24 trying to consider whether or not it had scrambled or
25 whether or not they should manually scram it.

1 MR. STAROSTECKI: Well, let me say there are a
2 couple of things to clarify. On the 22nd there were
3 other complications, specifically those associated with
4 the transfer of electrical buses. When you look at
5 other factors like that and looking at the judgment of
6 the operator with respect to the rate at which his level
7 is dropping, I distinguish between that and the 25th.
8 It was not as hectic and they did not have the
9 electrical problems.

10 CHAIRMAN PALLADINO: On the 25th that is why
11 they did the waiting.

12 MR. STAROSTECKI: That is a gray area in the
13 fact that it is not a standard practice to manually
14 scram the plant every time the protection system calls
15 for a scram. On the 25th the operators consciously
16 scanned the boards to understand the situation they were
17 deal with and then initiated their procedure and the
18 first thing that was called for was a manual scram. I
19 think we are going to have to get some people get some
20 insight as to is 30 seconds a reasonable time. The
21 licensee has indicated his preliminary findings that he
22 finds that very reasonable.

23 COMMISSIONER GILINSKY: Let me ask you again
24 about the February 22nd event. Let's accept the
25 operators' thoughts that they may have themselves

1 scrambled the reactor. Was there any doubt about this?
2 In other words, were there any suspicions that it might
3 have been otherwise, because it would seem to me that
4 even if you thought you had scrambled it but thought
5 perhaps not that is something that you would really want
6 to look at very hard.

7 MR. CASE: You mean at Salem?

8 COMMISSIONER GILINSKY: Yes.

9 MR. EISENHUT: I don't think we know of any
10 suspicions, but I think one of the things we will be
11 addressing, if we get to the second part, generic
12 aspects, one of the things we are doing is, and Bill
13 Dircks signed a memo out yesterday and the Region will
14 be doing an evaluation of the facts surrounding the
15 situation by March the 9th, but one of the things we are
16 certainly asking for is any information and data
17 relating to what the operators were doing, what the
18 operators' evaluations were, operator response times and
19 information that was available to the operator during
20 the event. Those are really inputs. That is factual
21 information of what occurred at the site.

22 I just think it is premature at this point,
23 but we don't have any, certainly I have never heard of
24 any information. In fact, every indication I had and
25 ever heard is that up until Saturday when people were

1 actually at the plant looking at the details, everyone
2 believed that the plant had essentially simultaneously
3 and was manually scrambled.

4 COMMISSIONER GILINSKY: Before you get into
5 corrective actions, you said earlier something about the
6 plant not receiving the Westinghouse bulletin on
7 maintenance and you were going to go into that. I don't
8 see that in any of the following slides.

9 CHAIRMAN PALLADINO: The fact that Salem
10 didn't get the, what was it, the 1974 memo?

11 MR. CASE: There has been action taken to make
12 sure that they have it.

13 COMMISSIONER GILINSKY: Can you just tell us
14 what the problem was before we get into the solution.

15 MR. CASE: The problem is that they didn't
16 have it.

17 CHAIRMAN PALLADINO: Are you going to start on
18 the corrective actions?

19 MR. EISENHUT: Yes.

20 CHAIRMAN PALLADINO: I wonder if I could just
21 interrupt for housekeeping purposes. I propose we take
22 a break soon, in fact in about one minute.

23 (Laughter.)

24 CHAIRMAN PALLADINO: Also, could I get an idea
25 of what more you have for presentation. You are going

1 to through the corrective actions. Are you going
2 through the backup slides?

3 MR. EISENHUT: We figure the corrective
4 actions we could probably be through with in 10
5 minutes. Then we would turn to the generic aspects and
6 we would turn to I&E to summarize what the bulletin is
7 and what are the preliminary results that we have been
8 getting in. Ed Jordan is here.

9 Ed, how long do you think?

10 MR. JORDAN: Five minutes.

11 CHAIRMAN PALLADINO: I want to make sure we
12 have some time for the licensee.

13 MR. EISENHUT: Then we could summarize the
14 generic direction we are heading and what we have set up
15 and the mechanisms we have got in very sort order. So
16 we could probably be done certainly in a half an hour.

17 COMMISSIONER GILINSKY: I guess I would also
18 like to hear what sort of restrictions the plant is
19 under right now and will continue to be.

20 CHAIRMAN PALLADINO: The status of it.

21 COMMISSIONER GILINSKY: Yes.

22 CHAIRMAN PALLADINO: Well, I am going to
23 suggest we take a seven or eight minute break and then
24 come back.

25 (Whereupon, a recess was taken from 11:05

1 a.m., to 11:20.)

2 CHAIRMAN PALLADINO: Well, I wonder if we
3 could resume the discussion, and I gather you had raised
4 a question on receipt of the '74 memo.

5 MR. LAINAS: I will try to. The NSD 74-02
6 were the directions that went out that were supposed to
7 be applied to the breakers. They recommended some
8 maintenance procedures, lubrication procedures and
9 period preventive maintenance type of procedures. That
10 is the second item, 74-02, NSD 74-02.

11 I might point out that the slide I have there
12 up on the screen for corrective actions was based on the
13 meeting that we had last Monday with the licensee. This
14 has since been supplemented by a letter dated March 1st,
15 which has been made available to the Commission.

16 CHAIRMAN PALLADINO: Is it attached hereto?

17 MR. LAINAS: It was a separate attachment and
18 there are additional copies in the back if they haven't
19 been passed out.

20 Trying to paraphrase some of the things that
21 the licensee is recommending, the first item of course
22 is to verify that the surveillance testing meets the
23 current tech spec requirements.

24 The second, that the maintenance procedures ---

25 COMMISSIONER GILINSKY: Let's see, was that

1 all you were going to say about that '74 memo?

2 MR. LAINAS: About the 74-02?

3 MR. CASE: There is not much more we can say.
4 The fact is the licensee said it was never sent and he
5 does not have the procedures.

6 COMMISSIONER AHEARNE: You mean the licensee
7 said it was never received. That does not say it was
8 never sent.

9 MR. LAINAS: Right, it was never received.

10 COMMISSIONER GILINSKY: Did Westinghouse ever
11 send it, or we don't know?

12 MR. CASE: We don't know.

13 MR. LAINAS: As you will see later on,
14 Westinghouse is developing an interagency task force to
15 make sure that all licensees are updated on the current
16 maintenance procedures.

17 COMMISSIONER GILINSKY: And there is just
18 nothing that brings something like this to the surface
19 over a period of ten years that a maintenance bulletin
20 on a fairly important piece of equipment just hasn't
21 been received?

22 MR. EISENHUT: Well, I guess to put it in
23 perspective, there was a 1971 technical manual relating
24 to the equipment, and then there was a January 1974
25 technical bulletin or a technical letter ---

1 MR. LAINAS: Technical bulletin.

2 MR. EISENHUT: --- technical bulletin from
3 Westinghouse. Then there was a February 1974 bulletin
4 which clarified or modified the January '74 bulletin.
5 So there were those three basic documents. It is my
6 understanding that the 1974 02 latest guidance just
7 physically wasn't received and it relates to the
8 maintenance and lubrication of the device.

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

1 MR. CASE: I feel part of the underlying
2 problem is likely a lapse of implementation of quality
3 assurance requirements that should be applied to the
4 safety related piece of equipment.

5 COMMISSIONER AHEARNE: I recognize that it is
6 nine years ago that the bulletin was issued. At that
7 time was there a recognition this was safety related or
8 safety grade, whatever terminology was used at that time?

9 MR. CASE: My understanding is that the FSAR
10 so states.

11 COMMISSIONER GILINSKY: How could it not be?
12 It is a good question still.

13 MR. EISENHUT: You will see when we get to the
14 issues that the first item on our issue list we need to
15 resolve is the safety classification of the breaker on
16 this plant.

17 COMMISSIONER AHEARNE: I am looking not so
18 much at Salem, but I am looking at Westinghouse. This
19 item that Westinghouse says is a verbatim transcription
20 of the Westinghouse letter talks about saying that a
21 technical bulletin issued in January of '74 described a
22 reactor trip breaker malfunction at the Robinson station
23 and then it goes on to talk about various maintenance
24 procedures.

25 What I guess I am asking is did Westinghouse

1 have a system which said here is something that is a
2 safety grade item and so this went out in a distribution
3 with some kind of priority attached to it or at least
4 separate handling or was it just one of many thing sent
5 out by a large commercial division?

6 MR. EISENHUT: I don't think we know today and
7 that is one of the items that we are exploring
8 generically, too, as a result of the bulletin which we
9 will go to in a moment.

10 COMMISSIONER GILINSKY: When did the plant
11 start operating?

12 MR. EISENHUT: I thought the about the time
13 frame of '74.

14 MR. STAROSTECKI: Unit 2 was in commercial
15 operation about a year and a half ago. Unit 1 was in
16 '76.

17 MR. EISENHUT: I was told '76 was the year for
18 Unit 1.

19 COMMISSIONER AHEARNE: So actually this would
20 have come out before that plant went into operation.

21 MR. STAROSTECKI: Yes.

22 CHAIRMAN PALLADINO: I do think it is an issue
23 that ought to be examined and gone into in detail. I
24 gather you are finding that.

25 MR. LAINAS: It might be worthy to note that

1 when the breakers or the undervoltage coil was worked on
2 last January that there was a Westinghouse
3 representative on site at that time that supervised that
4 kind of work.

5 MR. CASE: That was a representative of
6 Westinghouse Commercial as distinguished from
7 Westinghouse Nuclear.

8 CHAIRMAN PALLADINO: Do I understand that
9 there is a contract for maintenance of this equipment
10 with Westinghouse Commercial?

11 MR. CASE: I don't know whether there is a
12 contract.

13 MR. STAROSTECKI: Salem procured the services
14 of Westinghouse to send a representative to give them
15 guidance and direction in the overhaul of the breakers.
16 As a result of the August 20th event, they called in
17 Westinghouse for assistance. The work itself was done
18 by Public Service at the supervision of the Westinghouse
19 representative.

20 COMMISSIONER GILINSKY: Did Westinghouse not
21 check the procedures?

22 MR. CASE: Apparently not. This was a
23 Westinghouse Commercial representative and not
24 Westinghouse Nuclear.

25 COMMISSIONER AHEARNE: Why did Salem contract

1 not with Westinghouse Nuclear?

2 MR. CASE: I can only guess. They were
3 implementing a non-safety grade.

4 COMMISSIONER AHEARNE: That is what it sounded
5 like.

6 MR. EISENHUT: In fact, on Monday it was
7 stated by Public Service that these devices, the relays
8 here, are commercial off-the-shelf items, that they
9 acquire them as commercial off the shelf and then they
10 look at them and decide what is needed to have to give
11 them the proper pedigree.

12 Recently, starting with about the January
13 occurrence, they are now getting certificates of
14 conformance, or sometime in the very recent past.

15 MR. CASE: It was after this incident that
16 they have written procedures.

17 MR. EISENHUT: But it was clearly stated that
18 it was considered a commercial off-the-shelf component.

19 COMMISSIONER AHEARNE: From I&E's view is
20 there anything inconsistent with safety grade and
21 commercial off-the-shelf items?

22 MR. EISENHUT: Yes. Not necessarily if it is
23 commercial off the shelf by itself, but if it comes as
24 commercial pieces of equipment certain features would be
25 required before it could be used in any safety related

1 application. So then you look and see whether those
2 steps were done and we believe they were not.

3 COMMISSIONER AHEARNE: Do you know whether the
4 Westinghouse Commercial people were familiar with this
5 Westinghouse Nuclear Service Division report?

6 MR. EISENHUT: I have no way of knowing that
7 today.

8 MR. JORDAN: They advised us during the
9 meeting that they did not use the 1974 chart.

10 CHAIRMAN PALLADINO: They did not?

11 MR. JORDAN: They did not, yes.

12 MR. CASE: The person at the site was not
13 necessarily Westinghouse Commercial.

14 CHAIRMAN PALLADINO: But he did not use the
15 guidance provided in '74?

16 MR. EISENHUT: That one individual at the site.

17 CHAIRMAN PALLADINO: He was the one that was
18 sent.

19 MR. EISENHUT: That is correct.

20 CHAIRMAN PALLADINO: So presumably he knew
21 what the right thing was that should be done. What did
22 he use if he didn't use this 74 bulletin?

23 MR. STAROSTECKI: We don't know what they in
24 fact used. We can only go by the evidence. For
25 example, the kind of solvent and lubricant they used is

1 not the kind called for in the '74 bulletin. Based on
2 that you would have to say he was not knowledgeable of
3 the '74 bulletin.

4 CHAIRMAN PALLADINO: Is this one of the issues
5 under consideration?

6 MR. STAROSTECKI: Yes.

7 COMMISSIONER GILINSKY: Didn't somebody
8 somewhere along the way say that my God this is part of
9 the reactor protection system and this has got to be
10 safety grade? That is what surprises me.

11 MR. STAROSTECKI: That is one of the issues we
12 have in the utility as to how that information is
13 captured in their system, and I think when we get to the
14 issues page that is where we have some leg work in front
15 of us in terms of finding out how it got to this
16 situation.

17 CHAIRMAN PALLADINO: Let me suggest that we go
18 through the corrective actions and the issues. If there
19 is more you can pick it up later, because we won't even
20 get through these by noon.

21 MR. EISENHUT: Well, the important distinction
22 on this that we need to make is these corrective actions
23 are the corrective actions as proposed by the licensee.
24 So we don't leave the wrong impression, the staff has a
25 number of issues and a number of questions before us,

1 and those are these plus the issues page.

2 CHAIRMAN PALLADINO: Do you want to go to the
3 issues then?

4 MR. EISENHUT: I think we can go through these
5 briefly.

6 MR. LAINAS: I will go through very quickly.

7 Three is they are going to install new
8 undervoltage attachments and it will be under
9 Westinghouse guidance using the latest procedures and I
10 believe it is the Nuclear Services Division that is
11 doing it.

12 As far as four is concerned, the question of
13 verification, is what they are putting in now adequate,
14 and that program is being developed by the licensee.

15 MR. CASE: The testing program.

16 MR. LAINAS: Whatever it is, including maybe a
17 statistical analysis of some sort.

18 The fifth item, Westinghouse will make sure
19 that the original safety classification requirements are
20 met for that component.

21 Six is important in that the licensee has
22 recommended increased surveillance on the testing of the
23 undervoltage relay. As I mentioned earlier, currently
24 it is every two months and how it will be every month.

25 Seven is a procedural type of change which

1 will require the operator to actuate the manual trip at
2 any time he gets an indication of an automatic trip,
3 which is exactly the situation that occurred in the past
4 four events.

5 COMMISSIONER ROBERTS: When is what they did.

6 MR. CASE: Which is what they did, but this
7 will be an automatic procedure, as I understand and I
8 haven't seen the procedure, rather than using other
9 instrumentation. Once he gets an indication of
10 automatic trip to confirm it by hitting the scram button.

11 CHAIRMAN PALLADINO: Does that imply
12 immediately?

13 MR. CASE: Yes.

14 MR. LAINAS: The eighth item is to develop a
15 formalized post-trip procedure. Considering the length
16 of time it took to identify the February 22nd problem,
17 he is going to institute a procedure.

18 COMMISSIONER GILINSKY: Is there no procedure
19 now?

20 MR. STAROSTECKI: It is not a formalized
21 procedure.

22 COMMISSIONER GILINSKY: The tech specs don't
23 require any specific items to be looked at? Are they
24 required to look at the events sequence?

25 MR. STAROSTECKI: Right now there is no formal

1 requirement.

2 COMMISSIONER GILINSKY: Did they look at the
3 events sequence after the February 22nd event?

4 MR. STAROSTECKI: Based on the information I
5 have, they looked at the computer printout.

6 MR. EISENHUT: I think the matter of degree
7 and the depth of the review ---

8 COMMISSIONER GILINSKY: Well, let's see, if
9 they looked at the events sequence, why did they not
10 pick up the fact that it was the manual scram that
11 scrambled the reactor?

12 MR. STAROSTECKI: One would have to be aware
13 of the time interval necessary between the initiation
14 of the trip signal and the breaker opening to recognize
15 that.

16 COMMISSIONER GILINSKY: Wait a minute. They
17 looked at the number of cycles and so on.

18 MR. STAROSTECKI: Well, we are still looking
19 at that, but it is obvious that they were not aware of
20 the number of cycles that should have tripped it. Their
21 evaluation was based on the fact that it was protection
22 system logic that initiated the trip first and they did
23 not count cycles and they did not make the evaluation as
24 to when the reactor tripped with respect to the receipt
25 of a trip signal.

1 MR. EISENHUT: That is what we were told. I
2 think in summary that any post-trip review that was done
3 was inadequate because it didn't pick it up. That is
4 where we are.

5 COMMISSIONER GILINSKY: I guess what I am not
6 clear on is whether they did not want to take the cycles
7 that it took to go from one point to the next in the
8 sequence.

9 CHAIRMAN PALLADINO: One thing I don't think
10 we should try to do is speculate on what happened. I
11 think the staff is in the process of trying to develop
12 the information and I think we have pressed this point
13 as far as we should.

14 COMMISSIONER ROBERTS: But I don't think it is
15 a fair characterization to say that it was inadequate as
16 of February 25th.

17 MR. EISENHUT: As of Monday, the utility
18 stated in a meeting that the review process they had for
19 post-trip review was not adequate to pick up the problem
20 and they were "developing a formalized post-trip review
21 procedure." I am just trying to characterize that this
22 is as they proposed in a meeting.

23 COMMISSIONER GILINSKY: Let me just
24 understand. When they did their post-trip review, were
25 they aware that there were several seconds between ---

1 MR. EISENHUT: The details of that we certainly
2 don't know until we go back and do a detailed
3 evaluation, unless, Rich, you may know now.

4 MR. STAROSTECKI: We are in the process of
5 interviewing the people who were involved.

6 CHAIRMAN PALLADINO: All right. Why don't we
7 go on then.

8 MR. LAINAS: All those items are committed to
9 be done by the licensee prior to start-up.

10 COMMISSIONER ROBERTS: Are these different in
11 any way from the March 1st letter?

12 MR. LAINAS: There was one additional item on
13 the March 1st letter which talked about test after
14 maintenance procedures to make sure that when equipment
15 is maintained that it is tested.

16 There was also in the March 1st letter that a
17 traceability program for the breakers will be done, and
18 they said that would be done by April 1st.

19 So those were two differences from what we had
20 on Monday.

21 Nineth is that Public Service will get a
22 compilation of all technical bulletins and manuals
23 pertaining to Westinghouse equipment at Salem.

24 Tenth is really a Westinghouse item. They are
25 conducting an internal review of their procedures for

1 dissemination of technical information to utilities.

2 Eleven is a review is in progress at Salem for
3 past equipment failures as documented in LER's and
4 deficiency reports. Their letter indicated that that
5 would be completed by January 1st, '84.

6 Going on to the issues, I guess the first ---

7 COMMISSIONER GILINSKY: These are the issues
8 as you see them?

9 MR. LAINAS: The issues as we see them, not
10 indicating that they are resolved or anything, but the
11 issues as we see them.

12 MR. CASE: The licensee's proposals go to some
13 of them to a degree. The question is should it be more
14 or should there be suggested changes and things like
15 that, and that is what they are in the process of doing.

16 MR. LAINAS: The first is the safety
17 classification of the breakers that we had a number of
18 discussions here on, the pedigree and degree and how the
19 licensee treated the breakers. So that is obviously an
20 issue at this stage of the game.

21 CHAIRMAN PALLADINO: I want to ask you one
22 question.

23 MR. LAINAS: Sure.

24 CHAIRMAN PALLADINO: You are identifying these
25 issues. I presume you will tell us as you go what is

1 being done about them or are you developing a plan to do
2 something about each one of them?

3 MR. CASE: These are issues that we are going
4 to look into.

5 MR. LAINAS: The second one is the
6 identification of the cause of the failure. The
7 licensee attributes the cause of the failure to be a
8 lack of lubrication and maintenance on the breakers at
9 specified intervals and previous Westinghouse experience
10 he quotes as indicating that the reason for the failure
11 was indeed the maintenance procedures that were
12 followed. Of course, this has to be agreed to that
13 indeed this is the cause.

14 The third item is verification testing. The
15 licensee proposes to come up with a program to say yes,
16 indeed, they fixed the problem, whatever it is. I might
17 add at this time that we also have under consideration
18 to do some independent type of testing of these breakers.

19 MR. CASE: To determine the cause of failure.

20 MR. LAINAS: To determine the cause and
21 whether they are fixed or not.

22 The next item is revised surveillance and
23 maintenance procedures. As far as surveillance is
24 concerned, is indeed the increased frequency of testing
25 the undervoltage adequate, and checking their

1 maintenance procedures to ensure that they are not
2 falling into the same trap that they fell before of not
3 updating their maintenance.

4 The next is operating procedures. The first
5 is the adequacy of the automatic/manual scram procedure
6 that the licensee is proposing to do, whether his
7 emergency procedures that he used for following the
8 event indeed were the ones to be followed and that he
9 did do it correctly.

10 As far as operator response is concerned, it
11 was indicated that it took about 25 seconds for the
12 operator to react to the February 25th event, and was
13 this indeed adequate and is that the kind of thing that
14 should be expected.

15 MR. CASE: And were the operators' actions on
16 February 22nd adequate or not.

17 MR. LAINAS: I might also add another thing
18 that we are looking at here is if there were more
19 operators in the control room at that time than there
20 would normally be. So the question is what is the
21 interface between those and did they have better
22 coverage at that time. So that is another one to be
23 looked at.

24 I listed a bunch of them under management
25 issues, specifically the procedures for the post-trip

1 reviews ---

2 COMMISSIONER GILINSKY: Let me ask you, are
3 there not uniform post-trip review procedures throughout
4 the industry? Do we not have uniform requirements?

5 MR. CASE: I don't know of any requirements
6 that we have. I may be wrong on that.

7 CHAIRMAN PALLADINO: By post-trip reviews, are
8 you talking about any time you have a trip you are going
9 to have a post-trip review?

10 COMMISSIONER GILINSKY: Aren't you required to
11 identify the cause of it?

12 MR. EISENHUT: They are required to first
13 submit the LER with the information. They are also
14 required to have a procedure, a special procedure for
15 feedback of operating experience, I think it is called.

16 MR. CASE: What we are talking about here is
17 review of what caused the previous scram and make sure
18 you understand that before you go.

19 COMMISSIONER GILINSKY: Is it different for
20 each reactor?

21 MR. CASE: I think it is. There is a general
22 requirement to do such a procedure, but the details I am
23 almost positive vary from plant to plant.

24 MR. EISENHUT: Oh, I am sure the details do.

25 CHAIRMAN PALLADINO: Are these procedures that

1 we call for and the licensee develops?

2 MR. CASE: Yes.

3 CHAIRMAN PALLADINO: So they would probably be
4 different.

5 COMMISSIONER GILINSKY: Well, the specific
6 details perhaps, but aren't there basic things that we
7 require just as we do on an LER in general?

8 CHAIRMAN PALLADINO: There are procedures for
9 getting there, but making the review presumably would be
10 different.

11 MR. CASE: For instance, do we always require
12 that the computer be looked at, and I don't believe we
13 do. We look at what the licensee's procedures are and
14 determine whether through I&E's and the Region's sample
15 inspection is it adequate, but they don't look at all
16 their procedures.

17 COMMISSIONER GILINSKY: Do they have any
18 procedures for proposed trip reviews?

19 MR. STAROSTECKI: I don't know. The
20 information I had is that they have a chain of people to
21 review the decision to start a unit after a trip. I do
22 not know what, if any kind, of procedure they have for
23 making that happen.

24 CHAIRMAN PALLADINO: On the review of these
25 issues, is there some timetable by which you hope to

1 look at all of these?

2 MR. CASE: We would look at all of them and
3 decide if it is an acceptable program before start-up.
4 Now some of the implementation may extend beyond
5 start-up.

6 CHAIRMAN PALLADINO: No, I meant when might we
7 get some feedback on some of these are what you are
8 planning to do on these?

9 MR. CASE: We will be reviewing them in the
10 next few days.

11 COMMISSIONER GILINSKY: I guess I hope you
12 will inform the Commission before letting the plant go
13 back up about how these things have been resolved. I
14 would certainly like to hear about it.

15 CHAIRMAN PALLADINO: You want information.
16 Are you suggesting that there be Commission approval?

17 COMMISSIONER GILINSKY: Well, I am not
18 suggesting Commission approval, but I certainly, as in
19 other cases, would like to be informed on a time scale
20 consistent with reacting to what we hear.

21 CHAIRMAN PALLADINO: Well, that relates to my
22 question of when might we get some feedback on these
23 items.

24 MR. EISENHUT: I think the best indication is
25 as Mr. Case said, in the next few days.

1 CHAIRMAN PALLADINO: All right. Why don't you
2 let us know after you have got a better feel for the
3 answer.

4 COMMISSIONER GILINSKY: Would you not want to
5 hear that, Joe?

6 CHAIRMAN PALLADINO: No, I do. I would like
7 to hear it. That is why I was asking when we were going
8 to hear about this, but I didn't want to imply ---

9 MR. CASE: He wants a better schedule of when
10 we would be ready.

11 CHAIRMAN PALLADINO: I personally did not want
12 to imply that they have to come back to us for approval,
13 but I would like to have information on this before they
14 start up. I don't know how the others feel. I would
15 like to at least get an indication of what is going on
16 on this items because I don't think we will have them
17 all settled.

18 MR. STAROSTECKI: I would just like to add
19 that on some of these items, like the mangement issues,
20 we need to sit down and tell the licensee what we
21 specifically are going to require. The schedules are
22 somewhat going to be dictated by how soon the licensee
23 can respond.

24 We obviously have a concern when we look at
25 all these events that there have been a number of

1 mistakes made by various people at various levels with
2 respect to QA. So there is a concern as to how that
3 organization treated this piece of equipment this way
4 and what needs to be done to prevent that from happening
5 again. That is a broad subject of management issue, the
6 timing of it.

7 CHAIRMAN PALLADINO: I don't expect that you
8 will have told us everything that is going to take
9 place, but at least plan you have on the items where you
10 have not reached a resolution.

11 COMMISSIONER GILINSKY: I think we ought to
12 get a full briefing before this plant goes back into
13 operation. There are some very serious things that have
14 happened here and I think the Commission ought to be
15 clear on how these problems have been resolved to the
16 satisfaction of the staff before this plant goes back
17 into operation. I can't imagine us not doing that.

18 CHAIRMAN PALLADINO: I am also concerned about
19 the generic implications of this whole incident.

20 COMMISSIONER GILINSKY: Well, that is another
21 matter we will want to hearing about.

22 COMMISSIONER AHEARNE: In your list of issues
23 you have perhaps embedded in here somewhere where I
24 can't quite see it a question of safety classification
25 of equipment.

1 MR. LAINAS: In general.

2 COMMISSIONER AHEARNE: Yes, at Salem, in the
3 sense that it appears that if there is a question did
4 they lable this correctly, then doesn't that also then
5 bring into the question have they mislabeled other things?

6 MR. STAROSTECKI: That is the intent for
7 putting quality assurance under mangement issues. That
8 is going to require looking at all equipment.

9 COMMISSIONER AHEARNE: I would have I guess
10 not necessarily put under quality assurance the question
11 of the classification, but if that is where it is.

12 MR. STAROSTECKI: Looking at classification is
13 one step, because it is obviously affected by things you
14 have to do in accordance with quality assurance.

15 COMMISSIONER AHEARNE: Yes, but I would have
16 felt that quality assurance, having classified it
17 correctly now and then putting in the procedures to
18 correctly maintain safety grade equipment, then quality
19 assurance is the program to make sure that you have got
20 maintenance done correctly. As long as somewhere you
21 are going to be looking at whether or not there are
22 other pieces of equipment that they ---

23 MR. STAROSTECKI: Yes, are going to make sure
24 that the two are married.

25 COMMISSIONER GILINSKY: Let's see, are we

1 agreed that we will informed about the resolution of
2 these problems before the plant goes back into operation?

3 CHAIRMAN PALLADINO: Well, others haven't
4 spoken. My feeling is we ought to have a report or a
5 briefing or perhaps both on where we stand on these
6 before we start up. I don't know how others feel.

7 COMMISSIONER ASSELSTINE: I would agree with
8 that.

9 CHAIRMAN PALLADINO: And what we do after that
10 will depend on what we get.

11 COMMISSIONER ROBERTS: I am not sure that at
12 this point you can say that all these issues are going
13 to be resolved with finality before it might be ---

14 CHAIRMAN PALLADINO: I said the status and I
15 did indicate earlier that not all of these will be
16 presumably done before restart.

17 COMMISSIONER GILINSKY: Well, you may not have
18 completed the various actions, but you have to have
19 reasonable confidence that the plant will be operated
20 properly and that is what I think we want to hear about.

21 COMMISSIONER AHEARNE: That is obvious.

22 COMMISSIONER ROBERTS: Nobody is going to
23 disagree with that.

24 CHAIRMAN PALLADINO: I sense we have agreement
25 that we will receive a briefing or a report or perhaps

1 both from the staff on the status and progress of the
2 items listed as issues prior to restart.

3 MR. CASE: There may be others added, too, and
4 I am sure you don't preclude those.

5 COMMISSIONER GILINSKY: Not at all.

6 CHAIRMAN PALLADINO: Okay, do you want to
7 continue.

8 MR. EISENHUT: That basically concluded where
9 we were on Salem specifically. We have a summary of two
10 other aspects of where we are generically. I&E, Mr. Ed
11 Jordan is going to be summarizing what we issued in the
12 form of a bulletin last Friday and the preliminary
13 results. Following that we will have some generic
14 implications of where we are going in a broader scheme.

15 Ed.

16 MR. JORDAN: Could I have the bulletin slide.

17 There was a decision on the morning of
18 February 25th by I&E and NRR management that a bulletin
19 was warranted on this issue. We did ascertain there had
20 been an earlier bulletin in 1971 which was I think
21 probably the second bulletin issued on the same issue.
22 We had established that there was a Westinghouse
23 technical bulletin. This is the NSD 74-02 that had been
24 issued on this same matter.

25 In communicating the generic problem we tried

1 to communicate it as widely as possible. So we did
2 advise INPO of the problem and INPO put it out on their
3 note pad Friday morning.

4 We also advised the Regional Administrators ---

5 COMMISSIONER GILINSKY: Let's see, Friday
6 morning?

7 COMMISSIONER ROBERTS: Friday morning?

8 MR. JORDAN: Friday about noon we advised INPO
9 of the event and then they put it out on their note
10 pad. I don't know what time they got it out, but we
11 advised them Friday morning of the event.

12 COMMISSIONER GILINSKY: But not of the
13 bulletin.

14 MR. JORDAN: That is corect. So that they
15 were providing a generic notification that there is a
16 problem with this particular relay undervoltage trip
17 system.

18 We advised then the Regional Administrators
19 and asked them to contact the resident inspectors in
20 each of their regions advising them to further notify
21 the licensees and indicate that a generic action, a
22 bulletin was forthcoming. Subsequently we requested the
23 regions to survey the plants the ascertain which plants
24 had this particular Westinghouse bulletin with the
25 undervoltage trip attachment.

1 The bulletin was prepared and in the
2 preparation of it there was an attempt to be as sharply
3 focused as practical with the best information we had
4 available at the time so that there are actually three
5 actions.

6 The first action is to request the utilities
7 to test the undervoltage trip function and the time
8 frame within which the test was requested was 24 hours
9 if a test had not been performed within five days. This
10 is of the undervoltage trip attachment. The normal
11 surveillance we understood at that point was about 30
12 days for the family plants that we knew had these
13 breakers.

14 The second item was to review the maintenance
15 program and to assure that that particular plant had
16 conformed to the Westinghouse 1974 NSP or a suitable
17 alternate. It is worth stating that at this point we
18 couldn't establish with finality that the 1974 bulletin
19 from Westinghouse was their most current indication.

20 MR. CASE: That is as of last Friday.

21 MR. JORDAN: That is correct, as of ---

22 COMMISSIONER AHEARNE: How did you determine
23 that it was an appropriate bulletin?

24 MR. JORDAN: We had contacted Westinghouse in
25 fact the previous day on the same issue based on the

1 earlier failure at Salem and we had run to the point of
2 knowing that that was apparently the most current. We
3 were trying to verify that it definitely was the most
4 current.

5 COMMISSIONER AHEARNE: Let's see, you had
6 contacted Westinghouse Nuclear and asked them whether
7 they had maintenance procedures?

8 MR. JORDAN: We already had in hand the 1974
9 maintenance procedure and we were trying to establish if
10 that was indeed the most current maintenance procedure
11 and that it had not been superseded by something
12 subsequent.

13 COMMISSIONER AHEARNE: That was something that
14 you had had in your files in I&E?

15 MR. JORDAN: Yes.

16 COMMISSIONER AHEARNE: So your question to
17 Westinghouse Nuclear was whether or not they had
18 superseded that with another ---

19 MR. JORDAN: That is correct.

20 COMMISSIONER AHEARNE: And they were unable to
21 tell you?

22 MR. JORDAN: With finality they were unable to
23 tell us.

24 MR. CASE: They had to go back to the
25 Westinghouse Switchgear Division because what they do is

1 to get Switchgear's recommendations and more or less
2 endorse them and sent them out to the nuclear plants.

3 COMMISSIONER AHEARNE: And they had no filing
4 system of their own to tell what they had sent out on
5 that?

6 MR. CASE: Well, at least the people we were
7 talking to on Friday afternoon.

8 MR. JORDAN: So that is the reason for the
9 stated "or alternate maintenance procedure." Perhaps
10 there was a better one based on our knowledge at that
11 time of issuance.

12 The last one was to notify ---

13 COMMISSIONER AHEARNE: Let me ask this. What
14 you have told the licensees is to conform to this
15 particular maintenance procedure.

16 MR. JORDAN: Or an alternate, or an equivalent
17 alternate. So that we left the open door if there was a
18 procedure that the utility felt was better.

19 I should make it clear that these are
20 requested items. They are not ordered items.

21 MR. CASE: I should also make it clear that
22 Westinghouse has confirmed that this is the latest
23 bulletin.

24 MR. JORDAN: Yes, subsequently that has been
25 confirmed.

1 Then the last action was for the utilities to
2 each notify all of their licensed operators of this
3 particular event and to review with them when they came
4 on ship their own emergency procedures for a failure to
5 trip event.

6 We do require a report within seven days of
7 receipt of the bulletin. The bulletin was also sent to
8 boiling water reactors and reactors under construction
9 for information purposes and all of the PWRs for action.

10 Could I have the next slide, please.

11 CHAIRMAN PALLADINO: What was the rationale on
12 the 24 hours being the time limit for the test?

13 MR. JORDAN: We felt that there was an
14 immediate health and safety concern and that we wanted
15 verification that there was not in existence across this
16 family of plants an inability to trip in an automatic
17 mode with the undervoltage trip circuit. So that was a
18 time frame within which the utilities should be able to
19 perform their routine surveillance, and if they had not
20 done it within a relatively short time, which we
21 selected as five days ---

22 CHAIRMAN PALLADINO: That was what was giving
23 me a little problem. You said if you hadn't done it in
24 five days to it in the next 24 hours, the reason being
25 it was a weekend and I don't know how these utilities

1 work, but if they are somewhat like other organizations
2 they may have key people off and it takes time to plan
3 such an operation. If you are allowing five days since
4 the last test, it would have seemed that you could have
5 allowed between 48 and 72 hours to give them a chance to
6 schedule ---

7 MR. JORDAN: That was clearly a judgment call,
8 Mr. Chairman, and it was the staff's judgment that the
9 significance of this matter warranted that kind of
10 timely response.

11 MR. SNIEZEK: I would like to add something.
12 It was our understanding that the normal tech spec
13 surveillance was about 30 days on these breakers. Even
14 if Salem had been doing their surveillance, we found
15 their breakers failed. So we didn't want to allow, you
16 know, within the past 30 days. We we said if you
17 haven't done it within five days, a judgment call, do it
18 promptly within 24 hours. We didn't want to sit around
19 waiting.

20 These procedures, the normal surveillance
21 procedures, people are already trained in them. So it
22 is not a lack of preparation that you do have to go
23 through. It is a procedure that would be done
24 periodically as part of normal surveillance. We didn't
25 see it as having to develop new procedures, get

1 approvals or any of those types of processes.

2 CHAIRMAN PALLADINO: Well, it just seemed that
3 you might have had a little more time than 24 hours on
4 the weekend. Okay, you have given me your rationale.

5 COMMISSIONER GILINSKY: Well, in any case,
6 their collective view was that the matter was urgent and
7 they had the direct responsibility.

8 MR. JORDAN: The survey, and this is
9 preliminary ---

10 MR. CASE: Let me just add to that. It is
11 fair to say that the people who at least work for us
12 questioned the 24 hours. So we collectively reviewed it
13 and decided that we felt that was the correct period of
14 time. It wasn't just something that passed through
15 without consideration.

16 CHAIRMAN PALLADINO: I was interested in what
17 the thinking was.

18 MR. JORDAN: These are preliminary results of
19 the regional surveys by the inspectors that all of the
20 Westinghouse operating plants, except Farley, McGuire
21 and Summer do use the DB breaker with the undervoltage
22 trip attachment. Based on that survey, none of the B&W,
23 or EC plants use this type breaker with the undervoltage
24 trip provisions. We had a less formal survey of the GE
25 plants that were not addressed for action and there was

1 no identification of this type used in their circuit.
2 Their circuit is significantly different and the staff
3 was convinced in the reactor protective system in the
4 scram function that it was not applied.

5 As a last item on this slide, we are
6 considering other safety related applications of this
7 type breaker with the undervoltage trip attachment, and
8 that would be subject to other action. This would be
9 on, for instance, turbine trip of plants.

10 CHAIRMAN PALLADINO: Are you sending out
11 another bulletin to get that data?

12 MR. JORDAN: We have not anticipated which
13 other action we will take, but there certainly will be
14 subsequent actions based on what we have learned.

15 The next slide, please.

16 The test results from the bulletin. The
17 utilities have performed the testing as requested in the
18 meeting with the utilities and the Owners Group. On
19 Monday the Owners Group stated agreement with the
20 bulletin actions. They felt that those actions were
21 appropriate for the problem as it was understood.

22 COMMISSIONER AHEARNE: This Owners Group are
23 ownes of ---

24 MR. JORDAN: Westinghouse plants.

25 There were no failures found during the

1 testing period and there were not reactor trips that
2 occurred as a result of the testing. Those plants that
3 have not tested are shut down and they will do the
4 testing before they resume operations.

5 COMMISSIONER ROBERTS: And everybody met the
6 24 hours?

7 MR. JORDAN: Yes, sir.

8 That is all I have.

9 MR. EISENHUT: Going on to the generic
10 implication follow-up slide, there are several things we
11 are going to be addressing and the industry is
12 addressing on a broader perspective.

13 Gus, why don't you take that one.

14 MR. LAINAS: At the Monday meeting we had
15 representatives of Westinghouse there plus
16 representatives of the RRG, the Westinghouse Owners RRG.

17 MR. EISENHUT: Those are regulatory response
18 groups that the industry has set up that we can call if
19 we perceive there is a pending immediate safety concern
20 or a question and they activate their group to address
21 the issue.

22 MR. LAINAS: They each have since, both
23 Westinghouse and the RRG have sent in a letter
24 confirming what they told us last Monday.

25 Essentially item one is what Westinghouse

1 plans to do. Clearly there was a mix-up in the
2 distribution of technical documents and they are
3 establishing an intercompany task force of the various
4 divisions to correct this problem.

5 Secondly, they are going to develop an
6 evaluation and test program for the model DB-50
7 undervoltage coil.

8 Thirdly, they are developing procedures for
9 independent testing of the undervoltage and shunt coil.

10 CHAIRMAN PALLADINO: I don't know what you
11 mean by evaluation and testing program. Presumably they
12 have got a lot of tests. What are they going to do
13 different?

14 MR. LAINAS: I don't think we have the details
15 on exactly what they are planning to do.

16 MR. CASE: Re-evaluate the adequacy of the
17 design and the maintenance procedures.

18 MR. LAINAS: With respect to the last item as
19 far as independent testing of the undervoltage and shunt
20 coil, this testing capability is available at Salem but
21 not in all plants.

22 Secondly, with respect to the Owners Group and
23 RRG, they are getting a listing of all current
24 Westinghouse technical data letters and they will
25 distribute them to the various utilities.

1 They are evaluating the effectiveness of the
2 manual scram following an automatic scram. This is what
3 Salem is proposing to change their procedures to.

4 Review of the trip and ATWS emergency
5 guidelines procedures. As indicated in their last
6 letter, these guidelines have been reviewed and found to
7 be adequate.

8 The adequacy of the standard tech spec,
9 surveillance interval, test method and testing of the
10 shunt coil is being looked into. The schedule for that
11 as stated in their letter is June 30th.

12 And they plan to notify their members to
13 conduct a review for similar type failures in other
14 systems.

15 MR. EISENHUT: That sort of takes us up to
16 where we are today.

17 The last three items there are we are
18 presently in the process of setting up meetings with the
19 CE, B&W and GE regulatory response groups. We will
20 probably be having those meetings next week. It is a
21 little more relaxed schedule, but it is the same thing
22 of looking at and addressing the issues and seeing
23 whether they have any of the same problems.

24 CHAIRMAN PALLADINO: Darrell, with regard to
25 generic follow-up, are there any plans or do you see any

1 need to accelerate the rulemaking on ATWS?

2 MR. EISENHUT: Is I can hold that for one more
3 item. That is my last bullet.

4 The fourth item is Bill Dircks sent out a memo
5 dated February 28th, and a copy of his memo is attached
6 in the back of the package. There will be a detailed
7 event report developed by Region I by next Wednesday,
8 March the 9th, and that report will address not just the
9 system response, but will go into operator response, as
10 we mentioned earlier, and information available to
11 operators. It is a factual summary. It is comparable
12 somewhat to the Ginna evaluation report that was done,
13 albeit, although a shorter time frame.

14 The second item is NRR has been tasked with
15 setting up a task force to review and evaluate the
16 generic implications and to submit a report to the
17 Commission by April 18th. That task force is presently
18 being formed. It will be chaired by Roger Mattson and
19 it will have representatives of the various other
20 offices as well as the Region, AEOD, I&E, et cetera.

21 That group then would be the group that will
22 be responsible for recommending any other prompt
23 actions, such as another bulletin, a follow-up to the
24 bulletin or a clarification of the bulletin, whatever.
25 So it will be unfolding and aiming towards a report that

1 will be done to the Commission by April 18th. It is
2 fair to characterize it that it bridges the gap between
3 the immediate term where we issue the bulletin of last
4 Friday and the longer term which is the ATWS position.

5 The fifth item here on the page is factoring
6 the experience into our proposed ATWS position and ATWS
7 rule.

8 Dennie Ross is here and I am sure can answer
9 your questions.

10 COMMISSIONER GILINSKY: What does this do to
11 all the calculations?

12 MR. ROSS: It turns out we were about 95
13 percent complete with bringing back to the Commission a
14 proposed rule on ATWS. The schedule was mentioned in
15 SECY-82-275 last summer with the Commission. At that
16 time we thought that we could digest the public comments
17 on the three rules, the so-called Hendrie rule, the
18 staff rule and the utility rule.

19 We decided to contract with Energy,
20 Incorporated, to analyze some technical aspects of the
21 utility rule. We formed two groups that would look much
22 like the group that Darrell mentioned on the April 18th
23 report, a steering group and a task force.

24 A draft rule was prepared last fall and
25 discussed with CRGR. They had some questions on the

1 value impact. Written answers were prepared in
2 December. There was CRGR discussion again in January.
3 As of today we have a package which consists of a draft
4 Commission paper, a report by the steering group and a
5 draft proposed rule.

6 If Salem had not occurred, this would have
7 been, we believe, finalized in CRGR last this month,
8 there would have been ACRS discussions in April and
9 presumably an ACRS letter in May, a package to the
10 Commission in late May, Commission discussion in June
11 and presumably approval in June and then Federal
12 Register notice in July.

13 We were on that track and, as I said, the
14 document I believe and the supporting justifications are
15 in pretty good shape.

16 I now speculate that there will be a
17 six-weeks' slip. In the six weeks we will be allowed to
18 take into account the generic implications of this
19 six-weeks study that Roger is working on.

20 Now we may be able to recoup some of it
21 because the structure that Matton is working on ---

22 COMMISSIONER AHEARNE: Don't work too hard now.

23 (Laughter.)

24 MR. ROSS: Well, I think there is some
25 orthogonality between what the six weeks' study will do

1 and the rule. I think they are looking at different
2 things in the microstructure versus the macrostructure
3 of the rule. But, nonetheless, I think we do have to
4 wait until that review is complete.

5 That is where we are.

6 COMMISSIONER GILINSKY: What do these two
7 events do to the statistics?

8 MR. ROSS: We have taken a cursory look in
9 terms of what everyone likes to talk about these days,
10 uncertainties in PRA, and it does not affect it.
11 Obviously numerically it affects it, but we believe it
12 is less than a factor of two, and that is close enough
13 in terms of PRAs.

14 What has happened is when you revisit the
15 statistics since 1977, you also add in some more reactor
16 years. You also add in Browns Ferry. Then there is
17 controversy as to whether the Kahl failure every should
18 have been included in the first place.

19 Then you can start doing fine structure,
20 should it only be Westinghouse reactors north of the
21 Mason-Dixon Line.

22 (Laughter.)

23 MR. ROSS: Statisticians are not going to
24 agree, but within the uncertainty band no change. So I
25 don't think this places ATWS in a new or different light

1 in that respect.

2 COMMISSIONER GILINSKY: Let's see, can we give
3 the company a chance to comment?

4 MR. EISENHUT: That concluded the staff's
5 presentation, unless there is something else you want to
6 do.

7 CHAIRMAN PALLADINO: Do we have a
8 representative from the facility? I do think it would
9 be appropriate to give him an opportunity to make any
10 comments.

11 COMMISSIONER ROBERTS: I am going to have to
12 leave in a few minutes, and my leaving in way reflects a
13 lack of interest.

14 COMMISSIONER GILINSKY: This is just going to
15 take a few minutes.

16 MR. ECKERT: Thank you.

17 I appreciate the opportunity to at least make
18 a few comments on this whole situation.

19 CHAIRMAN PALLADINO: Do you want to provide
20 your name?

21 MR. ECKERT: My name is Dick Eckert. I am
22 Senior Vice President of Public Service Electric and Gas
23 Company. We have other members of our staff with us and
24 in case you have specific questions you would like to
25 have replied to, I can refer to them.

1 Obviously we took this situation we are in
2 very, very seriously and we have been looking at it in
3 great depth. We have submitted to the staff the letter
4 that you have in front of you that outlines the
5 corrective actions as we see them.

6 They have, as you know, come forth with a list
7 of issues and I would hope that in the immediate future
8 we can get together with the staff and resolve those
9 issues against what we have proposed because I think
10 many of them have been resolved but we need some time to
11 talk those things out.

12 As I see this problem, there really are three
13 major problems that we have to resolve.

14 The first is what is really the root cause of
15 what happened here, and the answer to that is the
16 maintenance problem on the UV relays. These were
17 purchased as safety grade equipment. They were
18 delivered with instruction books and the instruction
19 books indicated the maintenance that is required on the
20 equipment.

21 For reasons that we haven't yet been able to
22 find out, we never got any further information on how to
23 maintain this equipment, which means the 74-02 was never
24 received. We have no record of receiving it and they
25 have no record of sending it. We have got to get that

1 situation straightened out and in addition make sure
2 there aren't others which have been sent to some people
3 and not to others. You will see in our recommendations
4 that that is part of the program.

5 CHAIRMAN PALLADINO: You said when you bought
6 it you got it with the appropriate maintenance
7 instructions?

8 MR. ECKERT: Yes. They ship these things with
9 instruction books and it is safety grade equipment.

10 CHAIRMAN PALLADINO: Were the instructions in
11 the books followed?

12 MR. ECKERT: The instructions in the books
13 were followed, but they were very, very little in the
14 way of maintenance. Clean it, look at it, and make sure
15 there is nothing loose. That is all.

16 CHAIRMAN PALLADINO: No frequency?

17 MR. ECKERT: I think it was a six-month
18 interval, although I could check that for sure. I am
19 not personally sure of that.

20 The second problem as we see it is the fact
21 that we did have the failure to trip on the 22nd, and
22 this was not picked up until later. We recognize that
23 is a problem and we are formalizing our procedures to
24 make sure this is not a problem that is repeated.

25 You should bear in mind that at the time this

1 happened we had a manual scram within a couple of
2 seconds, we had a safety injection and we had a PORV
3 action. We had a busy place. You get many alarms and
4 you have busy operators.

5 Yes, we made a mistake. We did not pick it up
6 and we should have. But I can understand under the
7 circumstances why it was not picked up until a later
8 review.

9 The third item of concern in my mind at least
10 is this question of is the equipment safety grade. It
11 was purchased as safety grade equipment, it was stored
12 as safety grade, it was installed, it was operated and
13 it was maintained all as safety grade equipment.

14 The place the problem comes up is I believe in
15 January of this year there were two work orders issued
16 for overhaul of the equipment and they were mistakenly
17 identified as not safety grade. As far as we can tell i
18 checking our records, those are the only times that
19 happened. This was a man's mistake. It was wrong. A
20 man made a mistake.

21 We are putting into effect a check procedure
22 now on all work orders to make sure there is no work
23 order that goes through and is mistakenly identified as
24 non-safety grade when indeed it is safety grade.

25 To complicate the matter further, in the

1 meeting we had on Monday our Maintenance Manager talked
2 for quite a while and it became confusing as to whether
3 he considered it safety grade. Now this is a people
4 problem, if you will. We have a problem with that, but
5 it is very clear in everything we have done that this is
6 now and always was safety grade equipment. I just want
7 to make sure you understand that part, but we had a
8 problem with it, no question.

9 Those to me are the major things that we have
10 got to get straightened out on this.

11 I can make a couple of other comments, but I
12 think probably that is the thrust of our concerns.

13 CHAIRMAN PALLADINO: Okay, thank you.

14 Any questions?

15 COMMISSIONER GILINSKY: Was there anything we
16 heard today that was just factually wrong that is
17 important enough to correct?

18 MR. ECKERT: I don't think important enough to
19 correct. I would make a comment on operator action.
20 Twenty-four and a half seconds, as I understand it, is
21 the actual cycle count on that.

22 We talked to a number of people that were on
23 simulators and people that are familiar with operator
24 reaction time. They told us that they would consider a
25 minute too long but a half a minute very good. So we

1 don't really think that the operator waited too long to
2 do something. It was a reasonable reaction time on the
3 part of the operators. If that is still under review by
4 the NRC staff, fine, but that is the reaction that we
5 got and where we got it.

6 Other than that, I don't really know of
7 anything. Details you can get into, but basically the
8 facts were laid out very well I thought by the staff.

9 CHAIRMAN PALLADINO: Any other questions?

10 (No response.)

11 CHAIRMAN PALLADINO: Well, we thank you very
12 much, Mr. Eckert.

13 MR. ECKERT: Thank you.

14 CHAIRMAN PALLADINO: Are there any other items
15 that should come before us on this subject at this time?

16 (No response.)

17 CHAIRMAN PALLADINO: If not, then thank you
18 all and we will stand adjourned.

19 (Whereupon, at 12:10 p.m., the meeting
20 adjourned.)

21

* * *

22

23

24

25

NUCLEAR REGULATORY COMMISSION

This is to certify that the attached proceedings before the

COMMISSION MEETING

in the matter of: PUBLIC MEETING - Briefing on Salem

Date of Proceeding: March 2, 1983

Docket Number: _____

Place of Proceeding: Washington, D. C.

were held as herein appears, and that this is the original transcript thereof for the file of the Commission.

Mary C. Simons

Official Reporter (Typed)

Mary C Simons

Official Reporter (Signature)

D. G. EISENHUT, NRR
X27221

COMMISSION BRIEFING
SALEM EVENT
OF FEBRUARY 25, 1983

MARCH 2, 1983

SALEM EVENT
BRIEFING OUTLINE

SALEM EVENT

- o EVENT DESCRIPTION
- o ISSUES RELATING TO RESTART

GENERIC CONSIDERATIONS

- o NRC BULLETIN OF 02/25/83
- o GENERIC IMPLICATION FOLLOWUP

EVENT DESCRIPTION

EVENT DESCRIPTION

BACKGROUND

- o TRIP BREAKER
- o SOLID STATE PROTECTION SYSTEM (SSPS)
- o TRIP BREAKER HISTORY

EVENT #1 DESCRIPTION

FEBRUARY 22, 1983

EVENT #2 DESCRIPTION

FEBRUARY 25, 1983

TRIP BREAKER

- o ALLOWS POWER FROM MG SETS TO BE SUPPLIED TO CONTROL ROD DRIVE MOTORS (CRDM)
- o OPENING BREAKER ALLOWS MECHANICAL RELEASE OF ROD FROM CRDM ALLOWING SCRAM
- o TRIP BREAKER MECHANICALLY OPENED BY:
 - MANUAL BUTTON AT BREAKER
 - LATCH ON CABINET
 - SHUNT COIL
 - UV COIL

SOLID STATE PROTECTION SYSTEM (SSPS)

- o LOGIC AND STATUS INDICATOR IN CONTROL ROOM
- o AUTO SSPS TRIP SIGNAL -
DEENERGIZES (UV) COIL
- o ATWS INSTRUCTIONS
 1. MANUAL TRIP FROM CONTROL ROOM - DEENERGIZES
UV COIL AND ENERGIZES SHUNT COIL
 2. CONTROL ROOM BREAKER PUSHBUTTON - INDIVIDUAL
BREAKER CONTROLS FOR CLOSING AND OPENING (VIA
SHUNT COIL)
 3. INITIATE SAFETY INJECTION (INJECT BIT)
 4. LOCAL MECHANICAL PUSHBUTTON ON INDIVIDUAL BREAKERS
 5. LOCAL BREAKER TRIP OF ROD DRIVE MOTOR GENERATOR
INPUT OR OUTPUT BREAKERS

CONTROL ROOM INDICATION

- REACTOR TRIP -

POSITIVE

1. REACTOR TRIP BREAKER "OPEN"
 - SSPS DISPLAY
 - BREAKER CONTROL PUSHBUTTON
2. ROD POSITION INDICATORS
3. ROD BOTTOM LIGHTS
4. NUCLEAR INSTRUMENTATION
5. PLANT COMPUTER

CONTROL ROOM INDICATOR

- REACTOR TRIP -

FEEDBACK

1. SSPS LOGIC DISPLAY
2. SECONDARY REACTOR TRIP ALARMS
 - o NEGATIVE RATE TRIP
 - o LOW-LOW LEVELS IN SGs
 - o REACTOR TRIP/TURBINE TRIP
3. TURBINE TRIP
 - o GENERATOR BREAKER OPEN
 - o STOP VALVES AND GOVERNOR VALVES CLOSE
 - o TURBINE SPEED LESS THAN 1800 RPM AND DECREASING

TRIP BREAKER HISTORY

AUGUST 20, 1982	UNIT 2 "B" REACTOR TRIP BREAKER FAILED SSPS SURVEILLANCE TEST DUE TO UV COIL BINDING
JANUARY 6, 1983	UNIT 2 TRIP ON LOW-LOW SG LEVEL. "A" TRIP BREAKER FAILED TO OPEN FOR ABOUT 25 MINUTES.
JANUARY 1983	LER CONCLUDED 01/06 FAILURE DUE TO DIRT, CORROSION AND BINDING
JANUARY 13 - 18, 1983	UNIT 1 UV TRIP MECHANISMS DISASSEMBLED, CLEANED, AND REASSEMBLED
FEBRUARY 1983	FOLLOWING REFUELING OUTAGE, OPERABILITY CONDUCTED BEFORE UNIT 1 RESTART
FEBRUARY 20, 1983	UNIT 1 TRIP BREAKERS FUNCTIONED FOR 2 TRIPS: LOW-LOW SG LEVEL, HIGH-HIGH SG LEVEL
FEBRUARY 22, 1983	<ul style="list-style-type: none">o UNIT 1 TRIPS ON LOW-LOW SG LEVELo "B" REACTOR TRIP BREAKER COVER PLATE PROBLEMo FEED BYPASS VALVE POSITION INDICATORS REMOVED
FEBRUARY 22, 1983 2200 HOURS	SSPS TRIP SIGNALS ON LOW-LOW SG LEVEL "CONCURRENT" WITH MANUAL TRIP. TRIP BREAKER FAILURE ON SSPS SIGNAL NOT RECOGNIZED
FEBRUARY 25, 1983 0021 HOURS	REACTOR TRIP ON LOW-LOW SG LEVEL. NO INDICATION OF REACTOR TRIP. MANUAL SCRAM INITIATED 25 SECONDS LATER.

FEBRUARY 22 EVENT SEQUENCE

TIME

- 2155 - REACTOR BUS TRANSFER FROM OFF-SITE TO ON-SITE IN PROGRESS AT 20% POWER. DURING TRANSFER LOSS OF #13 RCP AND #12 MAIN FEED PUMP (MFP) OCCURS DUE TO LOSS OF CONTROL POWER (#12 MFP ONLY OPERATING MFP)
- 2156 :54 - REACTOR TRIP SIGNAL FROM LOW LOW LEVEL #13 S/G
- AUXILIARY FEEDWATER (AFW) PUMPS START
- 2156 :58 - MANUAL REACTOR TRIP DUE TO DEGRADING CONDITIONS
- TURBINE TRIP: REACTOR TRIP BREAKERS OPEN
- 2204 - *SAFETY INJECTION (SI) DUE TO 100 PSI DP BETWEEN #13 MAIN STEAM LINE AND OTHER STEAM LINES
- 2206 - OPERATOR NOTED #11 RCP HAD TRIPPED (WITH BOTH #11 AND #13 RCPs LOST, NO PRESSURIZER SPRAY TO CONTROL PRESSURE)
- BOTH PORVs LIFT FROM PRESSURE INCREASE DUE TO SI FLOW AND LOSS OF SPRAY FLOW
- 2211 - SI TERMINATED BY OPERATORS
- BOTH PORVs CLOSE
- PLANT STABILIZED IN MODE 3

2346 ** - NRC NOTIFIED VIA ENS

*100 PSI DEVELOPED BECAUSE #13 SG SUPPLYING TURBINE AFW PUMP AND #13 RCP NOT RUNNING

**NRC WAS INFORMED THAT THE SG LOW LOW LEVEL TRIPPED THE Rx AND THAT THE MANUAL TRIP INITIATED NEARLY SIMULTANEOUSLY

TIME

FEBRUARY 23

0628

- BLOCK VALVE FOR PORV PR-2 CLOSED BECAUSE
OF PORV SEAT LEAKAGE

SEQUENCE OF EVENT FOR FEBRUARY 25, 1983 EVENT

INITIAL CONDICTIONS - REACTOR POWER 12% TURBINE ON LINE
AND GENERATOR SYNCHRONIZED WITH
GRID: FEEDWATER SYSTEM IN MANUAL
CONTROL

TIME

- 0021 - LOW LOW WATER LEVEL #12 STEAM GENERATOR
- REACTOR TRIP SIGNAL GENERATED BY
SSPS AND INDICATED IN CONTROL ROOM
- PLANT PARAMETERS NOT CONSISTENT WITH
SCRAM
- 0021 :30 (APPROX) - REACTOR MANUAL SCRAM FROM CONTROL ROOM
- PLANT PARAMETERS INDICATE SCRAM
- 0048 - 0115 - EACH BREAKER TESTED VIA SSPS 5 TIMES -
"B" TRIP BREAKER FAILED
5 TIMES, "A" TRIP BREAKER FAILED 3 TIMES
- 0130 - ALERT DECLARED
- 0146 - ENS NOTIFICATION MADE
- 0200 - ALERT TERMINATED

ISSUES RELATED TO SALEM RESTART

AGENDA

1. DESCRIPTION OF BREAKER
2. LICENSEE CORRECTIVE ACTIONS
3. ISSUES

AUTOMATIC PROTECTION

INSTRUMENT CHANNELS

ACTUATION LOGICS (2/4)

POWER SOURCES (MG's)


TRIP BREAKERS

MANUAL PROTECTION


MANUAL SCRAM

BREAKER MANUAL CONTROLS


POWER TO CONTROL RODS




REACTOR TRIP SYSTEM




BASIC W DB-TYPE TRIP BREAKER



REACTOR TRIP BREAKER



UNDervOLTAGE TRIP MECHANISM



CORRECTIVE ACTIONS

(AS PROPOSED BY LICENSEE AT FEBRUARY 28, 1983 MEETING)

1. PSE&G VERIFIED SALEM SURVEILLANCE TESTING MEETS TECH SPEC REQUIREMENTS.
2. MAINTENANCE PROCEDURES FOR THE UV TRIP DEVICES WILL BE DEVELOPED BASED ON NSD 74-02 AND NCD-ELEC-18.
3. W WILL INSTALL NEW UNIT 1 UV ATTACHMENTS.
4. PROPER OPERATION OF THE BREAKERS WILL BE VERIFIED BY PSE&G AND W - PROGRAM BEING DEVELOPED.
5. W WILL VERIFY THAT THE UV ATTACHMENTS MEET SAFETY CLASSIFICATION SPECIFICATIONS FOR THE ORIGINAL RX SWITCHGEAR.
6. SURVEILLANCE OF BREAKER OPERATION WILL BE INCREASED TO MONTHLY INTERVAL.
7. PROCEDURES WILL BE REVISED TO REQUIRE THE OPERATOR TO ACTUATE THE REACTOR MANUAL TRIP SWITCH FOLLOWING AN AUTOMATIC REACTOR TRIP.
8. DEVELOP A FORMALIZED POST TRIP REVIEW PROCEDURE.
9. W WILL SEND COMPILATION OF ALL TECH BULLETINS, MANUALS PERTAINING TO W EQUIPMENT AT SALEM - SALEM WILL REVIEW AND INCORPORATE AS NECESSARY INTO STATION DOCUMENTS.
10. W IS CONDUCTING AN INTERNAL REVIEW OF THEIR PROCEDURES FOR DISSEMINATION OF TECHNICAL INFORMATION TO UTILITIES, PSE&G HAS IDENTIFIED THE DESIRED DISTRIBUTION OF THIS INFORMATION AS PART OF RECENT IMPROVEMENT IN THEIR HANDLING OF TECHNICAL DOCUMENTS.

11. A REVIEW IS IN PROGRESS AT SALEM OF PAST EQUIPMENT FAILURES DOCUMENTED IN LER'S, DEFICIENCY REPORT. A PREVENTIVE MAINTENANCE PROGRAM WILL BE IMPLEMENTED BASED UPON RESULTS OF REVIEW.

ISSUES

- SAFETY CLASSIFICATION OF BREAKERS
- IDENTIFICATION OF CAUSE OF FAILURE
- VERIFICATION TESTING
- REVISED SURVEILLANCE & MAINTENANCE PROCEDURES
- OPERATING PROCEDURES
 - AUTOMATIC/MANUAL SCRAM
 - ATWS EMERGENCY PROCEDURES
 - OPERATOR RESPONSE
- MANAGEMENT ISSUES
 - PROCEDURES FOR POST-TRIP REVIEWS
 - QUALITY ASSURANCE
 - ENFORCEMENT
 - LICENSEE UPDATING WESTINGHOUSE MAINTENANCE INFORMATION
 - OTHER EQUIPMENT MAINTENANCE PROCEDURES

NRC BULLETIN OF 02/25/83

IE BULLETIN 83-01: FAILURE OF REACTOR TRIP BREAKERS (WESTINGHOUSE DB-50)
TO OPEN ON AUTOMATIC TRIP SIGNAL

REQUESTED ACTION ITEMS - ALL PWRs

- TEST UNDERVOLTAGE TRIP FUNCTION WITHIN 24 HOURS IF NOT TESTED WITHIN 5 DAYS
- REVIEW MAINTENANCE PROGRAM AND CONFORM TO W PROGRAM OR ALTERNATE
- NOTIFY ALL LICENSED OPERATORS OF THE SALEM EVENT, AND REVIEW EMERGENCY PROCEDURES FOR FAILURE-TO-TRIP WITH EACH OPERATOR ON HIS ARRIVAL ON SHIFT
- REPORT TO NRC WITHIN 7 DAYS

PLANTS WITH DB BREAKERS IN RPS

- ° ALL W OPERATING PLANTS EXCEPT FARLEY, MCGUIRE AND SUMNER
- ° NO B&W, CE OR GE PLANTS USE DB TYPE BREAKERS WITH UV TRIP PROVISIONS IN RPS
- ° OTHER SAFETY RELATED APPLICATIONS OF DB BREAKERS ARE BEING REVIEWED

IEB 83-01 TEST RESULTS

- TESTING COMPLETED AS REQUESTED FOR ALL W PLANTS WITH DB TYPE BREAKERS
- NO FAILURES FOUND
- PLANTS SHUTDOWN WILL TEST BEFORE RETURN TO POWER

GENERIC IMPLICATION FOLLOW-UP

GENERIC IMPLICATION FOLLOW-UP

1. WESTINGHOUSE ACTIONS
 - o INTERCOMPANY TASK FORCE - CONDUCTING AN INTERNAL REVIEW OF THEIR PROCEDURES FOR DISSEMINATION OF TECHNICAL INFORMATION TO UTILITIES
 - o EVALUATION AND TESTING PROGRAM FOR MODEL DB-50 BREAKER UV COIL
 - o DEVELOPING PROCEDURES FOR INDEPENDENT TESTING OF UV AND SHUNT COIL TESTING
2. OWNERS GROUP/RRG (WESTINGHOUSE PLANTS)
 - o A LISTING OF CURRENT W TECHNICAL DATA LETTERS TO BE DISTRIBUTED
 - o EVALUATE THE EFFECTIVENESS OF MANUAL SCRAM FOLLOWING AUTOMATIC SCRAM
 - o REVIEW OF TRIP AND ATWS EMERGENCY PROCEDURES
 - o ADEQUACY OF STS, SURVEILLANCE INTERVAL, TEST METHOD, AND TESTING OF SHUNT COIL
 - o NOTIFY MEMBERS TO CONDUCT A REVIEW FOR SIMILAR TYPE FAILURES IN OTHER SYSTEMS.
3. MEETINGS WITH CE/B&W/GE RRGs
4. PER EDO MEMO OF 02/28/83
 - o DETAILED EVENT REPORT BY MARCH 9 (REGION I)
 - o EVALUATION OF GENERIC IMPLICATIONS BY APRIL 18 (NRR)
5. FACTOR EXPERIENCE INTO ATWS POSITION

BACKUP SLIDES

- HISTORY OF PWR SCRAM BREAKER FAILURES
- STATUS OF PAST ACTIVITIES

HISTORY OF PWR SCRAM BREAKER FAILURES

- o SINCE 1973 THERE HAVE BEEN APPROXIMATELY 340 PWR REACTOR YEARS OF OPERATION:
 - 220 WESTINGHOUSE
 - 70 B&W
 - 50 CE

- o DURING THIS PERIOD OF TIME THERE HAVE BEEN 35 KNOWN SCRAM BREAKER FAILURES:
 - 21 WESTINGHOUSE
 - 13 B&W
 - 1 CE

- o THE AVERAGE NUMBER OF SCRAM BREAKER FAILURES PER REACTOR YEAR BY VENDOR IS:
 - 0.095 WESTINGHOUSE
 - 0.19 B&W
 - 0.021 CE

- o THE CORRESPONDING AVERAGE NUMBER OF REACTOR YEARS BETWEEN BREAKER FAILURES BY VENDOR IS:
 - 11 WESTINGHOUSE
 - 5.3 B&W
 - 48 CE

- o THE CORRESPONDING EXPECTED NUMBER OF SCRAM BREAKER FAILURES IN A CALENDAR YEAR BY VENDOR IS:
 - 2.9 WESTINGHOUSE
 - 1.3 B&W
 - 0.15 CE

FAILURE MECHANISMS FOR SCRAM BREAKERS

35 SCRAM BREAKER FAILURES SINCE 1973

- o 25 DUE TO UNDERVOLTAGE COIL MECHANISM FAILURE OR BINDING
- o 6 DUE TO MECHANICAL PROBLEMS WITHIN THE BREAKER OR BREAKER PARTS BEING OUT OF ADJUSTMENT
- o 3 UNKNOWN
- o 1 DIRT

STATUS OF PAST ACTIVITIES

NOVEMBER 24, 1981	FRN NOTICE WITH PROPOSED RULES
APRIL 23, 1982	COMMENTS RECEIVED ON FRN. LARGE STUDY BY UTILITY GROUP ON ATWS.
SEPTEMBER - NOVEMBER, 1982	TASK FORCE AND STEERING GROUP MET AND DRAFTED RECOMMENDATIONS
NOVEMBER 3, 1982	CRGR BRIEFED
NOVEMBER 10, 1982	CRGR SUBMITS QUESTIONS TO STAFF
DECEMBER 7, 1982	STAFF SUBMITS ANSWERS TO CRGR QUESTIONS
JANUARY 26, 1982	CRGR BRIEFED ON ANSWERS TO QUESTIONS AND SLIGHTLY REVISED VALUE/IMPACT ANALYSIS

PROPOSED RULE ELEMENTS

GE (BWR)

- o ARI INSTALLED
- o INCREASE SLCS TO 86 GPM
- o AUTOMATICALLY TRIP RECIRCULATING PUMPS
- o PROVIDE RELIABLE SCRAM DISCHARGE VOLUME
- o IMPLEMENT PROCEDURES FOR OPERATOR RESPONSE

PWR (ALL)

- o INSTALL AMSAC-DIVERSE AND INDEPENDENT AFW INITIATION AND TURBINE TRIP

CE/B&W



- o PROVIDE A DIVERSE SCRAM SYSTEM, INDEPENDENT FROM THE REACTOR PROTECTION SYSTEM

CURRENT STATUS

1. DRAFT REPORT OF TASK FORCE AND STEERING GROUP
RECOMMENDATIONS ISSUED FOR COMMENT TO MEMBERS
2. DRAFT RULE AND FR NOTICE ISSUED FOR STAFF COMMENT
3. COMMENTS FROM STAFF AND CRGR ON VALUE/IMPACT
ANALYSES BEING RESOLVED
4. IMPLICATIONS OF SALEM ATWS UNDER REVIEW

ATWS RULEMAKING SCHEDULE

- 3/9/83 ATWS TASK FORCE AND STEERING GROUP
CONCUR ON REPORT AND PROPOSED RULE
- 3/23/83 PRESENTATION OF PROPOSED RULE AND
COMMISSION PAPER TO CRGR.
- 4/22/83 CRGR CONCURRENCE
- 5/6/83 ACRS REVIEW
- 6/6/83 PAPER PRESENTED TO COMMISSION





NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

February 28, 1983

MEMORANDUM FOR: Harold R. Denton, Director, NRR

FROM: William J. Dircks
Executive Director for Operations

SUBJECT: EVALUATION OF THE IMPLICATIONS OF THE SALEM UNIT I EVENT


This memorandum confirms our conversation of February 28, 1983. I am establishing an NRC Task Force to undertake a review and evaluation of the implications of the Salem Unit I event.

You are appointed to organize that task force in order to develop criteria for the review and to prepare a final report. You should designate a senior member of the NRR staff to act as Chairman and a senior representative from appropriate Regional Offices, OIE, NRR and AEOD to be a member of the Task Force. Contact those offices directly to acquire mutually acceptable members. You are authorized to task NRC offices directly to accomplish this work. Offices are expected to give priority to this request unless they obtain relief from me.

Your review and evaluation shall include the extent to which similar equipment is used in other facilities, the extent to which proper surveillance and maintenance of such equipment has been adhered to, and the effect quality classification may have had on the malfunction. At the conclusion of this review and evaluation, I expect that you will identify any changes that are needed in license and/or procedural requirements at any affected facilities.

I request that you keep me advised of progress and difficulties encountered as necessary. A report should be scheduled for transmission to the Commission by April 18, 1983. Publication of the report should be in the form of a NUREG which provides adequate documentation to support any recommendations you may have.

By copy of this memorandum, Region-I is directed to provide you with a report by March 9, 1983 on the circumstances and details of the events that took place on February 22-25, 1983 and any relevant prior experience at the Salem Unit I facility during which the automatic scram system did not function properly.


William J. Dircks
Executive Director
for Operations



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555


March 1, 1983

MEMORANDUM FOR: Chairman Palladino
Commissioner Gilinsky
Commissioner Ahearne
Commissioner Roberts
Commissioner Asselstine

FROM: William J. Dircks
Executive Director for Operations

SUBJECT: SALEM UNIT EVENT

By the attached memorandum, I am asking Harold Denton to prepare a report on the incident at Salem that occurred on February 25, 1983. I have asked that the report be submitted by April 18, 1983.


William J. Dircks
Executive Director
for Operations

Enclosure
Memo to HRDenton/NRR
fm WJDircks/EDO dtd 2/28/83

CC: SECY ✓
OGC
OPE



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

February 28, 1983

MEMORANDUM FOR: Harold R. Denton, Director, NRR

FROM: William J. Dircks
Executive Director for Operations

SUBJECT: EVALUATION OF THE IMPLICATIONS OF THE SALEM UNIT I EVENT


This memorandum confirms our conversation of February 28, 1983. I am establishing an NRC Task Force to undertake a review and evaluation of the implications of the Salem Unit I event.

You are appointed to organize that task force in order to develop criteria for the review and to prepare a final report. You should designate a senior member of the NRR staff to act as Chairman and a senior representative from appropriate Regional Offices, OIE, NRR and AEOD to be a member of the Task Force. Contact those offices directly to acquire mutually acceptable members. You are authorized to task NRC offices directly to accomplish this work. Offices are expected to give priority to this request unless they obtain relief from me.

Your review and evaluation shall include the extent to which similar equipment is used in other facilities, the extent to which proper surveillance and maintenance of such equipment has been adhered to, and the effect quality classification may have had on the malfunction. At the conclusion of this review and evaluation, I expect that you will identify any changes that are needed in license and/or procedural requirements at any affected facilities.

I request that you keep me advised of progress and difficulties encountered as necessary. A report should be scheduled for transmission to the Commission by April 18, 1983. Publication of the report should be in the form of a NUREG which provides adequate documentation to support any recommendations you may have.

By copy of this memorandum, Region-I is directed to provide you with a report by March 9, 1983 on the circumstances and details of the events that took place on February 22-25, 1983 and any relevant prior experience at the Salem Unit I facility during which the automatic scram system did not function properly.


William J. Dircks
Executive Director
for Operations

Richard A. Uderitz
Vice President -
Nuclear

Public Service Electric and Gas Company P.O. Box 236, Hancocks Bridge, NJ 08038 609 935-6010

R. L. NAS

March 1, 1983

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing

Gentlemen:

REACTOR TRIP BREAKER FAILURE
NO. 1 UNIT
SALEM GENERATING STATION
DOCKET NO. 50-272

The purpose of this letter is to document our investigation of two reactor trip breaker failures and provide corrective actions to be taken.

On February 22 and 25, 1983, the Salem Unit 1 reactor trip breakers failed to open upon receipt of a valid trip signal from the reactor protection system. In both instances, the manual trip was used to shut down the unit.

PSE&G has determined that the reactor trip breaker undervoltage trip attachment failures were caused by a lack of proper lubrication on the latch. Westinghouse expert opinion concurs with this based upon:

- a. An inspection of the undervoltage trip attachments.
- b. A review of PSE&G accounts of the tests performed after the failures.
- c. Previous Westinghouse experience which indicates that the lack of lubrication has been the cause of similar previous failures.

Blair

As presented in our meeting on February 28, 1983, our investigation of these incidents is summarized herein.

PSE&G has reviewed the plant data from the events of February 22 and 25, 1983 to evaluate any potential safety impact on the primary system. Review of the primary coolant parameters did not reveal any significant perturbations and followed trends that would be expected in a normal plant trip.

The bounding case in the FSAR is the loss of normal feedwater at 102% power with only one auxiliary feedwater pump starting. In that transient, two steam generators boil dry and the other two drop to a level where approximately 50% of the tube bundles are exposed. This provided sufficient heat removal to preclude boiling in the primary system. This is a more limiting case than the two recent incidents at Salem, where on February 22nd as a result of the transient, the water level in three steam generators briefly dropped to a level equivalent to approximately 20% of the tube bundle exposed. On February 25th, the level in one steam generator again briefly dropped to approximately this same level. On both occasions, there was automatic auxiliary feedwater initiation.

The potential for waterhammer in the steam generator feed ring exists when the feedwater flow is interrupted long enough to allow the feed ring to drain. In both recent instances, there was no flow interruption since auxiliary feedwater was initiated automatically. In addition, "J-tubes" have previously been installed in the feed rings.

In conclusion, the events of February 22 and 25, 1983 were within bounds of FSAR analyses and did not have the necessary prerequisites for feedwater line waterhammer.

Our review of the breaker failures has resulted in a program of corrective actions to assure that such failures will not recur. These corrective actions are described below:

1. PSE&G has verified the Salem surveillance testing meets the technical specification requirements.

Procedure PD18.1.004/5 Solid State Protection System Reactor Trip Breakers and Permissive P-4 Test Train A/B satisfy the requirements for testing the reactor trip breakers.

3-1-83

Procedure PD18.1.008/9 Solid State Protection System Functional Test Train A/B satisfied the requirements for testing the automatic trip logic.

2. A detailed maintenance procedure M3Q-2 entitled Reactor Trip and Bypass ACB Inspection and Test, which includes the undervoltage trip attachment, has been developed and approved. This procedure is based on and references Westinghouse data letter NSD-TB-74-2, Westinghouse Procedure NDC-ELEC-18 and the Westinghouse Instruction Book for DB-50, DBF-16 and DBL-50-ACB's. This includes electrical testing of the breaker, notification of the Technical Department of the need for post maintenance testing and appropriate QA inspection hold points.
3. New undervoltage trip attachments will be supplied by Westinghouse and will be installed on each of the four No. 1 Unit breakers. Westinghouse will provide technical assistance to PSE&G to assure that No. 1 Unit undervoltage trip attachments are installed properly and that the breakers operate properly.
4. Proper operation of the breakers will be verified prior to placing the breakers in service. A program to verify proper operation will be developed and completed prior to returning to service. This program will take into consideration statistical data and recommendations to be provided by Westinghouse.
5. PSE&G will verify that Westinghouse has determined that the UV attachments meet the specification requirements for the original reactor trip switchgear.
6. Surveillance of reactor trip breaker operation will be increased as follows:
 - a. Main and bypass breakers will be shunt-tripped weekly.
 - b. Main breakers will be UV-tripped monthly.

Proposed technical specification changes will be submitted as appropriate.

7. The following tests will be performed after maintenance on reactor trip breakers to demonstrate operability prior to return of the breaker to service:
 - a. Breaker will be shunt-tripped.
 - b. Breaker will be UV-tripped.
 - c. Breaker will be time-response tested.
8. Emergency Instruction I-4.3, Reactor Trip, for Salem Units 1 and 2 will be revised to include the requirement to manually trip the reactor trip breakers on all reactor trips.

The revision to this procedure and the basis for this additional action will be disseminated to all licensed operators.

9. A formal reactor trip/safety injection post trip review procedure will be developed and issued as an Operations Department Directive. This procedure will specify the review and documentation necessary to determine the cause of the event and also determine that affected equipment performed in its intended function. The procedure will also include management authorization requirements for startup. All licensed operators will be informed of the requirements of this document.
10. A review of LER's, deficiency reports, maintenance work sheets and work orders is in progress to identify items requiring preventative maintenance. Our preventative maintenance program will incorporate the results of this review to be completed by January 1, 1984.
11. A reactor trip and bypass breaker traceability program will be established to insure that all work performed on the breakers will be traceable to a particular breaker and its location. This will be accomplished by April 1, 1983.
12. Westinghouse has committed to provide PSE&G with a compilation of all technical bulletins, manuals, etc., pertaining to Westinghouse equipment utilized at Salem. These will be reviewed and incorporated into station documents as necessary in a timely manner.

Mr. Darrell G. Eisenhut
U. S. Nuclear Regulatory
Commission

- 5 -

3-1-83

13. Work orders will be reviewed by QA to insure that there is proper designation of safety related items. For safety related work, QA will establish proper inspection and/or surveillance coverage.

In addition, PSE&G is undertaking a thorough review of its Operational QA Program to identify changes necessary to improve performance.


In our meeting with the staff on February 28, 1983, we were requested to clarify the safety classification of the reactor trip breakers. The reactor trip breakers are part of the Reactor Trip System which is a safety-related system. In the design and construction of Salem Generating Station, PSE&G considered as safety-related, those structures, systems and components that prevent or mitigate the consequences of postulated accidents that could cause undue risk to the health and safety of the public.

Salem UPSAR Section 7.1.1.1 states that the Reactor Trip System consists of equipment which initiates reactor trip or activates engineered safety features. Included is equipment from sensors to actuating devices. The reactor trip breakers and the under-voltage attachment are safety-related. The shunt-trip attachment is not a functional part of the reactor trip system.

Corrective action Items 1 through 9 will be completed prior to startup. Corrective action Items 10 through 13 will be completed as described therein.

We believe that accomplishment of the corrective actions identified above will preclude recurrence of these and similar events and provide adequate confidence that Salem Unit 1 can be safely returned to service.

Sincerely,



TRANSMITTAL TO: Document Control Desk, 016 Phillips.

ADVANCED COPY TO: The Public Document Room

DATE: 3/3/83

cc: OPS File

FROM: SECY OPS BRANCH

C&R (Natalie)

Attached are copies of a Commission meeting transcript(s) and related meeting document(s). They are being forwarded for entry on the Daily Accession List and placement in the Public Document Room. No other distribution is requested or required. Existing DCS identification numbers are listed on the individual documents wherever known.

Meeting Title: Briefing on Salem

Meeting Date: 3/2/83 Open Closed

DCS Copies
(1 of each checked)

Item Description:	Copies Advanced To PDR	*	Original Document	May be Dup*	Duplicate Copy*
1. TRANSCRIPT (w/micrographs) When checked, DCS should send a copy of this transcript to the LPDR for: _____	1	*	1	—	—
2. <u>Memo Dircks to</u> <u>com. dated 3/1/83</u>	<u>1</u>	*	—	<u>1</u>	—
3. <u>Ltr Public Service</u> <u>Electric & Gas Co to</u> <u>Everhart, NRC</u> <u>Dated 3/1/83</u>	<u>1</u>	*	—	<u>1</u>	—
4. _____	—	*	—	—	—

(PDR is advanced one copy of each document, two of each SECY paper.)

*Verify if in DCS, and Change to "PDR Available."