

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81062 Technical Specification Involved T.S. Table 3.1.A Note 20

Reported Under Technical Specification 6.7.2.b(1) * Date Due NRC 12/17/81

Date of Occurrence 11/17/81 Time of Occurrence 1600 Unit 2

Identification and Description of Occurrence:

Main steam line radiation monitors 2-RM-90-137(C) and 2-RM-90-139(D) became erratic and read lower than normal.

Conditions Prior to Occurrence:

Unit 1 at 99%.

Unit 2 at 100%.

Unit 3 in refueling outage.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Loose-dirty connectors

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The connectors were tightened, SI 4.1.A-10 was successfully performed, and the radiation monitors returned to service. This is considered a random failure and no further recurrence control is required.

Failure Data:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: Jh. Wilson