

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | C | R | P | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 7 | 0 | 1 | 2 | 9 | 8 | 2 | 8 | 0 | 2 | 1 | 2 | 8 | 2 | 9

02 | At 1100 while performing a visual inspection of RCP-A seal package, a crack in the weld  
03 | between the 3rd stage cavity and a vent pipe was discovered. This created an event con-  
04 | trary to T.S. 3.4.6.2.a., no pressure boundary leakage. The plant was in Mode 3 at the  
05 | time of discovery. The plant was cooled down and Mode 5 was entered at 0255 on January  
06 | 30, 1982. There was no effect upon the health or safety of the general public. This is  
07 | the first occurrence concerning RCP-A, and this is the third event reported under this  
08 | Specification.

09 | C | B | 11 | X | 12 | Z | 13 | P | I | P | E | X | X | 14 | A | 15 | Z | 16 | 17 | 8 | 2 | 0 | 0 | 4 | 0 | 1 | T | 0 | 19 | A | 20 | A | 21 | 0 | 0 | 9 | 0 | Y | 23 | N | 24 | N | 25 | B | 5 | 8 | 0 | 26

10 | The cause of this event is attributed to a crack in a weld joint where the vent pipe meets  
11 | with the third stage cavity. The plant was cooled down to Mode 5 and the seal package was  
12 | replaced with a rebuilt spare seal package. The failed weld joint will be analyzed for  
13 | cause of failure. A revision(s) to this report will be forthcoming.

15 | G | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Operator observation | 32

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

18 | 0 | 0 | 0 | 40 | NA | 41

19 | Z | 42 | NA | 43

20 | Y | 44 | 1/29/82 General Press Release Made. | 68 69 | 904/795-6486 | 80

050 817-826

SUPPLEMENTARY INFORMATION

Report No.: 50-302/82/004/01T-0

Facility: Crystal River Unit #3

Report Date: February 12, 1982

Occurrence Date: January 29, 1982

Identification of Occurrence:

A reactor coolant pressure boundary leak was discovered on a weld joint of a vent pipe of the third stage cavity. This created an event contrary to Technical Specification 3.4.6.2.a.

Conditions Prior to Occurrence:

Mode 3 hot standby (0%).

Description of Occurrence:

While performing a visual inspection of RCP-A seal package, a crack in the weld between the third stage cavity and a vent pipe was discovered. The plant was cooled down to Mode 5 from Mode 3 and repair was initiated.

Designation of Apparent Cause:

The cause of this event is attributed to the cracking of a weld joint. The determination of actual failure is under investigation.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

The seal package for RCP-A was replaced with a rebuilt spare seal package and the weld failure will be investigated to determine cause of failure.

Failure Data:

This is the first occurrence concerning RCP-A and this is the third event reported under this Specification.

/rc