LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 5 E CAT 58
CON'T O 1 SOURCE I 6 0 5 0 - 0 3 2 5 7 0 1 1 8 8 2 8 0 2 1 6 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Following a 52% decrease in reactor power in < 1 hour, the surveillance requirements
[0]3 for reactor coolant sampling between 2 and 6 hours after a 15% power decrease were not
[0]4] performed. Reactor coolant analysis performed prior to and following the discovery
of this event showed the I-131 dose equivalent was < .2 µCi/gm. This event did not
0 6 affect the health and safety of the public.
Technical Specifications 4.0.2, 4.4.5
0 8 80
SYSTEM CAUSE CAUSE COMPONENT CODE COMPONENT CODE SUBCODE SUBCODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
The responsible control operator and senior control operator failed to properly notify
plant chemistry that required coolant analysis needed to be performed. Involved
operations personnel were counseled to be aware of required reactor coolant analysis
following > 15% power changes. All licensed operations personnel will review this
report to ensure their familiarity of this concern.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 F 28 0 4 7 29 NA D 31 NRC Inspector Review 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
7 8 9 PERSONNEL INJURIES DESCRIPTION (41) NUMBER O O O O O O O O O O O O O O O O O O O
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA
7 8 9 10 PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
2 0 N (44) NA
PDR ADOCK 05000325 PDR PHONE: (919) 457-9521 %