

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(0) (1) | P | L | C | R | P | 3 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | _____ | (5)
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

(0) (1) | R | (6) | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | (7) | 0 | 2 | 1 | 1 | 1 | 8 | 3 | (8) | 0 | 3 | 1 | 1 | 8 | 3 | (9)
7 8 9 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(0) (2) | At 1715, during normal operation, the absolute position indication for
 (0) (3) | Rod 1, Group 1, failed to indicate +/-2% motion, reportable under T.S.
 (0) (4) | 3.1.3.3. Control Rod 1, Group 1, was verified at 100% in accordance with
 (0) (5) | T.S. 3.1.3.3.a.2. Redundancy was provided by relative position indication.
 (0) (6) | This is the first occurrence for Rod 1, Group 1, and the thirteenth report
 (0) (7) | under this specification.
 (0) (8) | _____
7 8 9 80

(0) (9) | I | D | (11) | E | (12) | E | (13) | I | N | S | T | R | U | (14) | S | (15) | Z | (16)
7 8 9 10 11 12 13 14 15 16 17 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 (17) | LER/RO REPORT NUMBER | (18) | 8 | 3 | (19) | - | (20) | 0 | 0 | 8 | (21) | / | (22) | 0 | 3 | (23) | L | (24) | - | (25) | 0 | (26)
21 22 23 24 25 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 (18) | X | (19) | C | (20) | Z | (21) | Z | (22) | 0 | 0 | 0 | 0 | (23) | Y | (24) | N | (25) | N | (26) | D | 1 | 5 | 0 | (27)
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(1) (0) | This event was caused by a failed reed switch. Rod position is being veri-
 (1) (1) | fied every 12 hours via zone reference. The position indicator tube con-
 (1) (2) | taining the faulty reed switch will be replaced during the next refueling
 (1) (3) | outage.
 (1) (4) | _____
7 8 9 80

(1) (5) | E | (28) | 0 | 9 | 7 | (29) | NA | (30) | A | (31) | Operator Observation | (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 (1) (6) | Z | (33) | Z | (34) | NA | (35) | NA | (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 (1) (7) | 0 | 0 | 0 | (37) | NA | (38)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 (1) (8) | 0 | 0 | 0 | (40) | NA | (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL INJURIES NUMBER DESCRIPTION
 (1) (9) | Z | (42) | NA | (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 (2) (0) | N | (44) | NA | (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PUBLICITY ISSUED DESCRIPTION NRC USE ONLY

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/83-008/03L-0
FACILITY: Crystal River Unit #3
REPORT DATE: March 11, 1983
OCCURRENCE DATE: February 11, 1983

IDENTIFICATION OF OCCURRENCE:

On February 11, 1983, the Absolute Position Indicator (API) for Rod 1, Group 1 failed. This indicator is required to be operable by Technical Specification 3.1.3.3.

CONDITIONS PRIOR TO OCCURRENCE:

MODE 1 (97% FULL POWER)

DESCRIPTION OF OCCURRENCE:

At 1715 on February 11, 1983, during normal operation, Rod 1, Group 1 API was determined to be inoperable. The API indicates that this rod is 97.5% withdrawn while Zone Reference indicates fully withdrawn (100%). The rod is being verified at the fully withdrawn position every 12 hours.

DESIGNATION OF APPARENT CAUSE:

The indicator failure is caused by a faulty reed switch.

ANALYSIS OF OCCURRENCE:

Redundant position indication is provided by Zone Reference and the Relative Position Indicator. There is no effect on public health or safety.

CORRECTIVE ACTION:

The position indicator tube containing the faulty reed switch will be replaced during the next refueling outage.

FAILURE DATA:

This is the first failure for this rod and the thirteenth report under specification 3.1.3.3.