LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T O 1 REPORT L 6 0 5 0 0 0 2 7 2 7 0 2 0 9 8 3 8 0 3 0 7 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 2 On February 9, 1983, during routine shutdown operation, the Control Room Operator
0]3 discovered that the auxiliary alarm typewriter had failed. The failure rendered the
Containment Sump Monitoring System inoperable, and Action Statement 3.4.6.1 was entered.
Redundant Reactor Coolant System leakage detection systems were operable throughout
the occurrence. Due to the loss of redundancy the event constituted operation in a
degraded mode in accordance with Technical Specification 6.9.1.9b.
[0]8 (81-117, 81-095, 81-008, 80-015)
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
LER RO EVENT YEAR REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB, SUPPLIER MANUFACTURER C 18 F 9 Z 20 Z 21 0 0 0 0 0 Y 23 Y 24 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
Investigation revealed that the failure of the auxiliary alarm typewriter was due to
a failed circuit board in the Auxiliary Annunciator System. The board was replaced,
the typewriter was restored to operation, and the action statement was terminated.
Separate annunciators for the Containment Sump Monitoring System are presently being
installed.
FACILITY STATUS THER STATUS T
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 N/A N/A N/A 44 45
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 7 8 9 11 12 13 N/A
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY DESCRIPTION 1 9 Z (42) N/A
7 8 9 10 PUBLICITY ISSUED DESCRIPTION 45 PDR ADOCK 05000272 PDR ADOCK 05000272 PDR ADOCK 05000272 PDR ADOCK 05000272
7 8 9 10 68 69 80 5 R. Frahm (609) 935-6000 Ext 3078 °
NAME OF PREPARER PHONE: