

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

<u>0</u>	<u>1</u>	<u>N</u>	<u>J</u>	<u>S</u>	<u>G</u>	<u>S</u>	<u>1</u>	<u>0</u>	<u>0</u>	<u>-</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>-</u>	<u>0</u>	<u>0</u>	<u>4</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>4</u>	<u> </u>	<u> </u>
7 8		9 14 LICENSEE CODE						15 25 LICENSE NUMBER							26 30 LICENSE TYPE					31 57 CAT 58		58 60				

<u>0</u>	<u>1</u>	<u>L</u>	<u>0</u>	<u>5</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>2</u>	<u>7</u>	<u>2</u>	<u>7</u>	<u>0</u>	<u>2</u>	<u>0</u>	<u>5</u>	<u>8</u>	<u>3</u>	<u>0</u>	<u>3</u>	<u>0</u>	<u>7</u>	<u>8</u>	<u>3</u>
7 8		9 10		11 68 DOCKET NUMBER				69 74 EVENT DATE				75 80 REPORT DATE											

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 From October 16, 1982 to February 5, 1983 during scheduled testing of Containment Type

03 B and C components, three containment isolation valves exhibited leakage in excess of

04 the test equipment range (20,000 sccm). It was therefore not possible to demonstrate

05 combined leakage was less than 0.60 La as required by Limiting Condition for Operation

06 3.6.1.2b. Redundant containment barriers had been maintained during previous operation.

07 The event constituted operation in a degraded mode in accordance with Technical

08 Specification 6.9.1.9b. (82-030, 80-062)

<u>0</u>	<u>9</u>	<u>S</u>	<u>A</u>	<u>E</u>	<u>B</u>	<u>V</u>	<u>A</u>	<u>L</u>	<u>V</u>	<u>E</u>	<u>X</u>	<u>X</u>	<u>Z</u>
7 8		9 10		11 12		13 18 COMPONENT CODE					19 20	21 20 VALVE SURCODE	

<u>17</u>	<u>B</u>	<u>3</u>	<u>--</u>	<u>0</u>	<u>1</u>	<u>0</u>	<u>/</u>	<u>0</u>	<u>3</u>	<u>L</u>	<u>--</u>	<u>0</u>
7 8		9 10		11 12		13 14		15 16		17 18		19 20

<u>D</u>	<u>X</u>	<u>Z</u>	<u>Z</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>Y</u>	<u>Y</u>	<u>A</u>	<u>M</u>	<u>1</u>	<u>2</u>	<u>0</u>
7 8		9 10		11 12				13 14		15 16		17 18		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Two of the valves were restroked and tested satisfactorily. Steam Generator Blowdown

11 Valve 14GB4 internals were wire cut; the valve was reworked and was satisfactorily

12 tested. Due to a recurrence of problems with the valves, further engineering

13 investigation will be performed.

<u>1</u>	<u>5</u>	<u>G</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>N/A</u>	<u>B</u>	<u>Surveillance Testing</u>	
7 8		9 13				14 15		16 20	

<u>1</u>	<u>6</u>	<u>Z</u>	<u>Z</u>	<u>N/A</u>	<u>N/A</u>
7 8		9 10		11 12	

<u>1</u>	<u>7</u>	<u>0</u>	<u>0</u>	<u>Z</u>	<u>N/A</u>
7 8		9 11		12 13	

<u>1</u>	<u>8</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>N/A</u>
7 8		9 12			13 14

<u>1</u>	<u>9</u>	<u>Z</u>	<u>N/A</u>
7 8		9 10	

<u>2</u>	<u>0</u>	<u>N</u>	<u>N/A</u>	<u>S</u>	<u>PDR</u>
7 8		9 10		11 12	

GPO 917-926