

Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

March 11, 1983

Mr. R. C. Haynes
Regional Administrator
USNRC
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

LICENSE NO. DPR-70 DOCKET NO. 50-272 REPORTABLE OCCURRENCE 83-012/01T

Pursuant to the requirements of Salem Generating Station Unit No. 1 Technical Specifications, Section 6.9.1.8.c, we are submitting Licensee Event Report for Reportable Occurrence 83-012/01T. This report is required within fourteen (14) days of the occurrence.

Sincerely yours,

H. J. Midura

General Manager -Salem Operations

H.J. Sepidena

RF:ks

CC: Distribution

8303180423 830311 PDR ADDCK 05000272 S PDR

4 Cont

Report Number: 83-012/01T

Report Date: 03-10-83

Occurrence Date: 02-22-83

Facility: Salem Generating Station Unit 1

Public Service Electric & Gas Company Hancock's Bridge, New Jersey 08038

IDENTIFICATION OF OCCURRENCE:

Reactor Trip System - Reactor Trip Breakers - Inoperable.

This report was initiated by Incident Report 83-050.

CONDITIONS PRIOR TO OCCURRENCE:

Mode 1 - RX Power 20 5 - Unit Load 140 MWe.

DESCRIPTION OF OCCURRENCE:

On February 22, 1983, during a routine startup of Salem Unit 1, the reactor was manually tripped due to rapidly decreasing steam generator levels. Approximately 3 seconds before the manual trip, both reactor trip breakers failed to open automatically on receipt of a valid Low-Low Steam Generator Level reactor trip signal. The fact that both breakers had failed was obscured by the manual trip, and the ensuing investigation therefore focused on the reasons for the manual trip and the related events.

Following a similar occurrence on February 25, 1983 (see LER 83-011/01T), the plant was placed in a safe shutdown condition. A plant cooldown was subsequently commenced, and the unit entered Mode 5 at 0254 hours, February 26, 1983.

Letters to the NRC dated March 1 and 8, 1983, provide documentation of the investigation of the incident and proposed corrective action. A Supplemental Report will be submitted documenting the occurrence in detail.

FAILURE DATA:

Westinghouse Electric Corp. Air Circuit Breaker Model DB-50 Type A

Prepared By R. Frahm

General Manager -Salem Operations

SORC Meeting No. 83-031B