	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C A S 0 S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 4 5 57 CAT 58 5
O 1 8	REPORT L 6 0 5 0 0 0 3 6 1 7 0 2 1 8 8 3 8 0 3 0 3 0 3 8 3 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 0 02/18/83 with Unit 2 and Unit 3 in Mode 5, it was determined that sample system
0 3	piping associated with the plant vent stack monitor 3RT-7865 was incorrectly installed.
0 4	This rendered monitor 3RT-7865 inoperable and prevented collection of representative
0 5	iodine and particulate samples. Since monitor 2/3-RT-7808 was removed from service
0 6	for modification, neither Technical Specification 3.3.3.9 nor associated Action
0 7	Statements 'a' or 'b' could be satisfied. There was no impact on the health and
0 8	safety of the plant personnel or the public.
0 9 7 8	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	The sample line for plant vent stack monitor 3RT-7865 was improperly installed. The
11	proper piping configuration was established and monitor 3RT-7865 was declared
1 2	operable on February 23. All radiation monitoring piping will be examined to confirm
1 3	this is an isolated occurrence.
	9
1 5	7 19 16 13 44 45 46
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 N/A N/A
1 7 1	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  0 0 0 37 Z 38 N/A
1 8 1	NUMBER DESCRIPTION (41) N/A
1 9	Z 42 N/A
7 8 9	10 P 1 N/han 1
	NAME OF PREPARER H.B. Ray PITTING / TOTAL 714-492-7700