

ATTACHMENT TO LER 83-017
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION
UNIT NO. 3, DOCKET NO. 50-362

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Tank pressure was restored to within the allowable limits at 1409. Subsequent investigation revealed that HPSI #1 header isolation valve 3HV-9324 was not sealing properly due to an out of adjustment limit switch. The limit switch was adjusted and the valve was restored to operable status on February 21, 1983. Relief valve 3PSV-9346 was disassembled and pitting was observed on the seat. The valve seat is being relapped. No further action is required for the check valve, since the differential pressure across it was insufficient to seat it. No other corrective actions are planned.