

LICENSEE EVENT REPORT

CONTROL BLOCK: [] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [M][D][C][C][N][I] [0][0]-[0][0][0][0][0][0]-[0][0] [3][4][1][1][1][1][1] [4] [] [] [] [] [] (5)

CON'T
 [0][1] [L] [6] [0][5][0][0][0][3][1][7] [7] [0][8][1][6][8][2] [8] [0][9][1][5][8][2] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] While in Mode 4 at 0300, it was discovered that the containment partic-
 [0][3] ulate radiation monitor had failed low, rendering it inoperable (T.S.
 [0][4] 3.4.6.1.a). Repairs were made to the unit and it was returned to ser-
 [0][5] vice at 1350. The containment gaseous radiation monitor and the con-
 [0][6] tainment sump level alarm system remained operable during the event.
 [0][7] Similar events: none.
 [0][8]

SYSTEM CODE [B][B] (11)	CAUSE CODE [E] (12)	CAUSE SUBCODE [E] (13)	COMPONENT CODE [I][N][S][T][R][U] (14)	COMP. SUBCODE [E] (15)	VALVE SUBCODE [Z] (16)
LER/RO REPORT NUMBER [17]	EVENT YEAR [8][2] (21)	SEQUENTIAL REPORT NO. [0][4][9] (24)	OCCURRENCE CODE [] (27)	REPORT TYPE [L] (30)	REVISION NO. [0] (32)
ACTION TAKEN [A] (18)	FUTURE ACTION [C] (19)	EFFECT ON PLANT [Z] (20)	SHUTDOWN METHOD [Z] (21)	HOURS [0][0][0][0] (22)	ATTACHMENT SUBMITTED [Y] (23)
				NPRD-4 FORM SUB. [Y] (24)	PRIME COMP. SUPPLIER [A] (25)
					COMPONENT MANUFACTURER [W][1][2][0] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] Troubleshooting revealed a lead had detached from a transmitter in the
 [1][1] component board assembly (Westinghouse #3365C41G). Sample pump vibration
 [1][2] may have loosened the lead. The transformer was replaced with a spare.
 [1][3] The cause may be a design deficiency of the component board assembly.
 [1][4] An update report will be submitted when more information is known.

FACILITY STATUS [D] (28)	% POWER [0][0][0] (29)	OTHER STATUS [N/A] (30)	METHOD OF DISCOVERY [A] (31)	DISCOVERY DESCRIPTION [Operator Observation] (32)
ACTIVITY RELEASED [Z] (33)	CONTENT OF RELEASE [Z] (34)	AMOUNT OF ACTIVITY [N/A] (35)		LOCATION OF RELEASE [N/A] (36)
PERSONNEL EXPOSURES NUMBER [0][0][0] (37)	TYPE [Z] (38)	DESCRIPTION [N/A] (39)		
PERSONNEL INJURIES NUMBER [0][0][0] (40)		DESCRIPTION [N/A] (41)		
LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42)		DESCRIPTION [N/A] (43)		
PUBLICITY ISSUED [N] (44)		DESCRIPTION [N/A] (45)		

09280008 820915
 PDR ADDCK 05000317
 PDR

NAME OF PREPARER G. S. Pavis/L. F. Basso PHONE: 301-269-4742/4933

U.S. NRC USE ONLY

LER NO. 82-49/3L
DOCKET NO. 50-317
LICENSE NO. DPR 53
EVENT DATE 08-16-82
REPORT DATE 09-15-82
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Troubleshooting revealed a lead had detached from the pulse developing transformer in the component board assembly (Westinghouse #3365C41G). Vibration from the sample pump is suspected to have loosened the lead. The transformer was replaced with a spare.

Investigation is continuing into the possible design/manufacturing deficiency of the component board assembly. An update report will be submitted when additional information becomes available.