

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | A | R | S | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 9 14 15 25 26 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T

0 1 | REPORT SOURCE | 5 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 2 | 7 | 0 | 8 | 1 | 1 | 1 | 8 | 2 | 8 | 0 | 9 | 0 | 7 | 8 | 2 | 9  
7 8 9 50 51 58 59 64 65 69 74 75 80 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On August 11, 1982, it was reported that tendon surveillances performed in  
0 3 | July and August, 1982, on the Reactor Building post-tensioning tendons were  
0 4 | not performed according to written procedures or the Technical Specification, in  
0 5 | that one step in the procedure was performed out of sequence. There were no  
0 6 | effects on public or plant safety, since a final lift-off's provided assurance  
0 7 | that adequate tension remained on the tendon.  
0 8 | \_\_\_\_\_  
7 8 9 30

0 9 | SYSTEM CODE | S | A | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | F | 13 | COMPONENT CODE | V | E | S | S | E | L | 14 | COMP SUBCODE | D | 15 | VALVE SUBCODE | Z | 16  
7 8 9 9 10 11 12 13 18 19 20  
17 | LEF/RO REPORT NUMBER | 8 | 2 | 21 | SEQUENTIAL REPORT NO. | 2 | 1 | 24 | OCCURRENCE CODE | 0 | 3 | 28 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32  
23 | ACTION TAKEN | Z | 18 | FUTURE ACTION | H | 19 | EFFECT OF PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | ATTACHMENT SUBMITTED | Y | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP SUPPLIER | A | 25 | COMPONENT MANUFACTURER | V | 1 | 5 | 8 | 44  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Inspecting personnel performed the test incorrectly by doing one step out of  
1 1 | sequence. The Plant Review Committee reviewed the situation and determined  
1 2 | the test was still valid, but discussed the matter with the cognizant  
1 3 | engineer.  
1 4 | \_\_\_\_\_  
7 8 9 80

1 5 | FACILITY STATUS | G | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | C | 31 | DISCOVERY DESCRIPTION | QA Inspection of Tendon Surv. | 32  
7 8 9 9 10 12 13 44 45 46 47 48 49 50

1 6 | ACTIVITY RELEASED | Z | 33 | CONTENT | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36  
7 8 9 9 10 11 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39  
7 8 9 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41  
7 8 9 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43 | 8209280099 820907 PDR ADJCK 05000312 S PDR  
7 8 9 9 10 11 12 80 81 82 83 84 85 86 87 88 89 90

2 0 | PUBLICITY ISSUED | Y | 44 | DESCRIPTION | Local newspapers and wire services. | 45 | NRC USE ONLY  
7 8 9 9 10 11 12 80 81 82 83 84 85 86 87 88 89 90

NAME OF PREPARER R. W. Colombo PHONE: (916) 452-3211