

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 0 | R | T | N | P | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 4 | 7 | 0 | 8 | 2 | 4 | 8 | 2 | 8 | 0 | 9 | 1 | 4 | 8 | 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | WITH THE PLANT IN MODE 2, 1% POWER, STS 3.5.2 WAS NOT MET WHEN THE 'B' TRAIN
03 | RHR PUMP CONTROL SWITCH WAS FOUND IN THE PULL-TO-LOCK POSITION. THE PUMP
04 | HAD BEEN LEFT IN THE PULL-TO-LOCK POSITION FOR FIVE HOURS FOLLOWING ECCS
05 | VALVE INSERVICE TESTING. ALTHOUGH THE RHR PUMP WOULD NOT HAVE STARTED ON
06 | AN ECCS ACTUATION, IT WAS AVAILABLE FOR MANUAL STARTING. THERE WAS NO
07 | EFFECT ON PLANT OR PUBLIC SAFETY SINCE THE REDUNDANT TRAIN EQUIPMENT WAS
08 | AVAILABLE AT ALL TIMES.

09 | SYSTEM CODE | S | P | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16
17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | EVENT YEAR | 8 | 2 | 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 4 | 24 | OCCURRENCE CODE | 0 | 3 | 28 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32
ACTION TAKEN | H | 18 | FUTURE ACTION | G | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | Z | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | PERSONNEL ERROR OCCURRED WHEN THE CONTROL OPERATOR DEVIATED FROM THE ECCS
11 | VALVE TESTING PROCEDURE AND DID NOT FOLLOW PLANT PROCEDURES RELATING TO SUCH
12 | PROCEDURE DEVIATIONS OR EQUIPMENT OUTAGES. THE OPERATING PERSONNEL HAVE
13 | BEEN COUNSELED REGARDING PROCEDURE DEVIATIONS. A PROCEDURE REVISION HAS
14 | BEEN INITIATED TO ALLOW SPECIFIC STEPS FOR SUCH POSSIBLE PUMP CONTROL SWITCH
15 | MANIPULATIONS DURING ECCS VALVE TESTING.

15 | FACILITY STATUS | C | 28 | % POWER | 0 | 0 | 1 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | ROUTINE TOUR BY STA | 32
16 | ACTIVITY RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

NAME OF PREPARER: Gary G. Bair (MJA) PHONE: 503/556-3713 Extension 234