

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 VTVYS 1 2 00 - 00 00 00 00 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 L 6 0 5 0 0 0 2 7 1 7 0 9 0 2 8 2 8 1 0 0 5 8 2 9
7 8 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | RHR and RHRSW systems monthly surveillance test in progress when indication on
03 | RHR 89B started to blink on and off at 2700 gpm flow rate. Indication was lost
04 | when valve was shut. RHRSW subsystem was declared inoperative and the valve was
05 | deenergized. Alternate testing was initiated per T.S. 4.5.C.3. There were no
06 | consequences to the health and safety of the public. There have been no previous
07 | reportable occurrences of this type.

08 7 8 9 80

09 C F 11 E 12 A 13 I N S T R U 14 S 15 Z 16
7 8 9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 8 2 0 2 0 0 3 I 0
7 8 21 22 23 24 26 27 28 29 30 31 32
LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

B Z Z Z 0 0 0 0 0 Y Y X I 2 0 0 0
33 34 35 36 37 40 41 42 43 44 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The valve operator was inspected. A loose wiring connection was found on the
11 | valve's limit switch resulting in the loss of position indication. The
12 | connection was tightened and indication returned. (See attached)

14 7 8 9 80

15 E 28 1 0 0 0 29 NA 30 B 31 Monthly Surveillance 32
7 8 9 10 12 13 44 45 46 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 44 45 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 0 0 0 37 Z 38 NA 39
7 8 9 11 12 13 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 0 0 0 40 NA 41
7 8 9 11 12 80
PERSONNEL INJURIES NUMBER DESCRIPTION

19 Z 42 NA 43
7 8 9 10 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 N 44 NA 45
7 8 9 10 80
PUBLICITY ISSUED DESCRIPTION

B210190029 B21005
PDR ADOCK 05000271
S PDR

NRC USE ONLY

NAME OF PREPARER J. P. Pelletier

PHONE: 802-257-7711

VTVYS1
05000271
LER 82-20/3L

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The valve operator was inspected. A loose wiring connection was found on the valve's limit switch resulting in the loss of position indication. The connection was tightened and indication returned. Further inspection of the valve revealed; the spot welds which secured the seat to the valve body had broken. During system operation the seat unscrewed itself, resulting in excessive vibration due to seat movement. This vibration could have caused the loose wiring connection. The valve was repaired and returned to service.

LER 82-20/31

POTENTIAL REPORT FORM

Date 9/2/82

Time 22.35

Technical Specification Section ~~3.5.3~~ 3.5.C.3

Plant Conditions: 100% power level

Description: (Include circumstances leading up to and resulting from the occurrence).

Monthly surveillance test in progress on RHR & RHRSW systems. Indication on RHR 898 started to blink on and off at 2700 GPM flow rate. Indication lost when valve Cause: shut. Breaker looks normal, motor looks normal. Suspect position indication lost due to heavy vibration from RHR 1918 which is believed to have broken guides.

Corrective Action Taken: Declared RHRSW subsystem INOP and initiated alternate testing per TS specification.

Reported By [Signature]
Repair Dept. Head [Signature]
Shift Supervisor T. Houghton

ESS Recommendation: RO
 Fire 1. 24 Hour 2. 30 Day
 NPDES Noncompliance 3. Not Reportable
 Potential 10 CFR 21 Richard D. Lagodini 9-3-82
ESS Date

Attach supporting analysis in the event the condition is determined not to be reportable.

Approved [Signature] Plant Manager 9/8/82 Date