

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	0	H	D	B	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
8		9 LICENSEE CODE 14						15 LICENSE NUMBER 25						26 LICENSE TYPE 30				57 CAT 58									

CON'T

0	1	L	6	0	5	0	0	0	3	4	6	7	0	9	0	9	8	2	8	1	0	0	7	8	2	9
7		8		60 REPORT SOURCE 61						68 DOCKET NUMBER				69 EVENT DATE 74				75 REPORT DATE 80								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

① ② (NP-33-82-51) On 9/8/82 at 1908 hours, operators received a high decay heat (DH) flow alarm. The DH flow indicator for DH Pump 2 read >4200 gpm. It was verified that DH Pump 2 was not running. High pressure injection (HPI) flow indication for HPI Pump 2 also showed high flow with no pump running. HPI and LPI/DH flow indication for Train 2 was declared inoperable, and the station entered the action statement of Technical Specification 3.5.2. There was no danger to the health and safety of the public or station personnel. Both trains were still capable of injecting water.

0	9	C	F	E	X	I	N	S	T	R	U	P	Z	
7		8		9 SYSTEM CODE 10		11 CAUSE CODE 12		13 CAUSE SUBCODE 14		15 COMPONENT CODE 16			17 COMP. SUBCODE 18 VALVE SUBCODE 19	

17	8	2	0	4	6	0	3	L	0	8	2
7		8		21 LER/RO REPORT NUMBER 22		23 EVENT YEAR 24		25 SEQUENTIAL REPORT NO. 26		27 OCCURRENCE CODE 28	

A	X	Z	Z	0	0	0	0	Y	Y	N	L	0	4	5	
33		34		35		36		37		38		39		40	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

① ⑤ The -24 VDC power supply for the buffer cards failed causing the indication to fail high. The cause of the power supply failure is unknown at this time. The power supply was replaced under MWO IC-414-82. HPI and LPI Train 2 flow indication was declared operable at 1544 hours on 9/9/82, removing the station from the action statement. The power supply will be returned to the manufacturer for failure analysis.

1	5	E	0	4	0	NA	A	Operator observation	
7		8		9 FACILITY STATUS 10		11 % POWER 12		13 OTHER STATUS 14	

1	6	Z	Z	NA	NA	NA	
7		8		9 ACTIVITY CONTENT 10		11 RELEASED OF RELEASE 12	

1	7	0	0	0	Z	NA	
7		8		9 PERSONNEL EXPOSURES NUMBER 10		11 TYPE 12	

1	8	0	0	0	NA		
7		8		9 PERSONNEL INJURIES NUMBER 10		11 DESCRIPTION 12	

1	9	Z	NA				
7		8		9 LOSS OF OR DAMAGE TO FACILITY TYPE 10		11 DESCRIPTION 12	

2	0	N	NA	8210190261	821007	PDR	ADOCK	05000346	S	PDR	
7		8		9 PUBLICITY ISSUED DESCRIPTION 10		11 NRC USE ONLY		12			

DVR 82-102 NAME OF PREPARER Tom Isley PHONE (419) 259-5000, Ext. 230

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-82-51

DATE OF EVENT: September 8, 1982

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Low Pressure Injection (LPI) and High Pressure Injection (HPI) Train 2 Flow Indication Failed High

Conditions Prior to Occurrence: The unit was in Mode 1 with Power (MWT) = 1109 and Load (Gross MWE) = 343.

Description of Occurrence: At 1908 hours on September 8, 1982, the operators received a high decay heat (DH) flow alarm, and the DH flow indicator for DH Pump 2 showed > 4200 gpm. The operator verified that DH Pump 2 was not running. The operator also observed the HPI flow indication for HPI Pump 2 showed high flow with no pump running. An initial check showed the -24 VDC buffer card power supply in the essential metering cabinet had zero output. The HPI and LPI/DH for ECCS train 1-2 was declared inoperable, and the station entered the action statement of Technical Specification 3.5.2.

Designation of Apparent Cause of Occurrence: The -24 VDC power supply for the buffer cards failed causing the indication to fail high. The cause of the power supply failure is unknown at this time.

Analysis of Occurrence: There was no danger to the health and safety of the public or station personnel. Only the indication for HPI and DH Train 2 was inoperable as the HPI/LPI system would have started on an SFAS signal. In addition, Train 1 of ECCS was operable and would have provided injection water.

Corrective Action: The -24 VDC power supply was replaced under Maintenance Work Order IC-414-82. HPI and LPI flow 1-2 indication was declared operable at 1544 hours on September 9, 1982, removing the station from the action statement of Technical Specification 3.5.2. The power supply is being returned to the manufacturer, Lambda Electronics for failure analysis.

Failure Data: Previous similar occurrences of the loss of HPI Train 2 flow indication have been reported in Licensee Event Reports NP-33-81-10 (81-011) and NP-33-81-30 (81-027).

LER #82-046