

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D C C 1 | 2 | 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | 3 | 4 1 1 1 1 | 4 | _____ | 5
 7 8 9 14 15 25 26 57 58 59

CON'T
 0 1 | REPORT SOURCE | L | 6 | 0 5 | 0 0 0 0 3 1 1 5 | 7 | 0 9 | 1 2 8 2 | 8 | 1 0 1 2 8 2 | 9
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | ON SEPT. 12, 1982, AN UNPLANNED GAS RELEASE WAS DETECTED BY AN ELEVATED UNIT 1
 0 3 | VENT STACK GASEOUS MONITOR (R-26) READING. THIS EVENT CONTINUED FOR ABOUT
 0 4 | 1.75 HOURS. A TOTAL OF 1.657 Ci WAS RELEASED AT A RATE OF 1.905 E-4 Ci/SEC, WHICH
 0 5 | IS 0.3% OF THE TECH SPEC LIMIT. THE MAXIMUM RELEASE RATE WAS 5.64 E-3 Ci/SEC,
 0 6 | WHICH IS 9.5% OF THE TECH SPEC LIMIT. THIS RELEASE OCCURRED WITHOUT THE SAMPLING
 0 7 | AND ANALYTICAL REQUIREMENTS OF TECH SPEC APPENDIX B, 2.4.4.E.
 0 8 | _____

0 9	M A	X	Z	Z Z Z Z Z Z Z	Z	Z		
7 8	9 10	11	12	13	14	15	16	

17	8 2		0 8 4		0 4	L		0
21	22	23	24	25	26	27	28	29

X	Z	Z	Z		N	N	Z	Z 9 9 9
33	34	35	36	37	40	41	42	43

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | THE RELEASE OCCURRED WHEN VENTING U-2 PRT. IT WAS INITIALLY BELIEVED THAT THE
 1 1 | RELEASE WAS DUE TO BAD SEALS ON THE "S" WASTE GAS COMP. IT WAS LATER FOUND THAT
 1 2 | A LEAK EXISTED ON THE WASTE GAS O₂ ANALYZER WHICH MAY HAVE CONTRIBUTED TO THE
 1 3 | RELEASE. THE LEAKS WERE REPAIRED. NO FURTHER ACTION IS PLANNED.
 1 4 | _____

1 5 | E | 1 0 0 | NA | A | RADIATION MONITORING ALARM
 7 8 9 10 11 12 13 30 31 32

1 6 | G | N | 1.657 CI of XE-133 | AUX. BUILDING TO PLANT VENT
 7 8 9 10 11 12 13 35 36

1 7 | 0 0 0 0 | Z | NA
 7 8 9 10 11 12 13 37 38 39

1 8 | 0 0 0 0 | NA
 7 8 9 10 11 12 13 40 41

1 9 | Z | NA
 7 8 9 10 11 12 13 42 43

2 0 | N | NA
 7 8 9 10 11 12 13 44 45

NAME OF PREPARER C. E. Murphy PHONE 616-465-5901

8210190342 821012
 PDR ADOCK 05000315
 S PDR