NRC FOR (7-77)	M 366 U. S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT
	CONTROL BLOCK:
	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T	REPORT L 6 0 5 0 - 0 3 2 5 7 1 0 0 1 8 2 8 1 0 1 1 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During an evaluation of the orientation of snubbers and struts inside the drywell,
03	it was determined that the tailpipe for SRV . 'Ol3H could possibly fail during a
0 4	seismic event. Due to the ease of the required fix, additional analysis to remove
0 5	the conservatisms, which may prove it to be an LTF, will not be performed. The
06	corresponding pipe on Unit No. 2 is satisfactory. This event did not affect the
07	health or safety of the public.
08	Technical Specification 6.9.1.8i
09 7 8	SYSTEM CODE S H 10 CAUSE CODE SUBC
10	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
11	was added where the tailpipe passes through the deflector plate. The remaining
12	piping located in the drywell has been evaluated and no other problems were identified.
1 3	
14	9
	G O
	AND IN THE CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 2 (3) (2 (34) NA (44) (45) (10) (10) (10) (10) (10) (10) (10) (10
17 78	NUMBER TYPE DESCRIPTION (39) 9 9 11 12 13 NA 9 PERSONNEL IN JUBIES 13 80
18	
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
19	Z 42 B210190674 B21011 B210190674 B21019074
20	
7 8	9 10 NAME OF PREPARER R. M. Poulk, Jr. PHONE 919-457-9521 0