

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 0 | R | T | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T  
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 4 | 7 | 0 | 9 | 1 | 8 | 8 | 2 | 8 | 1 | 0 | 1 | 1 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING NORMAL PLANT OPERATION, STEAM PRESSURE TRANSMITTER PT-524 on 'B'  
03 | STEAM GENERATOR FAILED HIGH CAUSING ITS ASSOCIATED PROTECTION SYSTEM BIGTABLE  
04 | TO TRIP AND ITS PRESSURE COMPENSATED STEAM FLOW INSTRUMENT FI-522 TO FAIL  
05 | HIGH. THIS RESULTED IN VIOLATION OF ESF INSTRUMENTATION CHANNEL OPERABILITY  
06 | REQUIRED BY TECHNICAL SPECIFICATION 3.3.2.1. THERE WAS NO EFFECT ON PLANT  
07 | OR PUBLIC SAFETY. THE REDUNDANT PRESSURE TRANSMITTERS WERE OPERABLE AT THE  
08 | TIME OF THE FAILURE.

09 | SYSTEM CODE: C | C | 11 | CAUSE CODE: X | 12 | CAUSE SUBCODE: Z | 13 | COMPONENT CODE: I | N | S | T | R | U | 14 | COMP SUBCODE: T | 15 | VALVE SUBCODE: Z | 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | THE CAUSE HAS NOT BEEN DETERMINED. REACTOR TRIP AND SAFETY INJECTION BISTABLES  
11 | AFFECTED BY THE FAILED TRANSMITTER WERE PLACED IN THE "TRIPPED" CONDITION  
12 | WITHIN 45 MINUTES. THE TRANSMITTER WAS OPERATING NORMALLY WHEN TROUBLE-  
13 | SHOOTING WAS INITIATED; IT WAS SHORTLY THEREAFTER RETURNED TO SERVICE. THE  
14 | MANUFACTURER IS STUDYING THE SITUATION TO DETERMINE A POSSIBLE FAILURE CAUSE.

15 | FACILITY STATUS: E | 28 | % POWER: 1 | 0 | 0 | 29 | OTHER STATUS: NA | 30 | METHOD OF DISCOVERY: A | 31 | DISCOVERY DESCRIPTION: OPERATOR OBSERVATION | 32

NAME OF PREPARER Gary G. Bair (WON )

PHONE: 503/556-3713  
Extension 234