

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | D | C | C | N | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 57 CAT 58

CON'T
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 7 | 7 | 0 | 9 | 1 | 3 | 8 | 2 | 8 | 1 | 0 | 1 | 1 | 3 | 8 | 2 | 9
7 8 60 61 66 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | During normal power operation at 1025 and again on 9-20-82 at 1000 while
03 | performing a surveillance test, No. 11 emergency diesel generator failed
04 | to achieve the required 900 RPM within 10 seconds (T.S. 3.8.1.1.b). The
05 | diesel was repaired and tested satisfactorily both times. The other
06 | emergency diesel generators remained operable during the events.
07 | Similar events: none.
08 | _____

09 | SYSTEM CODE: EE (11) CAUSE CODE: X (12) CAUSE SUBCODE: Z (13) COMPONENT CODE: ZZZZZZ (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)
17 | LER/RO REPORT NUMBER: 82 (21) SEQUENTIAL REPORT NO.: 052 (24) OCCURRENCE CODE: 03 (28) REPORT TYPE: L (30) REVISION NO.: 0 (32)
ACTION TAKEN: F (33) FUTURE ACTION: Z (34) EFFECT ON PLANT: Z (35) SHUTDOWN METHOD: Z (36) HOURS: 0000 (40) ATTACHMENT SUBMITTED: Y (41) NPRD-4 FORM SUB.: N (42) PRIME COMP. SUPPLIER: Z (43) COMPONENT MANUFACTURER: Z999 (44)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | Investigation revealed both start failures were caused by a loose con-
11 | nector on speed switch 0-SS-4848 (Synchro Start Products, Model GT-2N),
12 | though the first failure was mistakenly attributed to a loose lead on
13 | speed switch 0-SS-4847. The connector was tightened and lock-wired to
14 | prevent recurrence. The other diesels' connectors were properly tight.

15 | FACILITY STATUS: E (28) % POWER: 100 (29) OTHER STATUS: N/A (30) METHOD OF DISCOVERY: (31) DISCOVERY DESCRIPTION: (32)

16 | ACTIVITY CONTENT RELEASED OF RELEASE: Z (33) Z (34) AMOUNT OF ACTIVITY: N/A (35) LOCATION OF RELEASE: N/A (36)

17 | PERSONNEL EXPOSURES NUMBER: 000 (37) TYPE: Z (38) DESCRIPTION: N/A (39)

18 | PERSONNEL INJURIES NUMBER: 000 (40) DESCRIPTION: N/A (41)

19 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: N/A (43)

20 | PUBLICITY ISSUED DESCRIPTION: N (44) DESCRIPTION: N/A (45)

8210250160 821013
PDR ADOCK 05000317
S PDR

NRC USE ONLY

LER NO. 82-52/3L
DOCKET NO. 50-317
LICENSE NO. DPR 53
EVENT DATE 09-13-82
REPORT DATE 10-13-82
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

While troubleshooting the event of September 13, 1982, an electrician found a loose wire from the overspeed trip speed switch, O-SS-4847. Suspected cause of the loose wire is vibration from the diesel engine and possibly an improperly crimped lug. The loose lead was repaired and the diesel tested satisfactorily.

On September 20, 1982, the diesel exhibited a similar problem. Investigation revealed a loose threaded connector on speed switch O-SS-4848 (Synchro Start Products, Model GT-2N), adjacent to O-SS-4847, caused the diesel start failure. The loose connector is also suspected to have caused the first event, because circuit analysis shows a loose lead on O-SS-4847 would not have caused the described failure.

While the electrician worked on O-SS-4847 on September 13, 1982, he may have adequately made up the contacts of the loose connector to O-SS-4848 resulting in a satisfactory post maintenance test.

The cause of the connector loosening is believed to be the high vibration from the diesel engine. A method has been developed to lock-wire the field connector to the body of the speed switch to prevent recurrence. The switches on emergency diesel generators #12 and 21 have been checked and are properly tight. The switch on diesel #21 has been lock-wired. The one on #12 is scheduled for other maintenance and will be lock-wired as part of this work.