

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 11LLSC1 | 200-000000-00 | 341000 | 4 | _____ | 5

CONT
01 | REPORT SOURCE: L | 605000373 | 70911682 | 8101582 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | _____
03 | On September 16, 1982 at 1700 hours during the performance of LIS-NB-01 the
04 | setpoint for DPIS-1B21-N024B, Rx vessel low water level scram, was found out
05 | of calibration. Technical Specification limits contained in Table 3.3.2-2.A.1
06 | were exceeded in the nonconservative direction. RPS Rx vessel low level scram
07 | remained operable due to redundant switches DPIS-1B21-N024 A, C, D. being within
08 | calibration limits.

09 | SYSTEM CODE: IA (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: E (13) | COMPONENT CODE: INSTRU (14) | COMP. SUBCODE: S (15) | VALVE SUBCODE: Z (16)

17 | LER/RO REPORT NUMBER: _____ | EVENT YEAR: 82 (21) | SHUTDOWN METHOD: _____ (23) | SEQUENTIAL REPORT NO.: 102 (24) | OCCURRENCE CODE: 03 (28) | REPORT TYPE: L (30) | REVISION NO.: 0 (32)

18 | ACTION TAKEN: E (33) | FUTURE ACTION: Z (34) | EFFECT ON PLANT: Z (35) | SHUTDOWN METHOD: Z (36) | HOURS: 0000 (40) | ATTACHMENT SUBMITTED: Y (41) | NPD-4 FORM SUB.: N (42) | PRIME COMP. SUPPLIER: A (43) | COMPONENT MANUFACTURER: B080 (47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | _____
11 | The cause for this Instr. being out of calibration is attributed to Instr. Drift
12 | Revision is in progress to change the required tolerance as specified for these
13 | instr. in LIS-NB-01. AIR 1-1-82-512 was initiated to track the completion of this
14 | revision. Instr. will be calibrated weekly till problem is resolved.

15 | FACILITY STATUS: B (28) | % POWER: 014 (29) | OTHER STATUS: NA (30) | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION: LIS-NB-01 (32)

16 | ACTIVITY CONTENT RELEASED OF RELEASE: Z (33) | AMOUNT OF ACTIVITY: NA (35) | LOCATION OF RELEASE: NA (36)

17 | PERSONNEL EXPOSURES NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION: NA (39)

13 | PERSONNEL INJURIES NUMBER: 000 (40) | DESCRIPTION: NA (41)

19 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) | DESCRIPTION: NA (43)

20 | PUBLICITY ISSUED: N (44) | DESCRIPTION: NA (45)

8210250163 821015
 PDR ADOCK 05000373
 S PDR

NRC USE ONLY

NAME OF PREPARER: Dale Winterhoff

PHONE: *815) 357-6761

- I. LER NUMBER: 82-102/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 50-373
- IV. EVENT DESCRIPTION:

On September 16, 1982 at 1700 hours during the performance of LIS-NB-01 by the Instr. Maint. Dept., DPIS-1B21-N024B setpoint for Rx vessel low water level scram was found out of calibration. Technical Specification limits contained in Table 3.3.2-2.A.1 were exceeded in the non-conservative direction.

V. PROBABLE CONSEQUENCES:

At the time of the occurrence LaSalle Unit 1 was operating at 14% power level. The Reactor Protection System Reactor Vessel Low Level Scram was operable due to redundant switches DPIS-1B21-N024A, C, D being within calibration limits. Safe operation of the plant was maintained at all times.

VI. CAUSE:

The cause for this instrument being out of calibration in the nonconservative direction is attributed to instrument drift.

VII. CORRECTIVE ACTION:

The Instr. Maint. Dept. immediately recalibrated DPIS-1B21-N024B within allowable specifications by 1840 hours. A revision is in progress to LIS-NB-01 to change the tolerance setpoint from 12.5" - 0.0", + 1.27" to 12.5" - 0.0, + 2.54". Action Item Record 1-1-82-512 has been initiated to verify completion of this revision. The Instr. Maint. Dept. will place this on trend analysis program.

Prepared by: Dale Winterhoff

Dale R Winterhoff