

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

JUN 9 1994

License: 05-17401-01 Docket: 030-12693

GTG-Fox Geotechnical Services, Ltd. ATTN: J. Craig Vaughn, President 4765 Independence Street

Wheat Ridge, Colorado 80033

SUBJECT: RESPONSE TO NRC INSPECTION REPORT 030-12693/94-01

Thank you for your letter of May 17, 1994, in response to our letter and attached Notice of Violation both dated April 19, 1994. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine whether full compliance has been achieved and will be maintained.

Sincerely,

Charles Z. Coly

Charles L. Cain, Chief Nuclear Materials Inspection Branch

cc: Colorado Radiation Control Program Director

9406150040 940609 PDR ADDCK 03012693 C PDR

JEOT!

bcc:
DMB - Original (IE-07)
SJCollins
RAScarano
CLCain
Dweiss, OC/LFDCB (4503)
WLFisher
MLMcLean
NMIB
MIS System
RIV Files (2)

RIV:NMIB	AC:NMIBULC	
MLMcLean mym	CLCain	
06/8/94	06/8/94	

bcc:
DMB - Original (IE-07)
SJCollins
RAScarano
CLCain
Dweiss, OC/LFDCB (4503)
WLFisher
MLMcLean
NMIB
MIS System
RIV Files (2)

RIV:NMIB	AC: NMIBULC	
MLMcLean Mym	CLCain	
06/8/94	06/8/94	



SOILS & FOUNDATION ENGINEERS
CONSTRUCTION MATERIALS TESTING LABORATORY

20

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

Subject:

Reply to Notice of Violation, Docket: 030-12693, License: 05-17401-1

Gentlemen:

In response to your notice of violation dated April 19, 1994, we are submitting the following explanation of the reason for the violation, the corrective steps taken, and the program in-place to prevent further violations of this type.

This violation occurred as the result of inaccurate record keeping on the part of my predecessor in the position of Radiation Safety Officer. In March of 1993, I assumed the position of Radiation Safety Officer. At that point in time, I began to organize the records so that accurate tracking of each gauge's maintenance, leak testing and usage was accomplished. This included inventories performed every six (6) months as required by our license. It was during the October 1993 inventory that I discovered Troxler gauge number T3418255 was not on the inventory and had not been leak tested with the other gauges during that round of testing. I immediately placed that gauge on our inventory and performed the wipe test which I sent off for leak testing. The results of that test and the subsequent test have been nil.

To prevent a repeat of this occurrence, wipe testing for the leak test and gauge inventory are performed concurrently to ensure that all gauges in inventory are tested. This is performed at a maximum time interval of six (6) months between tests. Additionally, any transfers of gauges are noted in the inventory at the time of transfer so that the inventory is accurate at all times.

We achieved compliance on November 15, 1993.

Should you have any questions regarding this or other matters, please call.

Very truly yours,

GTG-FOX GEOTECHNICAL SERVICES, LTD.

James 6 Blanklewsky

James C. Blankenship, P.G. Radiation Safety Officer

Radiation Safety Officer

JCB/mjm/DCN D0316.94

ce: Regional Administrator

4405250184

DENVER OFFICE 4765 Independence Street Wheat Ridge, CO 80033 (303) 424-5578

94-1080

BOULDER OFFICE 5763 Arapahoe Ave., Unit L Boulder, Colorado 80303 (303) 447-9008