

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A S E S I 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 [ ] [ ] 5

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 8 7 7 0 9 1 6 8 2 8 1 0 1 4 8 2 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During startup testing while cleaning the CRD suction strainers, the CRD pumps
0 3 tripped off, due to low suction pressure. Repeated attempts to start either
0 4 pump failed. Two accumulator low pressure alarms were received in less than
0 5 10 minutes. Action statement 3.1.3.5.6.2 was entered and the mode switch
0 6 placed in shutdown. This is reportable per 6.9.1.9.b.
0 7
0 8

0 9 SYSTEM CODE C B 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 2 18 ACTION TAKEN X 19 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD B 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The CRD pump tripped on low suction pressure due to pressure fluctuations from
1 1 a cycling condensate reject valve. The pressure changes were normally dampened
1 2 by the CRD suction strainers. The CRD low pressure suction trip logic was
1 3 modified with a time delay which prevents pump trip due to the above cause.
1 4

1 5 FACILITY STATUS B 28 % POWER 0 0 0 29 OTHER STATUS n/a 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION operator observation 32

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY n/a 35 LOCATION OF RELEASE n/a 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION n/a 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION n/a 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION n/a 43

2 0 PUBLICITY ISSUED N 44 DESCRIPTION n/a 45 NRC USE ONLY [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]
NAME OF PREPARER D.G. Mitchell PHONE: (717) 542-2181 X524