

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1)
(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 8 9 14 15 25 26 30 37 40 57 58 59
0 1 | A | R | A | N | O | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5
8 9 14 15 25 26 30 37 40 57 58 59

CONT
7 8 9
0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 8 | 7 | 0 | 9 | 1 | 8 | 8 | 2 | 8 | 1 | 0 | 1 | 5 | 8 | 2 | 9
60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | On 9/18/82, with the reactor defueled, four electrical cables were found
0 3 | to be pulled through a fire curtain. This occurrence was discovered during
0 4 | a routine quality control (QC) inspection. These cables had been used for
0 5 | a station battery capacity test, but a fire watch had not been established
0 6 | as required by T.S. 3.7.11.a. This occurrence is reportable per
0 7 | T.S. 6.9.1.9.b.
0 8 | _____
7 8 9 80

7 8 9
0 9 | A | B | 11 | A | 12 | C | 13 | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16 |
9 10 11 12 13 18 19 20
17 | L | E | R | R | O | R | E | P | O | R | T | N | U | M | B | E | R | 8 | 1 | 2 | 21 | 22 | 0 | 1 | 2 | 1 | 9 | 23 | 24 | 25 | 0 | 1 | 3 | 26 | 27 | L | 28 | 29 | 30 | 31 | 0 | 32 |
33 34 35 36 37 40 41 42 43 44 47
18 | H | 18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9 | 26 |
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The personnel performing the test did not realize that the opening in the
1 1 | wall had a fire curtain. It appeared that the opening was to provide vent
1 2 | tilation for the battery room. Also, the opening for the other battery
1 3 | room has a grille over the opening, whereas the one relative to this
1 4 | occurrence did not. The cables were left overnight without a fire watch,
7 8 9 80

(Continued on attachment)
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | QC Inspection | 32
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
1 9 | Z | 42 | NA | 43
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
2 0 | N | 44 | NA | 45
7 8 9 10 11 12 13 20 21 22 23 24 25 26 30 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER: Patrick Rogers PHONE: 501/964-3100

8210260123 821015
PDR ADOCK 05000368
S PDR

ATTACHMENT

LER NO. 50-368/82-029/03L-0

Cause Description and Corrective Actions (Continued)

but the cables were removed the next morning as soon as the error was discovered. Electrical maintenance personnel who performed the battery test received a review of this occurrence and were advised to maintain a fire watch when using this opening for cable routing while conducting the battery test. The opening in the wall has been marked to indicate the presence of a fire curtain. The addition of a penetration to allow battery testing without fire barrier degradation is being considered. Also, the existing job controls will be examined to determine the most appropriate corrective actions with regard to field controls for jobs involving fire curtains.