	CONTROL BLOCK: []] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	T N S N P 1 200 0 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T	REPORT L 6 0 5 10 10 10 13 12 17 7 10 13 12 11 8 3 8 0 14 1 9 8 13 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	With unit 1 in mode 1 (30% Rx power) at 0918 CST on 03/21/83, the turbine building
0 3	sump liquid effluent line radiation monitor was declared inoperable due to a leak
0 4	in the pump. This required entry into action statement 32 of LCO 3.3.3.9. There
0 5	was no effect upon public health and safety. Previous occurrences - one
06	(SQRO-50-327/81066).
0 7	
0 8	
0 9	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21. 22 23 24 26 27 28 29 30 31 31 32 32 32 33 30 31 32 32 32 33 30 31 32 32 33 33 34 33 35 36 37 40 41 23 N 24 125 D 0 6 5
10	Investigation revealed that the leaking pump was due to the Deaus Brothers pump
11	casing eroded resulting in a hole in the casing. This was caused by high pH levels
12	in the sump. A neutralization system is being added to reduce pH levels and prevent
13	recurrence. For immediate corrective action, the pump was replaced and operation
1,4	verified at 1214 CST on 03/24/83.
7 8	ALILITY SPOWER OTHER STATUS (JI) METHOD OF DISCOVERY DESCRIPTION (J2) E (J8) [0 3 0 (29) NA B (31) Operator observation STIVITY CONTENT 12 17 44 45 46 LEASED OF RELEASE AMOUNT OF ACTIVITY (J2) LOCATION OF RELEASE (J6)
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (30) NA 44 45
18	PERSONNEL INJURIES 13 NUMBER DESCRIPTION (1) 0 0 0 (40) NA
ान ।	OSS OF OR DAMAGE TO FACILITY (43) Z (42) NA
20 1	PUBLICITY SUED DESCRIPTION (15) NA S PDR B304260350 B30419 PDR ADDCK 05000327 S PDR
	Name of Preparer: H. R. Rogers /M. R. Harding