

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [G] [A] [E] [I] [H] [1] [2] [0] [0] [-] [0] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] (5)

CON'T [0] [1] REPORT SOURCE [L] [6] [0] [5] [0] [0] [0] [0] [3] [2] [1] [7] [0] [3] [1] [2] [8] [3] [8] [0] [4] [0] [7] [8] [3] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On 3/12/83, personnel smelled smoke around the 1H11-P609 panel in the control room. Shift personnel discovered smoke coming from the 1C71-K6C low reactor water level RPS relay. Unit 1 received a 1/2 scram as a result of the relay burning & failing in the safe condition. T.S. table 3.1-1 requires 2 channels per trip system be operable. The low reactor water level RPS relays in the "B" system were operable. The health & safety of the public were not affected by this non-repetitive event.

[0] [9] SYSTEM CODE [I] [A] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [R] [E] [L] [A] [Y] [X] (14) COMP. SUBCODE [A] (15) VALVE SUBCODE [Z] (16)

[1] [0] CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of this event has been attributed to component failure. The 1C71-K6C low reactor water level RPS relay was replaced. The new relay was satisfactorily functionally tested and returned to operable status.

[1] [5] FACILITY STATUS [E] (28) % POWER [0] [9] [4] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [A] (31) DISCOVERY DESCRIPTION [Operator Observation] (32)

[1] [6] ACTIVITY CONTENT [Z] (33) [Z] (34) AMOUNT OF ACTIVITY [NA] (35) LOCATION OF RELEASE [NA] (36)

[1] [7] PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION [NA] (39)

[1] [8] PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION [NA] (41)

[1] [9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43)

[2] [0] ISSUED DESCRIPTION [N] (44) DESCRIPTION [NA] (45)

NAME OF PREPARER S. B. Tipps PHONE: (912) 367-7851

8304260363 830407 PDR ADOCK 05000321 S PDR

NRC USE ONLY

GPO 917-925

NARRATIVE REPORT  
FOR LER 50-321/1983-033

LICENSEE : GEORGIA POWER COMPANY  
FACILITY NAME : EDWIN I. HATCH  
DOCKET NUMBER : 50-321

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9.b. due to event's showing that the unit was not meeting requirements of Tech. Specs. table 3.1-1, item 6.

Plant conditions at the time of the event(s):

This event occurred on 3/12/83 with reactor power at 2288 MWt (94%).

Detailed description of the event(s):

On 3/12/83, personnel smelled smoke around the 1H11-P609 panel in the control room. Shift personnel immediately began looking for the cause and discovered smoke coming from the 1C71-K6C low reactor water level RPS relay.

Consequences of the event(s):

Unit 1 received a 1/2 scram as a result of the relay burning and failing in the tripped (i.e., safe) condition.

Status of redundant or backup subsystems and/or systems:

The low reactor water level RPS relays in the "B" trip system were operable.

Justification for continued operation:

The defective relay was replaced. The new relay was satisfactorily functionally tested and returned to operable status on 3/12/83.

If repetitive, number of previous LER:

This event is non-repetitive.

Impact to other systems and/or Unit:

This event had no impact to other systems on Unit 1 or to Unit 2.

Cause(s) of the event(s):

The cause of this event was component failure due to the burning and failure of the 1C71-K6C low reactor water level relay.

Narrative Report for LER 50-321/1983-033  
Page Two

Immediate Corrective Action:

Control Room personnel extinguished the burning relay. The defective relay was replaced. The new relay was functionally tested and returned to operable status.

Supplemental Corrective Action:

No supplemental corrective action is required.

Scheduled (future) corrective action:

There is no scheduled future corrective action required.

Action to prevent recurrence (if different from corrective actions):

No further action is required.