

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOC 1: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | C | R | P | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | _____ | 5

LICEN E CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

CCNT

0 1 | R | T | S | R | C | E | L | 3 | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 7 | 0 | 3 | 1 | 8 | 8 | 3 | 8 | 0 | 4 | 1 | 5 | 8 | 3 | 9

REPORT SOURCE 61 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1045, during normal plant operation, the 175' wind speed meteorological

0 3 | monitoring instrumentation was discovered inoperable (T.S. 3.3.3.4). Main-

0 4 | tenance was initiated and operability restored at 1700 on March 20, 1983.

0 5 | This is the fifth report for the 175' wind speed meteorological monitoring

0 6 | instrumentation and the twenty-eighth report under T.S. 3.3.3.4.

0 7 | _____

0 8 | _____

0 9 | SYSTEM CODE I F (11) CAUSE CODE C (12) CAUSE SUBCODE B (13) COMPONENT CODE INSTRU (14) COMP. SUBCODE E (15) VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER 8 3 (21) EVENT YEAR 8 3 (22) SEQUENTIAL REPORT NO. 0 1 1 5 (24) OCCURRENCE CODE 0 3 (28) REPORT TYPE L (30) REVISION NO. 0 (32)

ACTION TAKEN A (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED Y (23) NPRO-4 FORM SUB. N (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER C 4 1 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cup assembly had evidently been broken during a weather disturbance.

1 1 | The assembly was replaced and operability restored after testing satisfac-

1 2 | torily.

1 3 | _____

1 4 | _____

1 5 | FACILITY STATUS E (28) % POWER 0 9 3 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION Operator Observation (32)

1 6 | ACTIVITY CONTENT Z (33) RELEASED OF RELEASE Z (34) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION NA (39)

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION NA (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION NA (43)

2 0 | PUBLICITY ISSUED N (44) DESCRIPTION NA (45)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER J. L. Bufe' PHONE: (904) 795-6486

830426047B 830415
PDR ADDCK 05000302
S PDR

SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/83-015/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: April 15, 1983

OCCURRENCE DATE: March 18, 1983

IDENTIFICATION OF OCCURRENCE:

The 175 foot wind speed meteorological monitoring instrumentation was inoperable. This monitoring instrumentation is required to be operable by Technical Specification 3.3.3.4.

CONDITIONS PRIOR TO OCCURRENCE:

MODE 1 (93% FULL POWER)

DESCRIPTION OF OCCURRENCE:

At 1045 on March 18, 1983, during normal operation, operators noticed that the 175 foot wind speed indicator was reading zero. The wind speed sensor was checked and found to be broken. The sensor was replaced and satisfactorily tested at 1700 on March 20, 1983.

DESIGNATION OF APPARENT CAUSE:

The cup assembly on the wind speed sensor was apparently broken during a weather disturbance.

ANALYSIS OF OCCURRENCE:

No unplanned radiological release was made while the instrument was inoperable. Backup data can be acquired through pre-established means from the National Weather Service should the need arise.

CORRECTIVE ACTION:

The broken cup assembly was replaced and the wind speed monitor was tested satisfactorily.

FAILURE DATA:

This is the fifth time the 175 foot wind speed monitor has failed and the twenty-eighth report under Technical Specification 3.3.3.4.