

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | 1 | | | | | | | | 11
1 6 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 | 0 | 1 | 8 | 9 | A | R | A | N | O | 1 | 12 | 10 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 13 | 14 | 1 | 1 | 1 | 1 | 1 | 14 | 1 | 1 | 15
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

7 | 0 | 1 | 8 | REPORT | L | 16 | 10 | 5 | 0 | 0 | 0 | 3 | 1 | 3 | 17 | 10 | 3 | 2 | 1 | 8 | 3 | 18 | 10 | 4 | 1 | 9 | 8 | 3 | 19
SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
| 0 | 2 | 1 On 3/21/83, during refueling shutdown, Reactor Coolant (RC) Pressure Transmitter PT-1023 was found to be out of
| 0 | 3 | 1 tolerance during the Reactor Protective System (RPS) Channel 'B' calibration. PT-1023 was found to be 2.3 psi
| 0 | 4 | 1 low at 0% (1700 psi) and 6.6 psi low at 100% (2500 psi). If linear regression is used to calculate the error
| 0 | 5 | 1 lat the RPS trip setpoints, the low pressure trip would have occurred at 1802.84 psi, instead of 1800 psi, and
| 0 | 6 | 1 | the high pressure trip would have occurred at 2305.5 psi instead of 2300 psi. This would result in a conserva-
| 0 | 7 | 1 | tive actuation for the low pressure trip, but a nonconservative actuation for the high pressure trip. This
| 0 | 8 | 1 | occurrence is reportable per Technical Specification 6.12.3.2.a. Occurrences related to instrument drift were
7 | 9 | 8 | 9

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE
9 1 A 11	1 E 12	1 E 13	1 I N S I T R U 14	1 T 15	1 Z 16
10	11	12	13 18	19	20

LER/RO REPORT NUMBER	EVENT YEAR	CAUSE CODE	SEQUENTIA REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO		
17	1 8 3 1	1 - - 1	1 0 0 6 1	1 / 1	1 0 3 1	1 L 1	1 - - 1	1 0 1
	1 21 22	23	24 26	27	28 29	30	31	32

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
1 E 18	1 Z 19	1 Z 20	1 Z 21	1 0 0 0 0 22	1 Y 23	1 Y 24	1 N 25	1 R 3 6 9 26
33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
| 1 | 0 | 1 The cause of the occurrence was instrument drift. PT-1023 was adjusted to within the specifications of the RPS
| 1 | 1 | 1 Channel calibration procedure. All RPS instrumentation has been calibrated and tested during the refueling
| 1 | 2 | 1 shutdown. PT-1023 is a model 1152GP manufactured by Rosemount.
| 1 | 3 | 1
| 1 | 4 | 1

FACILITY STATUS | 1 | H | 28 | 10 | 0 | 0 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | 1 | B | 31 | DISCOVERY DESCRIPTION | Routine Surveillance | 32
9 | 10 | 12 | 13 | 44 | 45 | 46 | 80

ACTIVITY RELEASED | 1 | Z | 33 | 10 | 0 | 0 | 11 | CONTENT | NA | 13 | AMOUNT OF ACTIVITY | 1 | NA | 135 | LOCATION OF RELEASE | NA | 136
9 | 10 | 11 | 13 | 44 | 45 | 80

PERSONNEL EXPOSURES | 1 | 0 | 0 | 0 | 37 | 1 | Z | 38 | 13 | DESCRIPTION | NA | 139
9 | 11 | 12 | 13 | 80

PERSONNEL INJURIES | 1 | 0 | 0 | 0 | 40 | 1 | NA | 141
9 | 11 | 12 | 80

LOSS OF OR DAMAGE TO FACILITY | 1 | Z | 42 | 1 | NA | 143
9 | 143

PUBLICITY ISSUED | 1 | N | 44 | 1 | NA | 145
9 | 10 | 145
DESCRIPTION NA 68 69

8304280058 830419
PDR ADOCK 05000313
S PDR

NRC USE ONLY
145 68 69 80

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/83-006/03L-0

Occurrence Date: 03/21/83

Event Description and Probable Consequences (Continued)

reported in LER's (50-313) 74-008, 76-003, 83-003, 83-004, and 83-007. The other three pressure transmitters feeding the RPS were found to be within tolerance.