LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 C T M N S 2 2 0 0 - 0 0 0 0 - 0 0
REPORT L G G 5 10 10 10 13 13 16 7 10 13 12 19 18 13 8 10 14 12 12 18 13 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 The plant was in steady state operation at 100% power. During a surveillance test
of a newly installed resistance temperature detector (RTD) the response time for the
[0]4] loop #1 Hot Leg, on channel D, was found to be out of specification in a non-
[0]5] conservation direction. The plant was operated in accordance with action statement
[0]6] 2b of Technical Specifications 3.3.1.1. Similar occurrences none.
071
O B L SYSTEM CAUSE CAUSE COMP. VALVE
SYSTEM CAUSE CODE SIBCODE COMPONENT CODE SUBCODE SUBCO
NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. SUPPLIER SUPPLIER SUPPLIER SUPPLIER MANUFACTURER [X] 18 A 9 7 20 Z 21 0 0 0 0 0 X 23 Y 24
The cause of the out of specification set point was RTD failure. The RTD was
removed as an reactor protection system input via the bypass/jumper system.
The Rosemount 104AFC-1 RTD will be replaced with a different manufacture's RTD in
the 1983 refuel outage.
7 8 9
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 1 0 0 29 N/A B 31 Surveillance Test
7 8 9 10 12 13 44 45 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 N/A N/A N/A N/A
7 8 9 10 11 11 14 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 0 0 0 37 Z 38 N/A
7 8 9 PEF. SONNEL INJURIES 13 NUMBER DESCRIPTION (4) N/A
1 8 9 11 12 12 143 B304280062 830422 PDR ADDCK 05000336 PDR PDR
PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY N/A
7 8 9 10 Keith D. Deslandes 447-1791 (4421)