DUKE POWER GOMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER VICE PRESIDENT NUCLEAR PRODUCTION

April 15, 1983

TELEPHONE (704) 373-4531

3 1 PR

D

1.0

0

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street NW, Suite 2900 Atlanta, Georgia 30303

Re: McGuire Nuclear Station Units 1 and 2 Docket Nos. 50-369 and 50-370

Dear Mr. O'Reilly:

On March 18, 1983 the NRC was notified (via ENS phone) that Unit 2 reactor trip breaker B failed to open on an undervoltage (UV) trip signal during testing performed to verify proper UV trip operation. On March 19, 1983 the NRC was notified (via ENS phone) that Unit 1 reactor trip breaker A failed to open on a UV trip signal during performance of the response time test. Pursuant to T.S. 3.3.1 which is reportable per T.S. 6.9.1.11(b) (Unit 2) and 6.9.1.13(b) (Unit 1), Reportable Occurrence reports RO-370/83-03 (Unit 2) and RO-369/83-15 (Unit 1) were to be submitted by April 15 and 18, 1983 respectively. However, a meeting with Duke Power Company requested by the NRC to discuss these recent reactor trip breaker failures has been tentatively rescheduled for Tuesday, April 19, 1983 (reference Ms. E. G. Adensam's letter to Mr. H. B. Tucker dated April 1, 1983). Therefore, these two reports will now be submitted by April 22, 1983 in order that they may include any results of this meeting.

Very truly yours,

H.B. Tucher 1 Med

Hal B. Tucker

PBN:jfw

cc: Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

Mr. W. T. Orders NRC Resident Inspector McGuire Nuclear Station

JEFICIAL COPY

8304280212 830415 PDR ADOCK 05000369 PDR