

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | I | L | T | P | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT 58

CON'T
 0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 0 | 7 | 0 | 4 | 0 | 5 | 8 | 3 | 8 | 0 | 4 | 1 | 9 | 8 | 3 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On 4-5-83, we were notified by our engineering department that some masonry walls |
 0 3 | in the Control Building do not comply with original designs. During the construction |
 0 4 | activities related to the control room modifications and computer room addition, |
 0 5 | some walls were found to have no internal grout and no reinforcing steel as called for |
 0 6 | by the design drawings. It is believed that this deficiency is limited to the Control |
 0 7 | Building. This is reportable in accordance with T.S. 6.9.2.a.9. The health and safety |
 0 8 | of the public were not affected. |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

0 9 | Z | Z | 11 | B | 12 | C | 13 | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
 17 | LER/RO REPORT NUMBER | 8 | 3 | 21 | 22 | - | 23 | 0 | 0 | 6 | 24 | 25 | 0 | 1 | 1 | 26 | 27 | T | 28 | - | 29 | 0 | 30 |
31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 18 | X | 19 | X | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | Y | 24 | N | 25 | Z | 26 | 9 | 9 | 9 | 27 | 28 | 29 | 30 |
31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Our engineering department is in the process of coordinating inspections and based on |
 1 1 | findings, corrective actions and repairs will be undertaken if necessary. If the results |
 1 2 | of the inspections reveal any relevant information, an LER update will be submitted. |
 1 3 | _____ |
 1 4 | _____ |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1 5 | E | 28 | 1 | C | 0 | 29 | N/A | 30 | C | 31 | Field Engineering Observation | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 1 6 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 1 8 | 0 | 0 | 0 | 40 | N/A | 41 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PERSONNEL INJURIES NUMBER DESCRIPTION
 1 9 | Z | 42 | N/A | 43 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 2 0 | N | 44 | N/A | 45 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER Jesus Arias, Jr. PHONE (305) 245-2910 Ext.200

Additional Event Description and Probable Consequences

The following walls were identified by our engineering department as non-conforming to the design drawings. The wall numbering system used was developed for our response to I & E Bulletin 80-11.

- A. Masonry Wall C-18-24 (Computer room west exterior wall)
- B. Masonry Walls C-42-1, C-42-2, and C-42-3 (Control room mechanical shaft)
- C. Masonry Wall C-42-4 (Control room offices)
- D. Masonry Walls C-42-12, and C-42-13 (Control room stairway)
- E. Masonry Wall C-30-6 (Mechanical equipment room)
- F. Masonry Wall C-30-10 (Mechanical equipment room)

We have concluded that continued operation of the plant during the investigation and possible subsequent repairs is warranted for the following reasons. First, Turkey Point Plant is located in an area of low seismic activity and the probability of a seismic occurrence is very low during the duration of the inspection and repair program (refer to FSAR 2.11.2). Second, the intensity of the design basis earthquake is very low (0.05g). Although the masonry walls may not be as absolutely rigid as the design assumes, they have an inherent capability to accommodate some earthquake loads. The lack of reinforcing steel and grout does not automatically disqualify the ability of the walls to withstand some seismic loading.