

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | L | B | R | F | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | [ ] [ ] [ ] [ ] (5)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T  
01 | L | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 0 | 3 | 2 | 2 | 8 | 3 | 8 | 0 | 4 | 2 | 0 | 8 | 3 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 | With unit 2 at 38.5-percent power for refueling tests, CRD 10-39 failed to scram  
03 | while performing SI 4.3.C as required by T.S. 3.3.C. The scram signal was  
04 | initiated from the auxiliary instrument room per SI 4.3.C/RTI-5. All other CRD's  
05 | were operable. There was no effect on the public health and safety. Redundant  
06 | systems were available and operable (SLC). T.S. 3.3.A.2.f allows plant operation  
07 | with an inoperable control rod.

09 | R | B | 11 | E | 12 | B | 13 | V | A | L | V | E | X | 14 | E | 15 | D | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 | LER/RO REPORT NUMBER | 8 | 3 | 21 22 | [ ] | 23 | 0 | 1 | 0 | 24 25 26 | [ ] | 27 | 0 | 3 | 28 29 | L | 30 | [ ] | 31 | 0 | 32  
18 | B | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | Y | 24 | L | 25 | H | 0 | 3 | 7 | 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 | Valve 85-617 (Hancock 950W) was found to have the valve stem separated from the  
11 | valve seat, blocking the scram discharge water path and causing failure to scram.  
12 | The CRD was inserted to "00" with drive pressure and tagged. The valve was  
13 | repaired and successfully tested per SI 4.3.C/RTI-5. This is a random event and  
14 | no recurrence control is required.

15 | C | 28 | 0 | 3 | 8 | 29 | NA | 30 | B | 31 | Surveillance Testing | 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 | 0 | 0 | 0 | 0 | 37 | [ ] | 38 | NA | 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

18 | 0 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

19 | Z | 42 | NA | 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

20 | N | 44 | NA | 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

8304280260 830420  
PDR ADOCK 05000260  
S PDR

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 83010 Technical Specification Involved 3.3.C

Reported Under Technical Specification 6.7.2.b.2 \* Date Due NRC 4-21-83

Event Narrative:

Unit 1 was at 91-percent power and steady state. Unit 3 was at 99-percent power and steady state. These units were unaffected by this event. Unit 2 was at 38.5-percent power and holding for testing per Surveillance Instruction 4.3.C/RTI-5.

Upon attempting to scram CRD 10-39 from the auxiliary instrument room during the performance of 4.3.C/RTI-5, the CRD failed to scram and therefore could not satisfy Technical Specification 3.3.C requirements. Investigation revealed valve 85-617 was closed as a result of the stem being separated from the valve seat. The valve had appeared to be open. This valve is the manual isolation valve between the scram discharge header and the scram outlet valve. It is suspected that this condition had existed only since startup from the refueling outage since the rod was scrambled satisfactorily on July 3, 1982, to enter the refueling outage. The CRD was operable with drive pressure. All other 184 CRDs were operable and

\* Previous Similar Events: (Continued)

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: JRP

LER Supplemental Information

Event Narrative:

SLC was operable. The CRD was inserted to "00" and tagged out; the three (3) other symmetric CRDs were inserted to "00". Upon the unit shutdown for maintenance, the 85-617 valve was repaired. The CRD was successfully tested per Surveillance Instruction 4.3.C/RTI-5 when the unit returned to service. This valve problem is of a random nature requiring no recurrence control.

Technical Specification 3.3.A.2.f allows plant operation with an inoperable control rod. There was no effect on the health or safety of the public.