



**North  
Atlantic**

North Atlantic Energy Service Corporation  
P.O. Box 300  
Seabrook, NH 03874  
(603) 474-9521, Fax (603) 474-2987

The Northeast Utilities System

Ted C. Feigenbaum  
Senior Vice President &  
Chief Nuclear Officer

NYN- 94065

June 13, 1994

United States Nuclear Regulatory Commission  
Washington, D.C. 20555

Attention: Document Control Desk

Reference: Facility Operating License No. NPF-86, Docket No. 50-443

Subject: Voluntary Licensee Event Report (LER) No. 94-007-00: Inadequate High Radiation Area Controls

Gentlemen:

Enclosed please find Licensee Event Report (LER) No. 94-007-00 for Seabrook Station. This submittal documents an event which occurred at Seabrook Station involving inadequate high radiation area controls. It is being reported as a voluntary LER.

Should you require further information regarding this matter, please contact Mr. James M. Peschel, Regulatory Compliance Manager, at (603) 474-9521, extension 3772.

Very truly yours,

Ted C. Feigenbaum

TCF:EWM/ewm

Enclosures: NRC Forms 366, 366A

200053

94062001B2 940609  
PDR ADOCK 05000443  
S PDR

United States Nuclear Regulatory Commission  
Attention: Document Control Desk

June 13, 1994  
Page two

cc: Mr. Thomas T. Martin  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Albert W. De Agazio, Sr. Project Manager  
Project Directorate I-4  
Division of Reactor Projects  
United States Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Antone C. Cerne  
NRC Senior Resident Inspector  
P.O. Box 1149  
Seabrook, NH 03874

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, GA 30339

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Seabrook Station	DOCKET NUMBER (2) 05000443	PAGE (3) 1 OF 3
---------------------------------------	-------------------------------	--------------------

TITLE (4)  
Voluntary LER 94-007-00, Inadequate High Radiation Area Controls

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	10	94	94	007	00	06	09	94	FACILITY NAME	DOCKET NUMBER 05000
									FACILITY NAME	DOCKET NUMBER 05000

OPERATING MODE (9) 6	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)									
POWER LEVEL (10) 0	20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)
	20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)
	20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			<input checked="" type="checkbox"/> OTHER
	20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)			(Specify in Abstract below and in Text, NRC Form 366A)
	20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)			
20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)				

LICENSEE CONTACT FOR THIS LER (12)

NAME Mr. James M. Peschel, Regulatory Compliance Manager	TELEPHONE NUMBER (Include Area Code) (603) 474-9521 Ext. 3772
---	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE).	<input checked="" type="checkbox"/>	NO					

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On May 10, 1994, at 1100 a Health Physics (HP) Supervisor on rounds discovered a High Radiation Area barrier repositioned which allowed access into the Volume Control Tank (VCT) area without the proper controls. The HP supervisor replaced the barrier to the proper position and searched the room for personnel, finding none. Two independent surveys of the VCT tank room were performed yielding the same results. The surveys determined that the radiation levels in this room indicated a maximum dose of 100mR/hr at 30 centimeters.

Technical Specification 6.11 requires that each High Radiation Area, as defined in 10CFR20, be conspicuously posted and barricaded. The radiation levels specified in 10CFR20 for a High Radiation Area are "in excess" of 100mR/hr at 30 centimeters. Based on the two radiation surveys performed after the barrier was found repositioned, the area did not meet the strict definition of a High Radiation Area and therefore posting and barricading, while unquestionably appropriate, was not required based on strict language of 10CFR20. Since the two independent surveys indicated radiation levels right on the High Radiation Area threshold, reporting of the barricade repositioning is in keeping with North Atlantic's conservative reporting philosophy.

There were no adverse safety consequences as a result of this event.

The root cause of this event was determined to be personnel error and/or inattention to detail. Although it could not be verified, it appears that the barrier was not properly replaced when personnel completed moving equipment in and out of the room.

The immediate corrective action taken in response to the repositioned High Radiation Area barrier was to immediately replace the barrier and to verify no workers present in the room. The barrier was subsequently replaced with a swing gate type. The Health Physics posting procedure will be revised to provide additional guidance on proper posting and barricade setup. This event was described in three site wide publications to stress to personnel that HP posting shall not be tampered with, modified or otherwise altered.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Seabrook Station	05000443	94	07	00	2 OF 3

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

### Description of Event

On May 10, 1994 at 1100 a Health Physics (HP) Supervisor on rounds discovered a High Radiation Area barrier repositioned which allowed access into the Volume Control Tank (VCT) area without the proper controls. The HP supervisor replaced the barrier to the proper position and searched the room for personnel, finding none. While continuing on rounds, the HP Supervisor found two workers in an adjacent room who had been in the VCT tank room earlier that day. They stated that the barrier had been in place at that time.

Further investigation into this event revealed that a roving fire watch, on rounds, opened the door to this room at approximately 1030 that same day. The fire watch reported that the barrier was in place at that time. Therefore, approximately 30 minutes elapsed from when the fire watch opened the door and when the HP Supervisor reported the barrier repositioned. A review of Radiation Work Permits (RWP) and security access logs could not determine if personnel entered the tank room during the 30 minute period. Two independent surveys of the VCT tank room were performed yielding the same results. The surveys determined that the radiation levels in this room indicated a maximum dose of 100mR/hr at 30 centimeters.

Technical Specification 6.11 requires that each High Radiation Area, as defined in 10CFR20, be conspicuously posted and barricaded. The radiation levels specified in 10CFR20 for a High Radiation Area are "in excess" of 100mR/hr at 30 centimeters. Based on the two radiation surveys performed after the barrier was found repositioned, the area did not meet the strict definition of a High Radiation Area and therefore posting and barricading while unquestionably appropriate was not required based on strict language of 10CFR20. Since the two independent surveys indicated radiation levels right on the High Radiation Area threshold (exactly 100mR/hr vs. "in excess" of 100 mR/hr) reporting of the barricade repositioning is in keeping with North Atlantic's conservative reporting philosophy.

### Safety Consequences

There were no adverse safety consequences as a result of this event. It is estimated that the barrier had been repositioned for approximately 30 minutes. A review of RWPs, security access logs, and personnel interviews could not determine if anyone entered the tank room during this period of time. A room search upon discovery found no one present in the room.

### Root Cause

The root cause of this event has been determined to be personnel error and/or inattention to detail. Although, it could not be verified, it appears that the barrier was moved by personnel moving equipment in or out of the room. It is recognized that stanchions are easily moved to accommodate the movement of personnel and equipment.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)
Seabrook Station	05000443	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
		94	07	00
3 OF 3				

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Corrective Actions

The barrier was immediately repositioned across the entrance to the VCT room and the room searched to verify that no workers were presently in the room. The stanchion type barrier to this area was subsequently replaced with a spring loaded swing gate barrier which does not have to be physically moved to allow personnel and equipment passage. In addition, the following corrective actions were or will be taken to reduce the probability of events of this nature from reoccurring in the future:

1. The Health Physics posting procedure will be revised to provide additional guidance on proper posting and barricade setup.
2. This event was described in three site wide publications to discuss this event and stress to personnel that HP postings shall not be tampered with, modified or otherwise altered.

Plant Conditions

At the time of this event, the plant was in Mode 6, with the reactor defueled.

Related Events

North Atlantic has reported a similar event of this type involving an improperly posted High Radiation Area in Seabrook Station LER 93-019.