LICENSEE EVENT REPORT

CONTROL BLOCK!	
CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [INFORMATION)
0 1 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 0 0 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 4 57 CAT 58 (5)
CON'T REPORT L 6 0 5 10 10 0 3 2 17 7 0 4 10 1 8 3 8 0 4 75 R	12 6 8 13 9 PERCET DATE 80
With unit 1 in mode 1 (100% Rx power) at 1610 CST on 04/01/83, the	No. 1 steam
generator wide range level channel was declared inoperable due to	failing low.
Similar events occurred at 0026 CST on 04/06/83 and 0605 CST on 04	/10/83. For each
event, the unit complied with action statement (b) of LCO 3.3.3.7.	There was no .
old effect upon public health and safety. Previous occurrences - none	•
07	<u> </u>
	VALVE
TO SEQUENTIAL OCCUMBENCE REPORT	Z (16)
17 REPORT 8 3	NO. 0
ACTION FUTURE CFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIED FORM SUB. SUPPLIED SUBMITTED FORM SUB. SUBMITTED FORM SUB. SUPPLIED SUBMITTED FORM SUB. SUBMITTED FORM SUB. SUPPLIED SUBMITTED FORM SUB. SUPPLIED SUBMITTED FORM SUB. SUBMITTED FORM SUBMITTE	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (21)	rectly except the
In each event, all loop components were verified to be working components.	*
recorder 1-LR-3-43. The cause for the faulty Foxboro Model 6400H	
probably due to defective switches in the connector. For the first	**
recorder was returned to service after cleaning the connectors at	1830 CST on .
04/01/83 and 0137 CST on 04/06/83 respectively. After the third end was replaced and verified operable at 1300 CST on 04/11/83.	8
1 5 E 28 1 0 0 29 NA B 30 Operator observation	
ACTIVITY CONTENT HELEASED OF HELEASE AMOUNT OF ACTIVITY (35) LOCATION OF HELEASE	
7 6 9 10 11 44 45 PERSONNEL EXPOSURES	50
NUMBER TYPE DESCRIPTION (32) NA NA	80
PERSONNEL INJUNIES NUMBER DESCRIPTION (41)	
1 8 0 0 0 (40) NA 1 8 2 11 12 12 13 14 14 14 14 14 14 14	80
PDR ADOCK 05000327	
PURLICITY ISSUED DESCRIPTION 45	NAC USE ONLY
7 8 9 10 NA	
Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 870)-6422