LICENSEE EVENT REPORT

LICENSEE EVENT HEFORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 G A E I H 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 CAT 58 6
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 12 On 10-22-82, with Unit 2 at 815 MWe, QC personnel were witnessing repair
old of a silicone foam fire barrier in the cable spread room when it was
old moted that an adjacent barrier had been breached. Tech. Specs. Section
3.7.7 requires a fire watch or equivalent monitoring whenever a fire
parrier is non-functional. Equivalent monitoring was immediately estab-
0 7 lished upon discovery of the breached barrier. The health and safety of
the public were not affected by this non-repetitive event.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LER/RO REPORT NUMBER 2 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURE! B 8 X 19 Z 20 Z 21 36 37 40 41 23 42 43 43 44 47 47 47 47 47
The penetration was apparently left unsealed after installation of con-
duit through the seal. A Maintenance Request was initiated and the seal
was successfully repaired on 11-02-82. The plant is now in full com-
pliance.
114
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 1 0 0 29 NA B 31 OA Inspection
7 8 9 ACTIVITY CONTENT 12 13 44 45 46 80 RELEASE DEFRELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
PERSONNEL EXPOSURES
1 7 0 0 0 37 Z 38 NA
1 7 0 0 0 37 Z 38 NA 7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41) 80
NUMBER OF OF OF DESCRIPTION (41) NUMBER DESCRIPTION (41) NA 1 8 9 PERSONNEL INJURIES 13 NA NA 80 1 1 1 12 82 80 80 80 80 80 80 80 80 80
NUMBER TYPE DESCRIPTION (39) NA PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA 80 1 8 9 11 12 13 NA 7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43) PDR ADDCK 05000366 1 9 Z (42) NA S PDR
NUMBER OESCRIPTION (39) 7
1 7 0 0 0 37 Z 38 NA NA NA NA NA NA NA N