

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259/ 82088 Technical Specification Involved 3.7.C.1
Reported Under Technical Specification 6.7.2.b.(4) Date Due NRC 11/27/82

Event Narrative:

Unit 1 was operating at 98-percent power; unit 3 was operating at 98-percent. These units were unaffected by this event. With unit 2 in a refueling outage, operating personnel discovered a momentary breach of secondary containment due to personnel access airlock door 236 to the unit 2 reactor building and door 235 to the turbine building being opened simultaneously (T.S. 3.7.C.1). Doors 235 and 236 were closed immediately and a doorwatch was posted until repairs were completed. The solenoid on door 235 was misaligned due to normal wear, preventing it from being locked. The solenoid was realigned and the personnel access interlock was returned to service. There are no redundant systems. There was no effect on public health and safety. Radioactive contamination did not occur since the secondary containment zone was maintained at negative pressure during this event. Considering the large number of entries through these doors, this event is considered a random failure and no further recurrence control is required.

* Previous Similar Events:

BFRO-50-259/81008, 81050, 82063
260/80045, 77015, 81024, 81025, 81025, 81032, 81038, 80003
296/7920

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP