NRC FOF (7-77)	1 366	U. S. NUCLEAR REGULATORY COMMISSION
		PRINT OR TYPE ALL REQUIRED INFORMATION
	$\begin{array}{c} N \\ \hline C \\ \hline B \\ \hline E \\ \hline P \\ \hline Licensee \ CODe \\ \hline 14 \\ \hline 15 \\ \hline C \\ \hline \hline C \hline \hline$	0 0 3 4 1 1 1 1 5 5 5
CON'T	REPORT SOURCE L 6 0 5 0 - 0 3 2 5 0 1 0 60 61 DOCKET NUMBER 68 69 EVE	2 6 8 2 8 1 1 1 2 4 8 2 9 ENT DATE 74 75 REPORT DATE 80
0 2	During plant operation, performance of the Supp	eression Pool Level Indicators Oper-
03	ability Test, PT-08.1.6 revealed that indicators	1-CAC-LI-2601-1 and 3 and 1-CAC-LR-2602
0 4	showed a level indication of -29". A check of t	he local level indicator showed the
0 5	actual level was -26.5", which exceeded the spec	ified upper limit of -27" and is being
0 6	reported in LER 1-82-118. This event did not af	fect the health and safety of the
37	public.	
08	Technical Specifications 3.6.2.1	, 6.9.1.9b
7 8 0 9 7 8	SYSTEM CODE I E (1) B (2) A (3) I N S T 9 10 11 25 COVE	CODE COMP. VALVE SUBCODE SUBCODE SUBCODE T R U (14) T (15) Z (16) 18 19 0000 T 20 0000 T 000000000000000000000
	1 LER/RO EVENT YEAR REPORT NO. 1 REPORT 8 2 1 1 1 7	CODE TYPE NO.
	NUMBER 21 22 23 24 26 27 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 SUE X 33 34 19 Z 20 Z 21 0 0 0 $0CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
10	A change in trickle flow to the wet reference le	eg of the LR-2602 instrument transmit-
11	ter, LT-2602, Model No. BQ15221, caused an incor	rect input signal to the instrument.
12	The instrument transmitter of LI-2601-1 and 3, I	T-2601, was found operating out of
1 3	calibration tolerances due to instrument drift.	The LT-2602 trickle flow was
14	adjusted and the LT-2601 was calibrated.	80
15	9 Acility Method of Discovery Status 30 Method of Discovery E 28 0 6 5 29 NA B 31 E 2 10 12 13 44 45 46	DISCOVERY DESCRIPTION (32) Periodic Test
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 A 45	LOCATION OF RELEASE 36
	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39	14
7 8	9 PERSONNEL INJURIES	80
1 8		A
2 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION	
7 8	9 10 PUBLICITY 0 8212070214 821124	80 NBC USE ONLY
20	SUED DESCRIPTION (45) PDR ADOCK 05000325 N 44 S PDR	
/ 8	NAME OF PREPARER M. J. Pastva, Jr.	PHONE 919-457-9521

LER ATTACHMENT - RO #1-82-117

Facility: BSEP Unit No. 1

Event Date: October 26, 1982

As a result of previously reported events involving this instrumentation on both units, plant modification packages (80-78 for Unit No. 1 and 80-99 for Unit No. 2) have been developed. These modifications will install a condensing pot in the reference leg of each subject instrument transmitter in order to increase the accuracy and reliability of these instruments. In addition, these modifications will remove the present requirement to have flow in each subject reference leg to ensure it is full.