NRC FOF (7:77)	U. S. NUCLEAR REGULATORY COMMISSION
	CONTROL BLOCK:
0 1 7 8	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T	REPORT LG 0 5 0 0 0 3 6 1 7 1 0 2 1 8 2 8 1 1 1 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	With the plant in Mode 2, hot leg sample isolation valve 2HV-0509 was observed to
03	have simultaneous open and closed position indication when it was, in fact, closed.
04	The valve was declared inoperable. Since the valve remained closed and its redundant
05	valves remained closed and operable throughout the event, there was no impact on
06	L health and safety of plant personnel or the public.
07	L
08	80
09	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
10	17 LER.RO REPORT EVENT YEAR NUMBER SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE NO.   17 LER.RO REPORT 13 3 24 26 27 0 3 1 0 32   ACYION TAKEN FUTURE ON PLANT EFFECT NETHOD SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER   18 13 34 20 12 0 0 0 0 0 32 32 32   26 13 21 23 24 26 27 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER   13 34 20 12 0 0 0 40 41 23 N 43 25 F 1 3 0 26   33 34 35 37 40 41 23 1 43 25 F 1 3 0 26   34 35 36 37 40 <t< td=""></t<>
11 12 13	Assembly 2ZSL-0509-1. The loosened actuator bar allowed lateral movement which resulted in the bar not making contact with the open limit switch when the valve was closed. After readjusting and tightening the actuator bar, the valve was declared operable. As corrective action, a Startup Problem Report (SPR) has been initiated to evaluate the feasibility of providing a key lock assembly on the valve stems of
14	L this type of valve.
1 5	B B B B B B B C B C C C C C C C C C C C C C
	9 CTIVITY CONTENT 12 13 44 45 46 80 LCTIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36 80 2 3 3 2 3 10 3 10 11 44 45 46 80 80
17 2 B	PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 NA 12 12 12 12 12 12 12 12 12 12 12 12 12 1
1	
7 8	9 11 12 80 1055 DE DE DAMAGE TO FACILITY (2) 8212070287 821119
19	TYPE DESCRIPTION (43) PDR ADOCK 05000361 Z (42) NA S PDR ADOCK 05000361 PDR 80
	PUBLICITY ISSUED DESCRIPTION 45
2 0	
	NAME OF PREPARER H. B. Ray HORAY / TYUMWAY PHONE 714/492-7700