



ATTACHMENT TO LICENSEE EVENT REPORT 82-08/03X-1

COMMONWEALTH EDISON COMPANY (CWE)

DRESDEN UNIT 3

DOCKET # 050-249

Following refueling outage, while performing surveillance DIS 2300-7 calibration testing on the HPCI temperature switches, the following switches were above Tec. Spec. limit of 200 degree F. (Tech. Spec. Table 3.2.a): 2371A, 2372A, 2373B, 2370C, 2370D and tripped at temperatures 203.4, 204.0, 207.0, 206.9 and 221.2 degree F. respectively. There was no effect on public health and safety. This event is of minimum safety significance since the remaining temperature switches were available to perform their intended function. Previous occurrences were reported by R.O. 050-249/80-8, 80-11, and R.O. 050-237/81-7, 74-63.

The event was caused by a misaligned microswitch. Repetitive vibration to the switches is believed to have caused the screws to loosen, resulting in an enlarged gap between the actuator and the switch plunger. The switches were aligned correctly, screws tightened and secured with Loc-Tite, and calibrated according to DIS 2300-7.

Testing of the HPCI area temperature switches will continue to be performed every refueling outage.