(12-81)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-62
-	CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFO	
0 1	P A S E S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4	57 CAT 50 (5)
0 1 7	REPORT	8 2 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While in the Startup Testing Program, it was determined that the Con	ntrol Rod
0 3	Position Indication full-out position switch was inoperable for one	rod. This
0 4	is reportable per 6.9.1.9.b. The appropriate action statements were	e met,
0 5	therefore, no adverse consequences existed.	
0 6		
0 7		
0 8		**
	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE	
0 9	I F 11 E 12 G 13 Z Z Z Z Z 14 Z 15 Z 16	
	TO REPORT NUMBER 2 23 24 26 27 28 29 30 31	REVISION NO.
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. SUPPLIER SUBMITTED FORM SUB. SUPPLIER SU	COMPONENT (26) Z 9 9 9 9 47
10	Full-out indication inoperability was the result of a failed subcom	ponent on
1 1	a printed circuit board. The board was replaced and the system ope	rated
1 2	properly. No further corrective action is deemed necessary.	
1 3		1
1 4		1
7 8	STATUS SPOWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION	(32)
1 5	B 28 0 0 0 0 29 n/a A 31 operator observation	**
	ACTIVITY CONTENT DELEASE OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) n/a n/a	
7 8	9 10 11 44 45 PERSONNEL EXPOSURES	80
17	NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 n/a 11 12 13	
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 40 n/a	
7 8	U 1 12 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43)	80
1 9	Z @ n/a	80
	PUBLICITY ISSUED DESCRIPTION 45	C USE ONLY
2 0	N (44)	
321206	NAME OF PREPARER D.G. Mitchell PHONE: (717) 542-	2181 X524