

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	L	L	S	C	1	0	0	-	0	0	0	0	0	0	-	0	0	4	1	0	0	0						
8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	58	59

0	1	L	0	5	0	0	0	3	7	3	1	0	3	0	8	2	1	1	2	9	1	8	2	
7	8	REPORT SOURCE	60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 _____

0 3 _____

0 4 _____

0 5 _____

0 6 _____

0 7 _____

0 8 _____

0	9	M	C	B	A	Z	Z	Z	Z	Z	Z	Z	Z	
7	8	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE					COMP. SUBCODE	VALVE SUBCODE		
9	10	11	12	13	14	15	16	17	18	19	20	21	22	
17	21	22	23	24	25	26	27	28	29	30	31	32	33	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
G	F	Z	Z	0	0	0	0	Y	N	A	Z	9	9	9
FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED	NPRO-4 FORM 548L	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 _____

1 1 _____

1 2 _____

1 3 _____

1 4 _____

1	5	Z	0	4	4	NA	A	OBSERVATION				
7	8	FACILITY STATUS		% POWER		OTHER STATUS	METHOD OF DISCOVERY					DISCOVERY DESCRIPTION
9	10	11	12	13	14	15	16	17	18	19	20	21
22	23	24	25	26	27	28	29	30	31	32	33	34
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
35	36	37	38	39	40	41	42	43	44	45	46	47
Z	Z	NA			NA							
PERSONNEL EXPOSURES		TYPE		DESCRIPTION								
48	49	50	51	52	53	54	55	56	57	58	59	60
0	0	0	Z	NA								
PERSONNEL INJURIES		DESCRIPTION										
61	62	63	64	NA								
0	0	0		NA								
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION										
65	66	NA										
Z	NA											
PUBLICITY ISSUED		DESCRIPTION										
68	69	NA										
N	NA											

8212080410 821129
PDR ADOCK 05000373
S PDR

NRC USE ONLY

- I. LER NUMBER: 82-140/03L
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

The monitor for Off-Gas Pretreatment was declared inoperable due to water in the sample line which causes loss of sample flow to the detectors. A purge was attempted to clear the line of the water so sample flow could be re-established. The purge was unsuccessful in eliminating the water. The line was then drained and flow re-established with monitor being declared operable. The purge also caused off-gas to enter the room for sampling in the Turbine Building, elevation 754 ft. west column number 9.

- V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

The health and safety of the public was not affected by the detector being inoperative. Post treatment monitor did not show any radioactivity above normal prior to or during the event. Radio isotopic analysis of Reactor Water did not show any radioactivity above what is expected at this time. Main Steam Line Rad Monitors did not increase appreciably during the event and there were no Area Radiation Monitor alarms in the vicinity of the Off-Gas Pretreatment Monitor. Station Vent Stack Monitor was operative and did not indicate any increase in radioactivity prior to or during the event.

- VI. CAUSE:

The cause of loss of gas flow in the sample line was water in the line blocking flow. The sample that enters this system is close to its dew point. The system takes suction downstream of moisture separator and prior to the 30 minute holdup volume of the Off-Gas system. The gas enters the sampling system at approximately 2 psig and 130°F and a high moisture content. The gas must take a couple pipe size reductions and pipe bends to reach the detector. The gas also has ambient heat losses and becomes more dense. It is this combination of flow restrictions and temperature losses that causes moisture to collect in the sample line and restrict or prevent flow causing an inoperative condition of the detection system.

The purge valve for this system was discovered to have been installed improperly which was the reason for the Off-Gas entering the sample room. The purge valve could not be used to purge the sample line because when it repositioned it stopped flow. (Noted on drawings.)

- VII. CORRECTIVE ACTION:

The sample line was drained and the monitor was restored to operable status. A temporary heat trace has been installed to keep the gas at a higher temperature. The purge valve has been properly installed to allow proper flow through the system. A modification has been written to install permanent heat tracing.

Operating has been advised to purge the sample line periodically and the annunciator procedure has been changed to identify the use of the purge switch.

Prepared by: W. Luett