

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 1 | L | L | S | C | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 0 | 0 | 0 | 4 | 5
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 7 | 3 | 7 | 1 | 0 | 3 | 0 | 8 | 2 | 9 | 1 | 1 | 3 | 0 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80 81
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Tech Spec 3.3.7.5 requires the drywell oxygen monitoring channels to be operable
0 3 | during conditions 1 & 2. On 10/30/82 it was noticed that the Div. II oxygen
0 4 | channel was reading erratically. At the time of the occurrence, LSCS was at 1450 MWT
0 5 | and 470 MWE. The drywell was not yet inerted since inerting is not a requirement
0 6 | for the present phase of the startup test program. The div II oxygen channel remained
0 7 | fully operable at all times. Safe operation of the plant was maintained.

0 8 | _____
7 8 9

0 9 | SYSTEM CODE: S E (11) CAUSE CODE: E (12) CAUSE SUBCODE: X (13) COMPONENT CODE: I N S T R U (14) COMP. SUBCODE: E (15) VALVE SUBCODE: Z (16)
7 8 9 9 10 11 12 13 14 15 16 17 18 19 20 21 22

(17) LER/RO REPORT NUMBER: 8 2 (21-22) SEQUENTIAL REPORT NO.: 1 3 9 (24-26) OCCURRENCE CODE: 0 3 (28-29) REPORT TYPE: L (30) REVISION NO.: 0 (32)

ACTION TAKEN: E (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 (37-40) ATTACHMENT SUBMITTED: Y (41) NPRD-4 FORM SUB.: N (42) PRIME COMP. SUPPLIER: Z (25) COMPONENT MANUFACTURER: Z 9 9 9 (44-47)

CAUSE DESCRIPTION AND CORRECTIVE ACTION'S (27)

1 0 | The erratic readings were a result of moisture build up in the oxygen sample flowmeter.
1 1 | Work Request No. L20147 was written to troubleshoot and repair the Div II Post LOCA
1 2 | Oxygen Channel. The moisture was removed from the oxygen sample flowmeter and the
1 3 | instrumentation was recalibrated under LIS-PC-07.
1 4 | _____

1 5 | FACILITY STATUS: B (28) % POWER: 0 4 4 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: OBSERVATION (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | ACTIVITY CONTENT: Z (33) RELEASED OF RELEASE: Z (34) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) TYPE: Z (38) DESCRIPTION: NA (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | PERSONNEL INJURIES: NUMBER 0 0 0 (40) DESCRIPTION: NA (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) DESCRIPTION: NA (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | PUBLICITY ISSUED: Z (44) DESCRIPTION: NA (45)

8212080413 821130
PDR ADOCK 05000373
S PDR

NRC USE ONLY

NAME OF PREPARER: R. Dus

PHONE: (315) 357-6761-
68 69 80

- I. LER NUMBER: 82-139/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

Technical Specification 3.3.7.5 requires the Drywell Oxygen Monitoring Channels to be operable during conditions 1 and 2. On 10/30/82 it was noticed that the Div II Oxygen Channel was reading erratically over a range from 15% to 20%.

- V. PROBABLE CONSEQUENCES:

At the time of the occurrence, LaSalle County Station was at 1450 MWT and 470 MWE. The drywell was not yet inerted with nitrogen since inerting is not a requirement for the present phase of the startup test program. The Div I Oxygen Channel remained fully operable at all times. Safe operation of the plant was maintained.

- VI. CAUSE:

The erratic oxygen readings were a result of moisture build up in the Oxygen Sample Flowmeter.

- VII. CORRECTIVE ACTION:

Work Request #L20147 was written to troubleshoot and repair the Div II Post LOCA Oxygen Channel. The moisture was removed from the oxygen sample flowmeter and the instrumentation was recalibrated under LIS-PC-07. Work was completed on 11/3/82.

Prepared by: R. S. Dus