U. S. NUCLEAR REGULATORY COMMISSION NRC FORM 366 (7-57) LICENSEE EVENT REPORT CONTROL BLOCK: (1)(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 200-R 0 C H B 10 LICENSEE CODE CON'T 6 0 5 0 0 2 6 1 7 1 1 0 3 8 2 8 1 1 3 0 8 2 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 REPORT 0 1 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On November 3, 1982, at 1155 hours, with the unit at 80% power, Containment Fan Cooler, 0 2 HVH-3 failed to restart during the performance of a periodic test. The cause of 0 3 failure was determined to be a defective time delay relay in the motor breaker cen-0 4 trol circuit. This event resulted in operation in a degraded mode permitted by a 0 5 Limiting Condition for Operation as defined by Tech. Spec. 3.3.2.2.a which is report-0 6 able pursuant to 6.9.2.b.2. The Containment Spray Pumps were verified operable in 0 addition to the other three Containment Fan Coolers, so there was no threat to the public health and safety. 3 8 C CAUSE SYSTEM CAUSE COMP VALVE SUBCODE COMPONENT CODE SUBCODE CODE SB X (14) H (15) A (13) E R E LA Z (16) (11) (12) 0 9 18 OCCURRENCE REVISION SEQUENTIAL REPORT CODE EVENT YEAR REPORT NO. TYPE LER/RO 013 0 0 1 REPORT 81 21 6 L NUMBER COMPONENT MANUFACTURER A 1 1 0 1 9 EFFECT ON PLANT NPRD-4 FORM SUB. PRIME COMP. ACTION FUTURE TAKEN ACTION SHUTDOWN ATTACHMENT SUBMITTED (22) HOURS SUPPLIER Y N (24) A (25 Z (21) Z (19 Z (20 0101 0 0 A (18) (23) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The defective time delay relay was replaced with a new unit. HVH-3 was tested and 1 0 declared operable at 1550 hours on November 3, 1982. This event is the result of 1 1 component failure caused by natural end of life. No further corrective action is considered necessary. 4 80 METHOD OF FACILITY STATUS (30)DISCOVERY DESCRIPTION (32) OTHER STATUS DISCOVERY > POWER 0 (29) B (31) Routine Test N/A E (28) 0 81 9 10 ACTIVITY CONTENT 80 N/A LOCATION OF RELEASE 36 AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE 80 44 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 0 0 37 2 38 N/A 80 P"HSONNEL INJURIES DESCRIPTION (41) UMAER 01 0 (40) N/A 80 LOSS OF OR DAMAGE TO FACIL! TY (43) TYPE DESCRIPTION N/A Z (42) 8212090128 821130 80 PDR ADOCK 0500026 PUBLICITY NRC USE ONLY DESCRIPTION (45 PDR SSUED N (44) 11 N/A 68 60 (803) 383-4524 Howard T. Cox NAME OF PEEPARER ____ PHONE -

SUPPLEMENTAL INFORMATION FOR LICENSEE EVENT REPORT 82-016

I. Cause Description and Analysis

On November 3, 1982, at 1155 hours, with the unit at 80% power, Containment Fan Cooler, HVH-3 failed to start. This failure occurred during the performance of Periodic Test (PT) 10.1B. HVH-3 had been stopped during the test and could not be restarted. Investigation revealed that a time delay relay in the motor control circuit had failed which prevented the motor breaker from closing on receipt of a start signal. Further investigation determined that the time delay relay failure was caused by contact arcing which resulted in the contacts welding together. This failure is attributed to normal end of life of the relay.

This event resulted in operation in a degraded mode permitted by a Limiting Condition for Operation as defined by Technical Specification 3.3.2.2.a which is reportable pursuant to 6.9.2.b.2. The remaining HVH units were operable, and the Containment Spray Pumps were verified operable, so there was no threat to the public health and safety.

II. Corrective Action

In accordance with Technical Specification 3.3.2.2.a, the Containment Spray Pumps were immediately verified operable. The defective time delay relay (63X) for HVH-3 motor breaker was replaced with a new unit, and HVH-3 was tested satisfactorily. HVH-3 was declared operable at 1550 hours on November 3, 1982.

III. Corrective Action To Prevent Recurrence

This event is the result of component failure caused by natural end of life. Current periodic testing is considered sufficient to detect such failures; therefore, no further corrective action is necessary.