

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 2 0 0 0 0 0 0 0 0 0 0 4 1 1 1 1 4 5
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

02 L 0 5 0 0 0 2 8 1 1 1 1 2 8 2 8 1 2 0 3 8 2 6
REPORT SOURCE 60 61 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
012 With the unit at 100% power, during the performance of PT 18.6B, TV-CC-209B
013 would not close when manually operated from the control room. This event is
014 contrary to T.S.3.8.A.1 and is reportable per T.S.6.6.2.b(2). The component
015 cooling system is a closed system and it's integrity was maintained during the
016 event. Therefore, an operable barrier existed between the containment and the
017 environment. Public health and safety would not have been affected.

09 W B 11 E 12 B 13 V A L V O P 14 D 15 Z 16
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
17 8 2 0 6 8 0 3 L 0
LER/RP REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
18 A 19 F 20 Z 21 Z 22 0 0 0 0 23 Y 24 N 25 A 26 H 0 3 5
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
110 The cause of the event has been attributed to a sticking pilot valve (pneumatic
111 operator) that controls air flow from the valve actuator. The pilot valve was
112 replaced and the valve was tested satisfactorily.

15 E 28 1 0 0 29 N/A 30 B 31 Periodic Test 32
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 Z 33 Z 34 N/A 35 N/A 36
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 0 0 0 37 Z 38 N/A 39
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 0 0 0 40 N/A 41
PERSONNEL INJURIES NUMBER DESCRIPTION

19 Z 42 N/A 43
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 N 44 N/A 45
ISSUED DESCRIPTION PUBLICITY

8212090144 821203
PDR ADOCK 05000281
S PDR

NRC USE ONLY

NAME OF PREPARED J. L. Wilson

PHONE (804) 357-3184

926-716-01

ATTACHMENT 1
SURRY POWER STATION, UNIT NO. 2
DOCKET NO: 50-281
REPORT NO: 82-068/03L-0
EVENT DATE: 11-12-82

TITLE OF THE EVENT: TV-CC-209B WILL NOT CLOSE

1. Description of the Event:

On 11-12-82, with the unit at 100% power, the reactor operator was performing PT-18.6B, Quarterly Testing of Miscellaneous Containment Trip Valves, when trip valve, TV-CC-209B (component cooling for residual heat removal) failed to close on demand from the control room. Inoperability of an automatic containment isolation valve is contrary to Technical Specification 3.8.A.1 and is reportable per Technical Specification 6.6.2.b(2).

2. Probable Consequences and Status of Redundant Equipment:

The Design Basis for the containment isolation system is that during accident conditions, at least two barriers exist between the atmosphere outside the containment structure and

- a) The atmosphere inside the containment structure
- b) The reactor coolant and connecting systems

Failure of one valve or barrier will not prevent isolation of the containment. Component cooling water piping is separated from the reactor coolant system, or a connecting system, and the atmosphere, by a membrane barrier.

Since the integrity of the membrane barrier, (the component cooling water piping inside containment), was maintained, an isolation barrier existed during this event. Therefore, the health and safety of the public would not be affected.

3. Cause:

The cause of this event was attributed to a sticking pilot valve which controls air flow to the discharge actuator of the component cooling trip valve.

4. Immediate Corrective Action:

The immediate corrective action was to dispatch an operator to take administrative control of the manual isolation valve.

5. Subsequent Corrective Action:

The pilot valve was replaced and the valve cycled satisfactorily.

6. Action Taken to Prevent Recurrence:

Necessary actions to prevent recurrence have been specified in Engineering Study No. 82-48 and are pending implementation of Design Change 82-27.

7. Generic Implications:

Similar failures have been experienced on TV-CC-209B, during previous periodic tests.