

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

December 2, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street, N.W.
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Thirty Day Written Report
LER 82-036

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #82-036 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (a) of Technical Specification 3.3.3.5, "Instrumentation, Remote Shutdown Instrumentation," on November 3, 1982.

Should there be any questions, please call us at your convenience.

Very truly yours,


O. W. Dixon, Jr.

HCF:OWD:dwf
Attachment

cc: V. C. Summer
T. C. Nichols, Jr.
G. H. Fischer
O. W. Dixon, Jr.
H. N. Cyrus
H. T. Babb
D. A. Nauman
M. B. Whitaker, Jr.
W. A. Williams, Jr.
O. S. Bradham
R. B. Clary
M. N. Browne

A. R. Koon
G. D. Moffatt
Site QA
C. L. Ligon (NSRC)
G. J. Braddick
J. L. Skolds
J. B. Knotts, Jr.
B. A. Bursey
I&E (Washington)
Document Management Branch
INPO Records Center
NPCF
File

OFFICIAL COPY
IE 22

Mr. James P. O'Reilly
LER No. 82-036
Page Two
December 2, 1982

DETAILED DESCRIPTION OF EVENT

On November 3, 1982, the Plant entered Mode 3 with the Reactor Coolant System Pressurizer Relief Tank Level Indicator LI-470A (Control Room Evacuation Panel Level Indicator) out of service. This indication is required to be operable per Technical Specification 3.3.3.5. The condition was discovered by surveillance testing prior to entering Mode 3; however, the provisions of Specification 3.0.4 are not applicable.

PROBABLE CONSEQUENCES

There were no adverse consequences as the applicable Technical Specification Action Statement was complied with.

CAUSE(S) OF THE OCCURRENCE

The event is attributed to LT-470A (Pressurizer Relief Tank Level Transmitter for the Control Room Evacuation Panel) being out of calibration.

IMMEDIATE CORRECTIVE ACTIONS TAKEN

- 1) A Maintenance Work Request was issued for investigation and restoration.
- 2) The level transmitter for the subject indicator was calibrated.
- 3) A Channel Check and subsequent surveillance test were then performed satisfactorily.
- 4) The system was returned to operable status on November 9, 1982.

ACTION TAKEN TO PREVENT RECURRENCE

The Licensee plans no further actions for this event other than the normally required surveillance testing.