

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	14										25										30					57		58
		LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE							

CON'T

0 1 7 8

REPORT SOURCE

L 6 0 5 0 0 0 3 6 6 7 0 6 2 5 8 0 8 1 1 2 3 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the performance of the "HPCI STEAM LINE DELTA P INSTRUMENT FT&C"
03 procedure, for flow switch, N004, setpoints were found to be -206" H2O
04 for switch 1 and +265 for switch 2. TS 3.3.2-2, item 5.a. requires a
05 setpoint of ≤ 300 percent of rated flow (equivalent to a setpoint of
06 ± 196 " H2O). Plant operation was not affected since redundant switch
07 N005 was operable. The health and safety of the public were not affected
08 by this repetitive event (last reported on LER 50-366/1980-072).

09		SYSTEM CODE S F		11	CAUSE CODE E		12	CAUSE SUBCODE E		13	COMPONENT CODE I N S T R U						14	COMP. SUBCODE S		15	VALVE SUBCODE Z		16
7	8	9	10		11	12		12		13						14	19		20				
17		LER/RO REPORT NUMBER		EVENT YEAR 8 0		21	22	SEQUENTIAL REPORT NO. 0 9 7		24	25	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE X		30	REVISION NO. 1		32	
33		ACTION TAKEN		FUTURE ACTION F		34	35	EFFECT ON PLANT Z		36	37	38	39	SHUTDOWN METHOD Z		41	42	HOURS 0 0 0 0		44	45	46	47
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35		36		37		38		39		40		41		42		43		44	
33		34		35</																			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event has been attributed to setpoint drift. The
1 1 switch, a Barton Model 288A, was recalibrated, successfully functionally
1 2 tested, and returned to service. An engineering study to find a means
1 3 of preventing or reducing the frequency of recurrence has recommended a
1 4 Design Change. Recommended corrective measures are being evaluated.

1 5 E 28 0 9 8 29 NA B 31 Surveillance testing

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

45 80

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA	(39)			

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

7 8 9 11 12

8212090388 8212090388 80

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION NA
1 9 Z (42) 8 9 10
PDR ADOCK 05000366
S PDR

2		0		ISSUED		PUBLICATION		DESCRIPTION		NRC USE ONLY	
7		8		9		10		11		12	
				N		44		NA			

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851