(7.77)	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1 7 8	LICENSEE CODE 14 15 1 01 -1 01 01 01 0 10 10 10 0 0 0 0 0 0
CON'T	REPORT L 6 0 5 0 0 0 3 7 3 0 11 11 0 7 8 2 8 1 2 0 6 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) 1 On November 7, 1982 the 'B' Chlorine and Ammonia Detector alarmed and would not reset.
0 2	
03	In accordance with Technical Specification 3.3.7.8 the failed detector was returned to
0 4	operable status within 7 days and safe operation of the Unit was maintained at all
0 5	times.
0 6	L
07	
7 8	9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE
09 7 8	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	17 LER/RO REPORT EVENT YEAR REPORT NO. CODE TYPE NO. 17 REPORT 1 4 5 1 0 3 1 0 NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPROA PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER 13 13 34 33 35 20 Z 20 Z 20 J 20 0 0 0 0 V 20 41 20 10 20 42 43 43 44 47 47 47 47 47 47 47 47 47 47 47 47
[1]0]	
	The cause of this occurrence was that the lens which detects chlorine
11	concentration in the air was dirty. The lens was cleaned and the 'B' Chlorine and
1 2	Ammenia Detector was declared operable on November 12, 1982 at 1400.
1 3	
	PACILITY DESCRIPTION (32)
1 5	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
1 6	ACTIVITY CONTENT IELEASED OF RELEASE AMOUNT OF ACTIVITY 35 2 33 2 34 NA 10 11 44 45 ACTIVITY 35 NA 30
17	PERSONNEL EXPOS HES NUMBER 0 0 0 0 37 0 38 085CRIPTION 39 NA 30
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION (4) 0 0 0 (40) NA
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION
7 8	9 10 B212140128 B21206 NRC USE ONLY
20	N (44) NA 5 101 8 69 30.2 (816) 257-6764 30.2
	NAME OF PREPARER Diane L. Kay PHONE PHONE

- 1. LER NUMBER: 82-145/03L-0
- 11. LASALLE COUNTY STATION: Unit
- III. DOCKET NUMBER: 050-373
 - IV. EVENT DESCRIPTION:

Technical Specification 3.3.7.8 requires two independent chlorine and ammonia detection subsystems to be operable. On November 7, 1982 the 'B' Chlorine and Ammonia Detector alarmed and would not reset.

V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

In accordance with Technical Specification 3.3.7.8 the failed chlorine and ammonia detector was returned to operable status within 7 days and safe operation of the Unit was maintained at all times. The other detector was operable during this event.

VI. CAUSE:

The cause of this occurrence was that the optical fiber lens which detects chlorine was dirty.

VII. CORRECTIVE ACTION:

The lens was cleaned and the 'B' Chlorine and Ammonia Detector was declared operable on November 12, 1982 at 1400. The Instrument Maintenance Department is in the process of changing LIS-VC-03, Control Room HVAC System Ammonia Detector Calibration and Functional Test, to include cleaning the lens monthly. AIR #1-82-580 has been generated to track this procedure change.

Prepared by: Diane L. Kay